COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

QBE

VEHICLE NO : SHD 4830D **DATE 22/10/2018 12:20**

MAKE :

Chiang

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			$ 553.00	
	Rear Bumper Clip 10 pcs			$ 22.00	
	SUB TOTAL			**$ 575.00**	
	LESS ~~20%~~ 25%			$ 115.00	
	DISCOUNTED TOTAL			**$ 460.00**	
	Rear Bumper Rubber Mat			$ 50.00	**Nett**
				$ 50.00	
	Labour Charge				
	Panel Beating			$ ~~400.00~~ 200	
	Spray Painting Charge		20	$ ~~300.00~~	
	Wiring Charge			$ ~~50.00~~	
	Remove/Refix Reverse Sensor		30	$ ~~80.00~~	
	TOTAL LABOUR			**$ 830.00**	
	ESTIMATE TOTAL			**$ 1,340.00**	

Kalin (Ck)

23/10/18 11.15 hrs.

2 Days

4s.

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Such [illegible] items must be resurveyed and is subject [illegible] approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.