a3

15/5/2010

INS. CASE OWNER: Jamel. | CC 3 /EQI1801 4470, Nubh | LKK: IDAC:

ASSIGNMENT

Surveyor: Nat DOI: 7/10/18 Date / Time : 7/10/18

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No. : SLG 7272G Claim No. : DMK/100/18/20

Name of Insured : Wong Tong Loong Policy No. : DMP PMR 18-00 6207

Insured Tel No. : HP: 97817766 Make / Model : BMW

Excess Sec II :S$ D.O.A : 20/10/18 (SUN) Place of Accident : Hougang Ave 7

Is driver the owner? (YES / NO) Nature of Accident :

If **NO**, Driver Name / Age : OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

SHB 5779 →

INSRS: WSP: Tel : Liability : SMRT RMKS:

INSRS: WSP: Tel : Liability : RMKS:

INSRS: WSP: Tel : Liability : RMKS:

INSRS: WSP: Tel : Liability : RMKS:

Date/ Time	
	SHB5779-X SLG7272G-X
7/11/18	LOD IN BY COURIER
11/11	
3/8/19	Spoke to Jane. Just present Dr.
2/9/19	File → typing ~
13/12/19	File → Sub Cs to send DWK ATA
6/1/2020	File pass to MK to close.

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	31/1/19

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)		
After call ltr to OI:	✓	
Authorisation To Act:	✓	
Release Voucher:	✓	
Final Repair Bill:	✓	
Car Rental Invoice:		
Towing Invoice		
LTA / GIA :	✓	
Medical Bill:		
PIR:		
Mandate/Reject Instruction:	✓	
LOD	✓	
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE Date/Time: Sent By: Confirm by: Email ☐ Call ☐

FINALIZATION Date/Time: Confirm with: Email ☐ Call ☐

Repair Cost: S$ (days) Reduction: %

FINAL SETTLEMENT Date/Time: 13/12/19 Confirm with Electric Email ✓ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 77 If NO or B 28. Ass. Lia :

Repair Cost: S$ 19850.00

Loss of Rental (LOR): S$ 2981.16 (28 days) x $ 106.47

Loss of Use (LOU): S$ — (S — x — days)

Loss of Income (LOI): S$ 1400-00 x 28 days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ **[Tick only one]**

GIA/LTA Search S$ 7.00

Medical: S$ —

Disbursement: S$ — (e.g. Tow/ Independent)

Legal Cost S$ —

Total: S$ 24238.16 **Global Sum S$:** 24200-00

COPY SENT 7/1/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format: GP

3) Survey fee: $400.00

FINAL PAYMENT Date/Time: Confirm with: Email ✓ Call ☐

Payee 1:	S$ 24200-00	Name 1:	SMRT Taxis Pte Ltd
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

Surveyor: NAZ

REF: EQ1

TAX/10/18/2084

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHB 577 Y Yr Regn: 4 MAR 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS c.c 1,798

Colour MAROON A/C: Insured / Std / NI / NA

Sp.Reading 439,143 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKN3642057599225

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ROADSTONE (F), FALKEN (R)

Front		Rear	
R/Bal.	5 mm	R/Bal.	6 mm
L/Bal.	5 mm	L/Bal.	6 mm
D.O.A.	20/10/18	D.O.I.	23/10/18

Survey held at SMRT WOODLANDS

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	EQ1 L/S
	CoE Rebate $33,849.
	Request Book Value to calculate Net Value
	4 S $ 19850 Credit $ 40711.12
	16 + 4 Sun + 1 PRS + 1 PH = 22

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation: S + RS SI

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI18019470/Nub3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 26-10-2018

Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	SLG 7272G	**Veh. Inspected**	SHB 577Y
	Policy No.		**Coverage ($)**	0.00
	Claim No.		**Excess ($)**	0.00
	Assign From		**Assign Date**	26/10/2018

2. Vehicle Particulars & Condition

	Make & Model		**c.c**	0
	Engine No.	HIDDEN	**Year of Reg.**	
	Chassis No.		**Colour**	
	Odometer	-	**Steering**	
	Brakes		**Modification**	
	General			

3. Conditions of Tyres

		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4. Description of Damages

5. General Information

	Accident Date	20/10/2018	**Inspection Date**	23/10/2018
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LWW Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI18019470/Nub3

Date: 26.10.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. **SHB577Y**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.10.2018 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S$	36,447.26
Revised Estimate Amount	: S$	10,247.03
"Check" Items Amount	: S$	20,090.41
Market Value	: S$	-
LTA Reimbursement Value	: S$	-
Nett Value	: S$	-

Description of Damage:
The vehicle sustained damages at the Rear portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 10 days

Yours faithfully,

MOHD. NAZRIL
Licensed Appraiser

SMRT AUTOMOTIVE

Case Details

Case Reference Number : TAX/10/18/2084
Type of Repair : Accident Repair
Vehicle Registration Number : SHB577Y

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-4239-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd
Accident Date and Time : 19/10/2018 04:00 PM
Vehicle Age(In Months) : 43

Documents / Photographs

View Documents / Photographs Total Documents: 1

Estimation Details

Spare Part's Cost Detail

				SMRT Recommendation							Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit($)	List Price($)	Dis(%)	Final Price($)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price($)	Repair/Replace
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Check
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Check
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0	Check
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0	Check
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0	Check
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0	Check
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Check
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Check
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Check
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Check
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Check
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Check
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check
One Time Key In	Main			GARNISH SIDE UPPER, LHR	1	261.70	261.70	25.00	196.27	Replace	0	0	Check
One Time Key In	Main			GARNISH ASSY, ROOF RH	1	256.40	256.40	25.00	192.30	Replace	0	0	Check
One Time Key In	Main			BATTERY	1	278.00	278.00	0.00	278.00	Replace	0	0	Check

Total Spare Part Cost	31,616.57	Surveyor Total	7,738.01
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	0
Final Spare Part Cost	25,293.26	Final Sur Total	7,738.01

				SMRT Recommendation							Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit($)	List Price($)	Dis(%)	Final Price($)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price($)	Repair/Replace	
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0	Check	?
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Check	?
One Time Key In	Main			WIRE, FRAME	1	1,680.90	1,680.90	25.00	1,260.68	Replace	0	0	Check	?
One Time Key In	Main			WIRE, ENGINE, NO.3	1	74.00	74.00	10.00	66.60	Replace	0	0	Check	?
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Check	?
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Check	?
One Time Key In	Main			RECEIVER, DOOR CONTROL	1	239.70	239.70	10.00	215.73	Replace	0	0	Check	?
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	?
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	?
One Time Key In	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	?
One Time Key In	Main			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	?
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	?
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	25.00	411.30	Replace	0	0	Check	?
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	25.00	83.18	Replace	1	83.18	Replace	? / DEF
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	? / DEF
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	? / NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	? / NEC
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	1	105.98	Replace	? / DEF
One Time Key In	Main			LID ASSY, FUEL	1	102.00	102.00	25.00	76.50	Replace	0	0	Check	?
One Time Key In	Main			CABLE SUB-ASSY, FUEL LID	1	63.90	63.90	25.00	47.92	Replace	0	0	Check	?
One Time Key In	Main			RETAINER, FUEL LID CABLE	1	5.90	5.90	25.00	4.43	Replace	0	0	Check	?
One Time Key In	Main			CAP ASSY, FUEL TANK	1	68.10	68.10	25.00	51.07	Replace	0	0	Check	?
One Time Key In	Main			PIPE SUB-ASSY, FUEL NECK	1	230.80	230.80	25.00	173.10	Replace	0	0	Check	?
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	1	126.07	Replace	/ NEC
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	/ NEC
							Total Spare Part Cost		31,616.57		Surveyor Total	7,738.01		
							Lump Sum Discount (%)		20.00		Lump Sum Dis (%)	0		
							Final Spare Part Cost		25,293.26		Final Sur Total	7,738.01		

				SMRT Recommendation							Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit($)	List Price($)	Dis(%)	Final Price($)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price($)	Repair/Replace	
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X SUC
One Time Key In	Main			REINFORCEMENT, ROOF SIDE INNER LH	1	60.30	60.30	25.00	45.22	Replace	0	0	Check	?
One Time Key In	Main			REINFORCE, ROOF SIDE OUTER LH	1	91.90	91.90	25.00	68.93	Replace	0	0	Check	?
One Time Key In	Main			REINFORCEMENT, BACK DOOR SIDE LH	1	89.50	89.50	25.00	67.13	Replace	0	0	Check	?
One Time Key In	Main			EXTENSION, QUARTER PANEL FRONT LH	1	83.50	83.50	25.00	62.63	Replace	0	0	Check	?
One Time Key In	Main			EXTENSION, QUARTER PANEL REAR LH	1	108.50	108.50	25.00	81.38	Replace	0	0	Check	?
One Time Key In	Main			PANEL, ROOF SIDE, INNER LH	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	?
One Time Key In	Main			PANEL, ROOF SIDE OUTER LH	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	?
One Time Key In	Main			PANEL, ROOF SIDE, / LH SIDE	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	?
One Time Key In	Main			RAIL, ROOF SIDE LH	1	273.60	273.60	25.00	205.20	Replace	0	0	Check	?
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	0	0	Check	?
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	0	0	Check	?
One Time Key In	Main			DOOR LOCK RR/LH	1	709.30	709.30	25.00	531.97	Replace	0	0	Check	?
One Time Key In	Main			DOOR BELT RR/LH	1	69.20	69.20	25.00	51.90	Replace	0	0	Check	?
One Time Key In	Main			DOOR HINGE UPPER RR/LH	1	81.70	81.70	25.00	61.28	Replace	0	0	Check	?
One Time Key In	Main			DOOR HINGE LOWER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Check	?
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check	?
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Check	?
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Give	X SUC
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	/ NEC
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	1	23.02	Replace	/ BT
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	1	502.02	Replace	/ CRK
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	1	83.18	Replace	/ DEF
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	/ DEF
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ NEC
							Total Spare Part Cost		31,616.57		Surveyor Total	7,738.01		
							Lump Sum Discount (%)		20.00		Lump Sum Dis (%)	0		
							Final Spare Part Cost		25,293.26		Final Sur Total	7,738.01		

				SMRT Recommendation							Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit($)	List Price($)	Dis(%)	Final Price($)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price($)	Repair/Replace	
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	NEC
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	1	105.98	Replace	DEF
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X SVC
One Time Key In	Main			REINFORCEMENT, BACK	1	89.50	89.50	25.00	67.13	Replace	0	0	Check	?
One Time Key In	Main			REINFORCEMENT, BELT	1	103.20	103.20	25.00	77.40	Replace	0	0	Check	?
One Time Key In	Main			REINFORCEMENT, ROOF	1	60.30	60.30	25.00	45.22	Replace	0	0	Check	?
One Time Key In	Main			REINFORCE, ROOF SIDE	1	91.90	91.90	25.00	68.93	Replace	0	0	Check	?
One Time Key In	Main			PANEL, ROOF SIDE,	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	?
One Time Key In	Main			EXTENSION, QUARTER	1	55.70	55.70	25.00	41.78	Replace	0	0	Check	?
One Time Key In	Main			EXTENSION, QUARTER	1	83.50	83.50	25.00	62.63	Replace	0	0	Check	?
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	0	0	Check	?
One Time Key In	Main			PANEL, ROOF SIDE INNER FRONT RH	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	?
One Time Key In	Main			PANEL, ROOF SIDE OUTER RH	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	?
One Time Key In	Main			RAIL, ROOF SIDE	1	273.60	273.60	25.00	205.20	Replace	0	0	Check	?
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	1	634.88	Replace	NEC
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	25.00	27.75	Replace	1	27.75	Replace	NEC
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	0	0	Not Give	X SVC
One Time Key In	Main			DOOR BELT RR/RH	1	69.20	69.20	25.00	51.90	Replace	0	0	Not Give	X SVC
One Time Key In	Main			DOOR HINGE LOWER RR/RH	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Give	X SVC
One Time Key In	Main			DOOR LOCK RR/RH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give	X SVC
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Not Give	X SVC
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Give	X SVC
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Not Given Replace	X SVC
Standard	Main	BODY RH	6505484	DOOR HINGE UPPER RR/RH	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	CRA

Total Spare Part Cost	31,616.57	Surveyor Total	7,738.01
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	0
Final Spare Part Cost	25,293.26	Final Sur Total	7,738.01

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit($)	List Price($)	Dis(%)	Final Price($)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price($)	Repair/Replace	
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	/ NEL
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	?
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	?
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	?
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	?
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	/ NEL
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ NEL
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace	/ DEF
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace	/ DEF
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	/ DEF
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	1	66.68	Replace	/ NEL
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace	/ NEL
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	/ LRK
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	/ LRK
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	1	385.88	Replace	/ DEF
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Givi	X SUL
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0	Not Givi	X SUL
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0	Not Givi	X SUL
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	/ DEF
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	/ NEL
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	/ NEL
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	/ NEL
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace	/ BR
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	/ NEL
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Check	?
							Total Spare Part Cost		31,616.57		Surveyor Total	7,738.01		
							Lump Sum Discount (%)		20.00		Lump Sum Dis (%)	0		
							Final Spare Part Cost		25,293.26		Final Sur Total	7,738.01		

				SMRT Recommendation							Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit($)	List Price($)	Dis(%)	Final Price($)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price($)	Repair/Replace	
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	1	378.67	Replace	/DEF
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE TRIM, RH	1	88.30	88.30	25.00	66.22	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE TRIM, UPPER	1	49.60	49.60	25.00	37.20	Replace	0	0	Check	?
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Check	?
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Check	?
One Time Key In	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.60	1,436.60	10.00	1,292.94	Replace	0	0	Check	?
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	146.10	146.10	10.00	131.49	Replace	0	0	Check	?
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace	/NEL
One Time Key In	Main			LICENSE PLATE LAMP	2	35.70	71.40	10.00	64.26	Replace	2	64.26	Replace	/NEL
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	/DT
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	/CRK
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/NEL
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace	/NEL
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/NEL
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	1	715.28	Replace	/DEF
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	1	208.17	Replace	/CRK
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/NEL

Total Spare Part Cost	31,616.57	Surveyor Total	7,738.01
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	0
Final Spare Part Cost	25,293.26	Final Sur Total	7,738.01

				SMRT Recommendation								Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit($)	List Price($)	Dis(%)	Final Price($)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price($)	Repair/Replace	
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/REC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	?
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	?
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check	?
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check	?
One Time Key In	Main		4006314	SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	?
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	?
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	?
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	?
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0	Check	?
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Check	?
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Check	?

Total Spare Part Cost	31,616.57	Surveyor Total	7,738.01
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	0
Final Spare Part Cost	25,293.26	Final Sur Total	7,738.01

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation($)	Surveyor Adjustment($)	Remarks
1	TO REPAIR REAR PORTION	1,859.00	800	WILL ADJUST ACCORDINGLY AFTER REVIEWING CHECK ITEMS PHOTOS.
Total:		1,859.00	800.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation($)	Surveyor Adjustment($)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY REAR PANEL	180.00	0	CHECK
3	TO RESPRAY TAIL GATE	378.00	200	
4	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80	
5	TO RESPRAY REAR SPOILER	180.00	80	
6	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	CHECK
7	TO RESPRAY RH REAR WHEEL HOUSE	180.00	0	NN
Total:		5,724.00	960.00	

S.No.	Job Scope	SMRT Recommendation($)	Surveyor Adjustment($)	Remarks
8	TO RESPRAY REAR LH WHEEL HOUSE	180.00	00	NN
9	TO RESPRAY REAR CHASSIS LH	180.00	0	CHECK
10	TO RESPRAY REAR CHASSIS RH	180.00	0	CHECK
11	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	CHECK
12	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	CHECK
13	TO RESPRAY BATTERY PANEL	180.00	0	CHECK
14	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	CHECK
15	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	CHECK
16	TO RESPRAY REAR FENDER RH	378.00	200	
17	TO RESPRAY REAR FENDER LH	378.00	200	
18	TO RESPRAY REAR DOOR RH	378.00	0	NN
19	TO RESPRAY REAR DOOR LH	378.00	0	CHECK
20	TO RESPRAY RH RAIL ROOF SIDE	180.00	0	CHECK
21	TO RESPRAY LH RAIL ROOF SIDE	180.00	0	CHECK
22	TO RESPRAY FRONT DOOR LH	378.00	0	NN
23	TO RESPRAY FRONT DOOR RH	378.00	0	NN
Total:		**5,724.00**	**960.00**	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation($)	Surveyor Adjustment($)	Remarks
1	TOWING CHARGE	126.00	0	NN
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	50	
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	50	
4	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
5	TO CHECK & RESET SYSTEM FUNCTION	350.00	100	
6	TO REMOVE / REFIT SEAT	120.00	0	CHECK
7	TO REMOVE & REFIT EXHAUST	120.00	0	NN
8	TO REMOVE & REFIT FUEL TANK	120.00	0	CHECK
9	TO ALIGN CHASSIS	350.00	0	CHECK
10	TO TRANSFER DOOR MECHANISM	240.00	0	CHECK
11	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	375.00	375.00	NEC
Total:		**3,571.00**	**915.00**	

S.No.	Job Scope	SMRT Recommendation($)	Surveyor Adjustment($)	Remarks
12	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	30	
13	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	30	
14	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	
15	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	
16	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
17	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	CHECK
18	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	
19	TO REMOVE AND REFIT WIRE HARDESS	250.00	0	CHECK
20	TO REPLACE SUNDRY PARTS	100.00	0	NN
21	TO WASH AND VACUUM	60.00	0	NN
Total:		**3,571.00**	**915.00**	

Summary

	Estimator Assesment($)	Surveyor Assesment($)
Total Spare Part Detail	25,293.26	7,738.01
Total Labour Cost	1,859.00	800.00
Total Spray Painting	5,724.00	950.00
Other	3,571.00	915.00
Overall Total	36,447.26	10,413.01
Lump Sum Repair Option	-	✓
Lump Sum Total	36,450.00	10,400.00
Surveyor Approved Amount		10,400.00
No of Repair Days*	16	10
Remarks	-	LUMP SUM REPAIR. 10 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS. NEED TO CALCULATE REPAIR MARGIN TO DETERMINE IF VEHICLE IS ECONOMICAL TO REPAIR.
Surveyor Name		Naz
Signature		
Survey Date	23/10/2018	

Save Clear

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NAZ LKK
23/10/18 1015
L/S
10 DAYS.

CHECK ITEMS PHOTOS
AFTER REPAIR PHOTOS

SMRT AUTOMOTIVE

NIC

SMRT Accident Vehicle Repair Estimates

Finalized. -Naz.

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68682623	
Accident Reporting Number : 68682672	

Date Generated : 24/01/2019

User ID : PehSuan

Section A - Accident Details

Registration Number	SHB577Y
Case Reference Number	TAX/10/18/2084
Registration Date	4/3/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LOW KOK HOI
Type of Accident	Head to Rear
Accident Date and Time	20/10/2018 12:00 AM
Accident Reported Date and Time	20/10/2018 11:04 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	20/10/2018 1:13 AM
Replacement Vehicle issued?	No
Job Card Number	24098382
Special Instruction to ARC,if any	TOWED $90
Prepared Date and Time	22/10/2018 8:48 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	$4,212.00	$1,650.00
Total Spray Cost	$9,000.00	$2,600.00
Total Spare Part Cost	$42,548.12	$14,644.10
Total Other Cost	$4,791.00	$1,285.00
TOTAL COST	**$60,551.12**	**$20,179.10**
Lump Sum Total	**$60,550.00**	**$20,200.00 (L/S)**
Number of Repair Days	26.0	16.0
Prepared / Adjusted By	Zhi Yang Phua	Naz (LKK) / EQ
ARC / Surveyor Sign Off Date	09/11/2018 12:57 PM	05/11/2018 7:25 PM
Signature		
Remarks		LUMP SUM REPAIR. 10 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.

SMRT

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number 68602623
Accident Reporting Number 68602672

Date Generated : 24/01/2019
User ID : PehSuan

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1901-0328	Invoice Number	
Quotation Date	15.01.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	$1,859.00	$800.00
TO REPAIR REAR PORTION	$2,353.00	$850.00
Total Labour	$4,212.00	$1,650.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable	
TO REPSRAY REAR BUMPER	$378.00	$200.00	/
TO RESPRAY REAR PANEL	$180.00	$0.00	XNN
TO RESPRAY TAIL GATE	$378.00	$200.00	/
TO RESPRAY TAILGATE OUTSIDE GARNISH	$180.00	$80.00	/
TO RESPRAY REAR SPOILER	$180.00	$80.00	/
TO RESPRAY REAR SPARE TYRE PANEL	$180.00	$0.00	XNN
TO RESPRAY RH REAR WHEEL HOUSE	$180.00	$0.00	XNN
TO RESPRAY REAR LH WHEEL HOUSE	$180.00	$0.00	XNN
TO RESPRAY REAR CHASSIS LH	$180.00	$0.00	XNN
TO RESPRAY REAR CHASSIS RH	$180.00	$0.00	XNN
TO RESPRAY REAR FLOOR SIDE PANEL LH	$180.00	$0.00	XNN
TO RESPRAY REAR FLOOR SIDE PANEL RH	$180.00	$0.00	XNN
TO RESPRAY BATTERY PANEL	$180.00	$0.00	XNN
TO RESPRAY TROUGH BACK DOOR LH	$180.00	$0.00	XNN
TO RESPRAY TROUGH BACK DOOR RH	$180.00	$0.00	XNN
TO RESPRAY REAR FENDER RH	$378.00	$200.00	/
TO RESPRAY REAR FENDER LH	$378.00	$200.00	/
TO RESPRAY REAR DOOR RH	$378.00	$0.00	XNN
TO RESPRAY REAR DOOR LH	$378.00	$0.00	XNN
TO RESPRAY RH RAIL ROOF SIDE	$180.00	$0.00	XNN
TO RESPRAY LH RAIL ROOF SIDE	$180.00	$0.00	XNN
TO RESPRAY FRONT DOOR LH	$378.00	$0.00	XNN
TO RESPRAY FRONT DOOR RH	$378.00	$0.00	XNN
TO RESPRAY REAR PANEL	$180.00	$100.00	/
TO RESPRAY REAR SPARE TYRE PANEL	$180.00	$100.00	/
TO RESPRAY REAR LH WHEEL HOUSE	$180.00	$100.00	/
TO RESPRAY RH REAR WHEEL HOUSE	$180.00	$100.00	/
TO RESPRAY REAR WHEELHOUSE	$360.00	$200.00	/

1,560

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/01/2019
User ID : PehSuan

TO RESPRAY REAR MEMBER,LH	$180.00	$100.00	
TO RESPRAY REAR MEMBER,RH	$180.00	$100.00	
TO RESPRAY REAR FLOOR SIDE PANEL RH	$180.00	$100.00	
TO RESPRAY TROUGH BACK DOOR LH	$180.00	$50.00	
TO RESPRAY TROUGH BACK DOOR RH	$180.00	$50.00	
TO RESPRAY REAR DOOR LH	$378.00	$200.00	
TO RESPRAY RH REAR DOOR	$378.00	$200.00	
TO RESPRAY PANEL SIDE ROOF LH	$180.00	$80.00	
TO RESPRAY PANEL SIDE ROOF RH	$180.00	$80.00	
TO REPRAY REAR SEAT LOWER PANEL	$180.00	$80.00	
Total Spray Painting & Panel Beating	**$9,000.00**	**$2,600.00**	1,040

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable	
TOWING CHARGE	$126.00	$90.00	
TO CHECK WIRING AND SYSTEM FUNCTION	$80.00	$50.00	
TO APPLY RUST-PROOFING ON AFFECTED AREA	$200.00	$50.00	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	$120.00	$60.00	
TO CHECK & RESET SYSTEM FUNCTION	$350.00	$100.00	
TO REMOVE / REFIT SEAT	$120.00	$0.00	X NN
TO REMOVE & REFIT EXHAUST	$120.00	$0.00	X NN
TO REMOVE & REFIT FUEL TANK	$120.00	$0.00	XNN
TO ALIGN CHASSIS	$350.00	$0.00	XNN
TO TRANSFER DOOR MECHANISM	$240.00	$0.00	XNN
~~TO PROVIDE LABOUR & MATERIAL FOR SOLAR~~ FILM (NET)	$375.00 SN	$375.00	NEL
TO REMOVE & REFIT REAR QUARTER GLASS LH	$120.00	$30.00	
TO REMOVE & REFIT REAR QUARTER GLASS RH	$120.00	$30.00	
TO TRANSFER REAR TAILGATE MECHANISM	$120.00	$50.00	
TO REMOVE AND REFIX REAR WINDSCREEN	$240.00	$120.00	
TO TEST AND REFIX REVERSE SENSOR SYSTEM	$120.00	$20.00	
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	$120.00	$0.00	XNN
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	$120.00	$30.00	
TO REMOVE AND REFIT WIRE HARDESS	$250.00	$0.00	XNN
TO REPLACE SUNDRY PARTS	$100.00	$0.00	XNN
TO WASH AND VACUUM	$60.00	$0.00	XNN
TO REMOVE AND REFIT BATTERY ASSY HV	$350.00	$50.00	
TO REMOVE / REFIT SEAT	$120.00	$30.00	
TO REMOVE & REFIT EXHAUST	$120.00	$50.00	
TO ALIGN CHASSIS	$450.00	$150.00	
TO TRANSFER DOOR MECHANISM	$180.00	$0.00	XNN
Total Other Costs	**$4,791.00**	**$1,285.00**	1,285

SMRT AUTOMOTIVE

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63665592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 24/01/2019

User ID : PohSuan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price ($)	Discount (%)	Final Price ($)	Estimator Approved	Surveyor Approved	
		58416-47030B3	BOX, RR FLOOR, BOARD	0.00	$679.60	0.00	$0.00	Replace	Check X	
		58415-47030	BOARD, RR FLOOR	0.00	$392.30	0.00	$0.00	Replace	Check X	
		58490-47140B0	BOARD ASSY, RR RH	0.00	$379.20	0.00	$0.00	Replace	Check X	
		58427-47040	SPACER, RR FLOOR	0.00	$130.60	0.00	$0.00	Replace	Check X	
		58418-47070B0	BOX, DECK FLOOR, COVER LH	0.00	$230.10	0.00	$0.00	Replace	Check X	
		64997-47020	BOX, DECK FLOOR, LH	0.00	$196.60	0.00	$0.00	Replace	Check X	
		64777-47090	CUSHION, SPARE WHEEL	0.00	$230.80	0.00	$0.00	Replace	Check X	
		64778-47050	PROTECTOR, SPARE	0.00	$143.70	0.00	$0.00	Replace	Check X	
		51931-47020	CARRIER, SPARE	0.00	$19.70	0.00	$0.00	Replace	Check X	
6503707			TYRE	0.00	$126.74	0.00	$0.00	Replace	Check X	
		42611-47140	WHEEL, DISC	0.00	$1,490.20	0.00	$0.00	Replace	Check X	
			BREAKDOWN SIGN	0.00	$35.00	0.00	$0.00	Replace	Check X	
		64740-47031B2	PANEL ASSY, DECK LH	0.00	$307.00	0.00	$0.00	Replace	Check X	
		64730-47031B2	PANEL ASSY, DECK RH	0.00	$307.00	0.00	$0.00	Replace	Check X	
		62480-47050-B0	GARNISH SIDE UPPER, LHR	0.00	$261.70	0.00	$0.00	Replace	Check X	SVC
		62470-47110B0	GARNISH ASSY, ROOF RH	0.00	$256.40	0.00	$0.00	Replace	Check X	
			BATTERY	0.00	$278.00	0.00	$0.00	Replace	Check X	
		74481-47050	BATTERY CLAMP	0.00	$16.10	0.00	$0.00	Replace	Check X	
		74440-47030	BATTERY TRAY	0.00	$42.80	0.00	$0.00	Replace	Check X	
		82164-47070	WIRE, FRAME	0.00	$1,680.90	0.00	$0.00	Replace	Check X	
		82123-47040	WIRE, ENGINE, NO.3	0.00	$74.00	0.00	$0.00	Replace	Check X	
		82161-47B22	WIRE, FLOOR	0.00	$1,675.00	0.00	$0.00	Replace	Check X	
		82162-47B20	WIRE, FLOOR, NO.2	0.00	$1,305.40	0.00	$0.00	Replace	Check X	
		89740-47031	RECEIVER, DOOR CONTROL	0.00	$239.70	0.00	$0.00	Replace	Check X	
		61605-47010	PANEL SUB-ASSY, QTR	0.00	$326.70	0.00	$0.00	Replace	Check X	
		61607-47060	PANEL SUB-ASSY, QTR	0.00	$588.40	0.00	$0.00	Replace	Check X	
		61608-47061	PANEL SUB-ASSY, QTR WHEEL HOUSE	0.00	$588.40	0.00	$0.00	Replace	Check X	
		61606-47010	PANEL, QUARTER WHEEL HOUSE, OUTER LH	0.00	$326.70	0.00	$0.00	Replace	Check X	
		52563-47010	TAIL LAMP BRACKET, LH	0.00	$30.70	0.00	$0.00	Replace	Check X	
		81561-47170	TAIL LAMP LH	1.00	$548.40	25.00	$411.30	Replace	Replace X	SVC
		61622-47030	TROUGH, BACK DOOR LH	1.00	$110.90	25.00	$83.18	Replace	Replace	DEF
		61602-47091	FENDER RR/LH	1.00	$766.80	25.00	$575.10	Replace	Replace	DEF
			SMRT LOGO	1.00	$7.80	0.00	$7.80	Replace	Replace	NEC
			STICKER DECAL 6555 8888	1.00	$21.60	0.00	$21.60	Replace	Replace	NEC
		65638-47021	FENDER LINER RR/LH	1.00	$141.30	25.00	$105.98	Replace	Replace	NEC
		77350-47030	LID ASSY, FUEL	0.00	$102.00	0.00	$0.00	Replace	Check X	
		77035-47090	CABLE SUB-ASSY, FUEL LID	0.00	$63.90	0.00	$0.00	Replace	Check X	
		77377-75010	RETAINER, FUEL LID CABLE	0.00	$5.90	0.00	$0.00	Replace	Check X	SVC
		77300-52030	CAP ASSY, FUEL TANK	0.00	$68.10	0.00	$0.00	Replace	Check X	

793.66

SMRT

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/01/2019
User ID : PohSuan

		77201-47250	PIPE SUB-ASSY, FUEL NECK	0.00	$230.80	0.00	$0.00	Replace	Check X	SVC
		62720-47031	QUARTER GLASS RR/LH	1.00	$168.10	25.00	$126.08	Replace	Replace	NEC
			SEALANT W/SCREEN	1.00	$37.00	0.00	$37.00	Replace	Replace	NEC
6503707			TYRE	0.00	$126.74	0.00	$0.00	Replace	Not Given X	
		61738-47020	REINFORCEMENT, ROOF SIDE INNER LH	0.00	$60.30	0.00	$0.00	Replace	Check X	
		61714-47020	REINFORCE, ROOF SIDE OUTER LH	0.00	$91.90	0.00	$0.00	Replace	Check X	
		61744-47010	REINFORCEMENT, BACK DOOR SIDE LH	0.00	$89.50	0.00	$0.00	Replace	Check X	
		61624-47010	EXTENSION, QUARTER PANEL FRONT LH	0.00	$83.50	0.00	$0.00	Replace	Check X	
		6162647020	EXTENSION, QUARTER PANEL REAR LH	0.00	$108.50	0.00	$0.00	Replace	Check X	
		61732-47030	PANEL, ROOF SIDE, INNER LH	0.00	$134.80	0.00	$0.00	Replace	Check X	
		61712-47020	PANEL, ROOF SIDE OUTER LH	0.00	$134.80	0.00	$0.00	Replace	Check X	
		61734-47020	PANEL, ROOF SIDE, / LH SIDE	0.00	$134.80	0.00	$0.00	Replace	Check X	SVC
		61218-47010	RAIL, ROOF SIDE LH	0.00	$273.60	0.00	$0.00	Replace	Check X	
		62940-16060	DUCT ASSY, QUARTER	0.00	$70.40	0.00	$0.00	Replace	Check X	
		67004-47080	DOOR RR/LH	0.00	$954.50	0.00	$0.00	Replace	Check X	
		69060-47080	DOOR LOCK RR/LH	0.00	$709.30	0.00	$0.00	Replace	Check X	
		75740-47021	DOOR BELT RR/LH	0.00	$69.20	0.00	$0.00	Replace	Check X	
		68760-20122	DOOR HINGE UPPER RR/LH	0.00	$81.70	0.00	$0.00	Replace	Check X	
		68780-52031	DOOR HINGE LOWER RR/LH	0.00	$72.20	0.00	$0.00	Replace	Check X	
		68630-47031	CHECK ASSY, RR DOOR,	0.00	$150.30	0.00	$0.00	Replace	Check X	
		69410-33010	DOOR LOCK STRIKER	0.00	$40.50	0.00	$0.00	Replace	Check X	
		67002-47070	DOOR FRT/LH	0.00	$894.40	0.00	$0.00	Replace	Not Given X	
			STICKER DECAL SMRT (DOOR)	1.00	$60.00	0.00	$60.00	Replace	Replace	NEC
		52562-47010	TAIL LAMP BRACKET, RH	1.00	$30.70	25.00	$23.03	Replace	Replace	BT
		81551-47180	TAIL LAMP RH	1.00	$557.80	10.00	$502.02	Replace	Replace	CRK
		61621-47030	TROUGH, BACK DOOR	1.00	$110.90	25.00	$83.18	Replace	Replace	DEF
		61604-47090	FENDER RR/RH	1.00	$766.80	25.00	$575.10	Replace	Replace	DEF
			SMRT LOGO	1.00	$7.80	0.00	$7.80	Replace	Replace	NEC
			STICKER DECAL 6555 8888	1.00	$21.60	0.00	$21.60	Replace	Replace	NEC
			FENDER LINER RR/RH	1.00	$141.30	25.00	$105.98	Replace	Replace	DEF
6503707			TYRE	0.00	$126.74	0.00	$0.00	Replace	Not Given X	
		61743-47010	REINFORCEMENT, BACK	0.00	$89.50	0.00	$0.00	Replace	Check X	
		61766-47020	REINFORCEMENT, BELT	0.00	$103.20	0.00	$0.00	Replace	Check X	
		6173747020	REINFORCEMENT, ROOF	0.00	$60.30	0.00	$0.00	Replace	Check X	
		61713-47020	REINFORCE, ROOF SIDE	0.00	$91.90	0.00	$0.00	Replace	Check X	
		61731-47020	PANEL, ROOF SIDE,	0.00	$134.80	0.00	$0.00	Replace	Check X	SVC
		61625-47040	EXTENSION, QUARTER	0.00	$55.70	0.00	$0.00	Replace	Check X	
		61623-47010	EXTENSION, QUARTER	0.00	$83.50	0.00	$0.00	Replace	Check X	
		62940-16060	DUCT ASSY, QUARTER	0.00	$70.40	0.00	$0.00	Replace	Check X	
		61733-47020	PANEL, ROOF SIDE INNER FRONT RH	0.00	$134.80	0.00	$0.00	Replace	Check X	
		61711-47020	PANEL, ROOF SIDE OUTER RH	0.00	$134.80	0.00	$0.00	Replace	Check X	

1,481.76
1541.79

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/01/2019
User ID : PohSuan

		61217-47010	RAIL, ROOF SIDE	0.00	$273.60	0.00	$0.00	Replace	Check X	SVC
		62710-47130	QUARTER GLASS RR/RH	1.00	$846.50	25.00	$634.88	Replace	Replace	NEC
			SEALANT W/SCREEN	1.00	$37.00	25.00	$27.75	Replace	Replace	NEC
		67003-47080	DOOR RR/RH	0.00	$954.50	0.00	$0.00	Replace	Not Given X	SVC
		75730-47021	DOOR BELT RR/RH	0.00	$69.20	0.00	$0.00	Replace	Not Given X	
		68740-12120	DOOR HINGE LOWER RR/RH	0.00	$90.10	0.00	$0.00	Replace	Not Given X	
		69050-47080	DOOR LOCK RR/RH	0.00	$709.30	0.00	$0.00	Replace	Not Given X	
		69410-33010	DOOR LOCK STRIKER	0.00	$40.50	0.00	$0.00	Replace	Not Given X	
		67001-47070	DOOR FRT/RH	0.00	$894.40	0.00	$0.00	Replace	Not Given X	
			STICKER DECAL SMRT (DOOR)	0.00	$60.00	0.00	$0.00	Replace	Not Given X	
6505484	BODY RH	68730-12120	DOOR HINGE UPPER RR/RH	0.00	$90.10	0.00	$0.00	Replace	Not Given X	
		52159-47905	BUMPER REAR	1.00	$458.60	25.00	$343.95	Replace	Replace	CRK
		52161-16010	BUMPER CLIPS	10.00	$1.61 16.10	25.00	$12.08	Replace	Replace	NEC
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	$205.70	0.00	$0.00	Replace	Check X	SVC
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	$139.60	0.00	$0.00	Replace	Check X	
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	$139.60	0.00	$0.00	Replace	Check X	
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	$157.40	0.00	$0.00	Replace	Check X	
			SENSOR REVERSE	1.00	$180.00	0.00	$180.00	Replace	Replace	NEC
			PIXEL STICKER	2.00	$60.00	0.00	$120.00	Replace	Replace	NEC
		76088-47020	BUMPER LIP COVER RR/LH	1.00	$72.20	25.00	$54.15	Replace	Replace	DEF
		76087-47020	BUMPER LIP COVER RR/RH	1.00	$118.10	25.00	$88.58	Replace	Replace	DEF
		76891-47020	BUMPER LIP REAR	1.00	$228.90	25.00	$171.68	Replace	Replace	DEF
		52592-47021	BUMPER SEAL, RR LH	1.00	$88.90	25.00	$66.68	Replace	Replace	NEC
		52591-47021	BUMPER SEAL, RR RH	1.00	$65.70	25.00	$49.28	Replace	Replace	NEC
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	$94.80	25.00	$71.10	Replace	Replace	CRK
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	$94.80	25.00	$71.10	Replace	Replace	CRK
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	1.00	$514.50	25.00	$385.88	Replace	Replace	DEF
		58327-47020	EXHAUST HEAT SHIELD, REAR	0.00	$107.40	0.00	$0.00	Replace	Not Given X	SVC
		17430-37380	EXHAUST TAIL PIPE	0.00	$656.20	0.00	$0.00	Replace	Not Given X	SVC
		17565-22030	SUPPORT, EXHAUST REAR	0.00	$33.60	0.00	$0.00	Replace	Not Given X	SVC
		67005-47241	TAILGATE ASY	1.00	$1,007.90	25.00	$755.93	Replace	Replace	DEF
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	$29.40	25.00	$22.05	Replace	Replace	NEC
		75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	$29.40	25.00	$22.05	Replace	Replace	NEC
		75575 - 47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	$29.40	25.00	$22.05	Replace	Replace	NEC
		64821-47030	TAILGATE LOWER WINDOW GLASS	1.00	$721.30	25.00	$540.98	Replace	Replace	BR
			SEALANT W/SCREEN	3.00	$37.00	0.00	$111.00	Replace	Replace	NEC
		68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	$58.30	0.00	$0.00	Replace	Check X	SVC
		69350-47030	TAILGATE DOOR LOCK	0.00	$444.10	0.00	$0.00	Replace	Check X	
		68960-0W532	TAILGATE DOOR STAY LH	0.00	$241.50	0.00	$0.00	Replace	Check X	
		68950-0W542	TAILGATE DOOR STAY RH	0.00	$241.50	0.00	$0.00	Replace	Check X	
		67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	$353.40	0.00	$0.00	Replace	Check X	

3751.17

SMRT

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68682623
Accident Reporting Number : 68682672

Date Generated : 24/01/2019
User ID : PohSuan

		69415-47020	TAILGATE LOCK, COVER	0.00	$15.70	0.00	$0.00	Replace	Check X	SUC
		76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	$504.90	25.00	$378.68	Replace	Replace /	DEF
		69431-47010	STRIKER, BACK DOOR	0.00	$48.90	0.00	$0.00	Replace	Check X	
		67938-47031C0	TAILGATE TRIM, LH	0.00	$85.90	0.00	$0.00	Replace	Check X	
		67751-47040C0	TAILGATE TRIM, LOWER	0.00	$180.70	0.00	$0.00	Replace	Check X	
		67937-47031C0	TAILGATE TRIM, RH	0.00	$88.30	0.00	$0.00	Replace	Check X	
		64790-47030C0	TAILGATE TRIM, UPPER	0.00	$49.60	0.00	$0.00	Replace	Check X	SUC
		67750-47071C0	TAILGATE, BOARD ASSY	0.00	$246.90	0.00	$0.00	Replace	Check X	
		82184-47370	WIRE, BACK DOOR, NO.1	0.00	$582.40	0.00	$0.00	Replace	Check X	
		86790-47040	CAMERA ASSY, TELEVISION, RR	0.00	$1,436.60	0.00	$0.00	Replace	Check X	
		84840-28040	SWITCH ASSY, BACK DOOR OPENER	0.00	$146.10	0.00	$0.00	Replace	Check X	
		75310-47020	EMBLEM REAR	1.00	$60.30	25.00	$45.23	Replace	Replace /	NEC
	10%	81271-53011	LICENSE PLATE LAMP	2.00	$35.70 71.4%	10.00	$64.26	Replace	Replace /	NEC
			NUMBER PLATE	1.00	$15.00	0.00	$15.00	Replace	Replace /	DD
			NUMBER PLATE FRAME	1.00	$12.00	0.00	$12.00	Replace	Replace /	CRK
		75374-47051	NAME PLATE (HYBRID)	1.00	$51.90	25.00	$38.93	Replace	Replace /	NEC
		75442-47030	NAME PLATE (PRIUS)	1.00	$60.80	25.00	$45.60	Replace	Replace /	NEC
		75443-47030	NAME PLATE (TOYOTA)	1.00	$51.90	25.00	$38.93	Replace	Replace /	NEC
		76085-47910	SPOILER REAR	1.00	$953.70	25.00	$715.28	Replace	Replace /	DEF
	10%	81006-47011	3RD BRAKE LAMP	1.00	$231.30	10.00	$208.17	Replace	Replace /	CRK
			SMRT LOGO	1.00	$7.80	0.00	$7.80	Replace	Replace /	NEC
			STICKER DECAL 6555 8888	1.00	$21.60	0.00	$21.60	Replace	Replace /	NEC
		58307-47060	END PANEL	0.00	$602.10	0.00	$0.00	Replace	Check X	
		64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	$46.10	0.00	$0.00	Replace	Check X	
		64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	$121.10	0.00	$0.00	Replace	Check X	
		58336-12090	REINFORCEMENT, RR	0.00	$34.60	0.00	$0.00	Replace	Check X	
4006314			SEALANT SIKAFLEX	0.00	$37.00	0.00	$0.00	Replace	Check X	
		58311-47071	SPARE TYRE PANEL	0.00	$667.70	0.00	$0.00	Replace	Check X	SUC
		57604-47030	MEMBER SUB-ASSY, RR LH	0.00	$174.10	0.00	$0.00	Replace	Check X	
		57603-47030	MEMBER SUB-ASSY, RR RH	0.00	$174.10	0.00	$0.00	Replace	Check X	
		58303-47301	FLOOR PANEL RR/LH	0.00	$102.00	0.00	$0.00	Replace	Check X	
		58302-47030	FLOOR PANEL RR/RH	0.00	$209.90	0.00	$0.00	Replace	Check X	
		64993-47020	BOX, DECK FLOOR, RR	0.00	$649.70	0.00	$0.00	Replace	Check X	
Total					$40,078.13		$8,089.40			1391.48

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price $	Discount (%)	Final Price ($)	ARC Check	Surveyor Check	
		58415-47030	BOARD, RR FLOOR	1.00	$392.30	25.00	$294.23	Replace	Replace /	DEF
		58490-47140B0	BOARD ASSY, RR RH	1.00	$379.20	25.00	$284.40	Replace	Replace /	DEF
		64997-47020	BOX, DECK FLOOR, LH	1.00	$196.80	25.00	$147.60	Replace	Replace /	DEF
		64778-47050	PROTECTOR, SPARE	1.00	$143.70	25.00	$107.78	Replace	Replace /	DEF

834.01

SMRT

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757706
FAX Number : 63685592
Estimator Telephone Number : 68602623
Accident Reporting Number : 68682672

Date Generated : 24/01/2019
User ID : PohSuan

		64740-47031B2	PANEL ASSY, DECK LH	1.00	$307.00	25.00	$230.25	Replace	Replace	DEF
		64730-47031B2	PANEL ASSY, DECK RH	1.00	$307.00	25.00	$230.25	Replace	Replace	DEF
			BATTERY	1.00	$278.00	10.00	$250.20	Replace	Replace	DEF
		74440-47030	BATTERY TRAY	1.00	$42.80	25.00	$32.10	Replace	Replace	DEF
		62940-16060	DUCT ASSY, QUARTER	2.00	$70.40 170.84	25.00	$105.60	Replace	Replace	DEF
		67003-47080	DOOR RR/RH	1.00	$954.50	100.00	$0.00	Replace	Repair XR	
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	$205.70	25.00	$154.28	Replace	Replace	DEF
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	$139.60	25.00	$104.70	Replace	Replace	BT
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	$139.60	25.00	$104.70	Replace	Replace	BT
		58327-47020	EXHAUST HEAT SHIELD, REAR	1.00	$107.40	25.00	$80.55	Replace	Replace	DEF
		17430-37380	EXHAUST TAIL PIPE	1.00	$656.20	25.00	$492.15	Replace	Replace	DEF
		17565-22030	SUPPORT, EXHAUST REAR	1.00	$33.60	25.00	$25.20	Replace	Replace	DEF
		69350-47030	TAILGATE DOOR LOCK	1.00	$444.10	25.00	$333.08	Replace	Replace	BT
		67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	$353.40	25.00	$265.05	Replace	Replace	DEF
		58307-47060	END PANEL	1.00	$602.10	25.00	$451.58	Replace	Replace	DEF
		64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1.00	$46.10	25.00	$34.58	Replace	Replace	DEF
		64716-47031B0	END PANEL COVER, DECK TRIM, RR	1.00	$121.10	25.00	$90.83	Replace	Replace	DEF
		58311-47071	SPARE TYRE PANEL	1.00	$667.70	25.00	$500.78	Replace	Replace	DEF
		57604-47030	MEMBER SUB-ASSY, RR LH	1.00	$174.10	25.00	$130.58	Replace	Replace	DEF
		57603-47030	MEMBER SUB-ASSY, RR RH	1.00	$174.10	25.00	$130.58	Replace	Replace	DEF
		58302-47030	FLOOR PANEL RR/RH	1.00	$209.90	25.00	$157.43	Replace	Replace	DEF
		64993-47020	BOX, DECK FLOOR, RR	1.00	$649.70	25.00	$487.28	Replace	Replace	DEF
		G9510-47060	BATTERY ASSY, HV	1.00	$5,544.40	10.00	$4,989.96	Replace	Replace	DEF
Total					13,340.50		10,215.72			9,381.71

-1676.18

~~18,305.12~~ 17,893.82

-20%

14,644.10 14,315.06

+ 1,650.00

+ 3,885.00

20,179.10 19,850.06

L/S $20,200/- L/S $19,850.00

CONFIRMED LUMP SUM REPAIR $19,850.00 / 16 DAYS.

NAZLEE

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	JAX/10/18/2084	Date of Collection	/ /
Vehicle No	SUB 577 Y	Date of Request	29/10/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	~~10~~ 6

Photo

S/N	Part Number	Part Description	Quantity	Unit Price
	[illegible]	BOARD, REAR FLOOR	1pc	DEF
	[illegible]	BOARD ASSY, REAR RH	1pc	DEF
	2351/2353 [illegible] 2355/2356	BOX, DECK FLOOR LH	1pc	DEF
	2403/2404	PROTECTOR, SPARE	1pc	DEF
	2406/2407	BREAKDOWN SIGN	1pc	CRK
	[illegible]	PANEL ASSY, DECK LH	1pc	DEF

<<<Please submit photographs for damaged parts>>>

I, (Name) [illegible]

(Position) [illegible]

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to [illegible] of perjury.

For [illegible]

Acknowledge By	Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	[illegible] Stock / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
[illegible]	YES / NO	Date of submission

PJ/0

REQUEST FOR SUPPLYMENT PARTS

Coordinator			
Assistant Claim Number	[illegible] 2018 4	Date of Collection :	/ /
Vehicle Reg.	[illegible] Y	Date of Request	29/10/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	~~10~~ 6

S.N	Part Number	Part Description	Quantity	Unit Price
	[illegible]	[illegible] DECK RH	1pc	✓ DEF
	[illegible]	[illegible]	1pc	✓ DEF
	[illegible]	[illegible] TRAY	1pc	✓ DEF
	[illegible]	[illegible] QUARTER LH	1pc	✓ DEF
2	[illegible]	[illegible] DOOR RH	1pc	X R
	[illegible]	[illegible] QUARTER RH	1pc	✓ DEF

Please attach photographs for damaged parts>>>

I, [illegible]

(Please [illegible]

[illegible] Supplementary Parts are raised for replacement for the aforesaid vehicle [illegible]

.....
Signature of person making this declaration
[to be signed in front of an authorised witness]

I [illegible] and I make it with the understanding and belief that a person who makes a false declaration is [illegible]

[illegible] Officer / Supervisor / SA	
[illegible] Surveyor / In-house Staff	
[illegible] Contractor Supply / Form 22 / C	Form22 / PO / WOC/ Reservation / Number
[illegible] NO:	Date of submission

[illegible]%

SUPPLYMENT PARTS

	Date of Collection :	/ /
	Date of Request	29/10/2018
	Number of Days to Extend (If any)	~~10~~ 6

	Quantity	Unit Price
BUMPER REINFORCEMENT	1pc	DEF
REAR BUMPER LH	1pc	BT
REAR BUMPER RH	1pc	BT
HEAT SHIELD, REAR	1pc	DEF
TAIL PIPE	1pc	DEF
REINFORCEMENT, REAR	1pc	DEF

For damaged parts>>>

Nil

Supplementary Parts are raised for replacement for the aforesaid

.....
Signature of person making this declaration
[To be signed in front of an authorised witness]

I have read and understand the contents of this declaration and I make it with the understanding that a person who makes a false declaration is

	Supervisor / SA	
Approved By	Surveyor / In-house Staff	
	Contractor Supply / Form 22 /	Form22 / PO / WOC/ Reservation / Number
	YES / NO	Date of submission

[illegible] SUPPLEMENT PARTS

[illegible]	Date of Collection :	/ /
[illegible]	Date of Request	29/10/2018
[illegible]	Number of Days to Extend (If any)	~~10~~ 6

[illegible]	[illegible]	Quantity	Unit Price
[illegible]	DOOR LOCK	1pc	/ BT
[illegible]	DOOR WEATHERSTRIP	1pc	/ DEF
[illegible]	[illegible]	1pc	/ DEF
[illegible]	[illegible] COVER, DECK TRIM HOLE	1pc	/ DEF
[illegible]	[illegible], DECK TRIM REAR	1pc	/ DEF
[illegible]	[illegible] PANEL	1pc	/ DEF

[illegible] photographs for damaged parts>>>

I, [illegible]

([illegible])

[illegible] Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....

Signature of person making this declaration
[To be signed in front of an authorised witness]

I [illegible] and I make it with the understanding and belief that a person who makes a false declaration is [illegible]

[illegible] / SA	
[illegible] / Technical Staff	
[illegible] Supply / Form 22 / [illegible]	Form22 / PO / WOC/ Reservation / Number
[illegible]	Date of submission

REPLACEMENT PARTS

	Date of Collection :	/ /
	Date of Request	29/10/2018
Vehicle Model	Number of Days to Extend (If any)	10 6

	Quantity	Unit Price
	1pr	DEF
	1pr	DEF
	1pr	DEF
	1pr	DEF
HV BATTERY	1pr	DEF
		$ 350

50

<<Attach other copies for damaged parts>>

Supplementary Parts are raised for replacement for the aforesaid

.....
Signature of person making this declaration
[To be signed in front of an authorised witness]

I [illegible] with the understanding and belief that a person who makes a false declaration is

	Office / Supervisor / SA	
Approved by	Supervisor/In-house Staff	
Parts Ordered	Procurement Coordinator Supply / Form 22 /	Form22 / PO / WOC/ Reservation / Number
Parts Received	YES / NO	Date of submission

PARTS

Date of Collection :	/ /
Date of Request	29/10/2018
Number of Days to Extend (If any)	~~10~~ 6

	Quantity	Unit Price	
23 REAR SEAT		$ ~~120~~	30
REAR EXHAUST		$ ~~120~~	50
REAR CHASSIS FRAME XL		$ ~~450~~	150
REAR DOOR mechanism RH		$ ~~180~~	20 X NN
REAR TRIM Inner		$ ~~180~~	50
2325/ 2329 SIDE PANEL RH		$ ~~180~~	50

>>Please complete the remaining pages

Supplementary Parts are called for replacement for the aforesaid

.....
Signature of person making this declaration
[Must be signed in front of an authorised witness]

I hereby certify that I have satisfied myself with the understanding and belief that a person who makes a false declaration is

Name / Designation / Date	
Name / Designation Staff	
Form 22 / Form 22 /	Form22 / PO / WOC/ Reservation / Number
Date / Time	Date of submission

SUPPLEMENTARY PARTS

Accident Case Number	2084P	Date of Collection :	/ /
[illegible]	[illegible]	Date of Request	29/10/2018
[illegible]	[illegible]	Number of Days to Extend (If any)	10-6

	Quantity	Unit Price	
REPAIR Port SIDE PANEL LH		$ ~~180~~	50
REPLACE REAR END PANEL		$ ~~450~~	100
REPLACE SPARE SIDE PANEL		$ ~~450~~	100
REPLACE REAR CHASSIS FRAME X2		$ ~~400~~	200
REPAIR SEAT LOWER PANEL		$ ~~300~~	100
REPAIR [illegible] PANEL		$ ~~180~~	100

[illegible] the [illegible] for the said parts>>

[illegible] Supplementary Parts are raised for replacement for the aforesaid

.....
Signature of person making this declaration
[To be signed in front of an authorised witness]

I [illegible] do solemnly and sincerely declare that I am fully aware and understanding and believe that a person who makes a false declaration is [illegible]

[illegible] Supervisor / PA	
[illegible] Inhouse Staff	
[illegible] Contractor Supply / Form 22 /	Form22 / PO / WOC/ Reservation / Number
[illegible]	Date of submission

[illegible]YMENT PARTS

Date of Collection :	/ /
Date of Request	29/10/2018
Number of Days to Extend (If any)	~~10~~ 6

	Quantity	Unit Price	
[illegible] PANEL		$ ~~180~~	100
[illegible] PANEL	HOUSE PANEL RH	$ ~~180~~	100
[illegible] WHEEL	HOUSE PANEL LH	$ ~~180~~	100
[illegible] WHEEL	HOUSE PANEL RR	$ ~~360~~	200
[illegible] CHASSIS	RH	$ ~~180~~	100
[illegible] CHASSIS	LH	$ ~~180~~	100

[illegible] number of [illegible] pages>>

NH

[illegible] Parts are [illegible] for replacement for the aforesaid

.....
Signature of person making this declaration
[To be signed in front of an authorised witness]

[illegible] the undersigned [illegible] that a person who makes a false declaration is

Fo[illegible]

[illegible] / [illegible]	
[illegible] / [illegible]	
[illegible] / Form 22 /	Form22 / PO / WOC/ Reservation / Number
[illegible]	Date of submission