ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/ 62717433 FAX:62745715

SUPPLEMENTARY ESTIMATE REPAIR

China Taiping Insurance (Singapore) Pte Ltd

Date: 29.10.2018

Owner's Name : Topsteel Solutions Asia Pte Ltd

Vehicle No : PC1855M

Vehicle Make & Model : Toyota Hiace Auto

Registration Date : 6 Aug 2013 (YOM 2013) COE Expiry Date 5 Aug 2023

Claim Type: Third Party Claim

Chassis No: JTFHT02P900119645

DOA: 26.10.2018

No	Description	Unit	List
	Special Nett		
1	DECAL REAR TAILGATE	1	$ 150 ~~300.00~~ A

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts – 2284.98

S/N – 518.00

Labour – 1270.00

Supp S/N – 150.00

Total – 4222.98

20%

3378.38

L/J – 3350

5 days