22/03/2001

ASS. REC. BY: | REF: CS/FCI18019904/RIVd302 | Special Instruction:

Surveyor: CWS

ASSIGNMENT (Office)

From (Person): May chua of FCI Date/Time: 1/11/18 @ 3:08pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBM 387S Insured: SHC3060X

at Workshop m/s Weaves Automotive Tel: 64304934

of 45 Jeng Kee Road

Policy No: Claim No: D18007806MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 26/10/2018

CA / REV / REP. / REV 24 HRS (up) 2/11/2018 H.O.D. Endorsement:

Date/Time: 4:15pm @ 1/11/18 Person Contacted: Tony Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBM 387S - X
	SHC 3060X - CS/FCI18003893 / Kqbn2 DOA : 27/02/2018
5/11/18	Email preli revised to FCI
17/1/19	@ 530pm Tony will email us finalised
5/3/19	final fig $ 20,252.70 confirmed by email (Red 3160.70, 13%)

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: Person Contacted:

D.O.A. 26/10/18 D.O.I. 02/11/18

Survey held at WGARAGES

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

RECEIVED 05 MAR 2019

5/3/2019

Date/Time. File Pass to? ☐ : Preli. Report

1). ☐ : Final Report

Date/Time. File Return to?

2) 5/3 - typist

Report Format : CWS

Lump Sum / I.B.I: ($ 20,252.70)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

13x15 = 195

Survey Fee.	170+195
Transportation	50
S + PS St	50
Photos	62
Others	
TOTAL	527

7/3/19