Repair Estimate

CarCrafters Singapore Pte Ltd
48 Toh Guan Road East
#05-155, Enterprise Hub
Singapore 608586

Tel: 6267 9916
Fax: 6267 9313
www.carcrafters.sg

AIG ASIA PACIFIC INSURANCE PTE LTAD
78 Shenton Way #07-16 Singapore 079120
Our Client
JAN PHILIP DIRKMANN

Date : 10/11/2018
Vehicle Num : SKD7146R
Make/Model : VOLKSWAGEN TOURAN 1.4L
Chassis No : WVGZZZ1TZCW053397
Accident Date : 2 November 2018 at 1500 Hrs

S/N	PARTS	QTY	PRICE	TOTAL
1	REAR BUMPER SCR	1	$ 1,240.00	$ 1,240.00
2	REAR LEFT FENDER BY	1	$ 1,700.00	$ 1,700.00
3	LH REAR GUIDE PIECE ?	1	$ 33.00	$ 33.00
4	WHEELHOUSING COVER ?	1	$ 107.00	$ 107.00
5	LH BUMPER GUIDE PIECE ?	1	$ 43.00	$ 43.00
6	ALLOY WHEEL SCR	1	$ 1,020.00	$ 1,020.00
7	WHEEL CAP New	1	$ 20.00	$ 20.00
8				
			Rasal	
			Hp 90010068	
			5 days	
			L/S	
	TOTAL PARTS			$ 4,163.00
	MISCELLANEOUS		15/11/18 @ 1240	
1		1		
	LABOUR			
1	To remove/ replace/ refit / cut out damage portion, welding and replace new parts		Resay after repair	$ 750 ~~1,200.00~~
2	To putty and respray painting on affected areas			$ 500 ~~800.00~~
3	To conduct computerise wheel alignment and balancing test			$ 60 ~~120.00~~
4	To conduct computerise clear fault			$ 60 ~~80.00~~
	TOTAL			$ 6,363.00
	GST 7%			$ 445.41
				$ 6,808.41

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: