

KOON HENG MOTOR

(Reg. No: 24840700K)

BLK 1 KAKI BUKIT AVE 6 #02-14 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883

TEL: 67487348 FAX: 67432524

email: koonhengmotor@gmail.com

M/S **AXA Insurance Pte Ltd**
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Estimation No : 16112018 / 4481

Type : TP

Date : 16/11/2018

A/C No : GBH4481C

Re: ESTIMATION ON REPAIR COST TO VEHICLE NO: GBH4481C

Make/ Model : Nissan Urvan NV350
Chassis No : JN1NC2E26Z0030323

Accident Date : 14/11/2018

PARTS REQUIRED

Description	Qty	U/Price (\$\$)	Amount (\$\$)
1 Front LH Door <i>R</i>	1	1,015.00	1,015.00 <i>X</i>
2 Front LH Door Lower Garnish <i>cut</i>	1	163.40	163.40 <i>✓</i>
3 Front Bumper <i>Deep cut</i>	1	514.70	514.70 <i>✓</i>
4 Front Bumper LH Side Retainer <i>Ref</i>	1	147.00	147.00 <i>✓</i>
5 Front LH Tyre Rim <i>11</i>	1	450.00	450.00 <i>X</i>
6 Front LH Tyre Knuckle Arm <i>11</i>	1	409.00	409.00 <i>X</i>
7 Front Bumper Side Clips <i>new</i>	2	8.00	16.00 <i>✓</i>
TOTAL			2,715.10
LESS DISCOUNT 10%			271.51
TOTAL SPARE PARTS <i>50%</i>			2,443.59

LABOUR CHARGES

8 TO KNOCK/REPAIR/WELDING OF DAMAGED PARTS, CHANGING OF ACCIDENT PAR	1,000.00	<i>400</i>
9 TO SPRAY PAINT FOR AFFECTED AREAS	1,000.00	<i>700</i>
10 TO WIRING	80.00	<i>20</i>
11 TO UNDERCOAT	<i>11</i> 200.00	<i>X</i>
12 DOOR SIDE ROC STICKER	<i>new</i> 30.00	<i>✓</i>
13 WHEEL ALIGNMENT	70.00	<i>60</i>
14 TO UNDER CARRIAGE	<i>11</i> 350.00	<i>X</i>
		2,730.00
GRAND TOTAL AMOUNT (PARTS & LABOUR)		5,173.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
like
20/11/18
2/5 #1600/2
Take photo After repair
3oh.

P-841.10
less 50%
P-420.55
L-1210.00
1630.55