LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	: 03 DEC 2018
TIME OF SURVEY	:

VEHICLE NO. : SKE 1232 J
MAKE : B.M.W.
MODEL : 335I AT 3.0L ABS D/AB HID 2WD 4DR
YEAR : 2009
CHASSIS NO : WBAPM72030A381035

DATE : 26-Nov-18
DATE OF ACCIDENT : 24-Nov-18
THIRD PARTY REF : SLM 3270 G / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper				$ 967.00
1 pc	N/S Front Bumper Retainer				$ 8.65
1 pc	N/S Headlamp			CM	$ 2,376.20
1 pc	N/S Front Fender				$ 664.60
1 pc	N/S Front Door			R	$ 1,204.15
1 pc	N/S Front Door Rubber				$ 136.50
1 pc	N/S Front Doour Outer Handle				$ 70.70
					$ 5,427.80
1 pc	N/S Front Sport Rim	S.Nett			$ 680.00
	To putty and spray painting				$ 1,000.00
	To check front wiring and focus headlights				$ 30.00
	To check wheel alignment				$ 60.00
	To transfer door fittings				$ 50.00
	Labour Charges			5 4hr	$ 600.00
	Not Included L/Lamp & ? Resurvey After Paint 4 days				
TG-RA/-	**TOTAL**				**$ 7,847.80**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd