CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

KIA

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110	Cust No/Name	/Ms Ong Hwee Yee Stella
	Reg No/Reg Date	SLE208A / 06/11/2015
	Date In/Mileage	11/12/2018/ 0
	Chassis No	KNAFX411MF5522252
	Engine No	G4FGFH796883
Contact No	Make/Model	KIA/FORTE K3 1.6 A EX BF4
	Colour/Trim	SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000061	Credit	11/12/2018/ 11:06	DS	218 / MarsLer	15132

		Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC/SCANNING				250.00
S	MIPNT88088	TO CHECK LIGHTNING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS				80.00
S	MIPNT88088	TO REPLACE FRONT BUMPER,RHF FENDER ETC. -STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS				2400.00
S	MIPNT88088	WHEEL BALANCING				50.00
S	MIPNT88088	COMPUTERIZED WHEEL ALIGNMENT				180.00
S	MIPNT88088	TO REMOVE & RE-INSTALL A/C CONDERSER & RADIATOR TO GIVE WAY ACCESS REPAIR ON FRONT ACCIDENT AFFECTED AREAS				280.00
S	MIPNT98088	SPRAY PAINTING ON FRT & RHS ACCIDENT AFFECTED AREAS				1680.00
M	KS 86511 A7 000	COVER - FRONT BUMPER	1.00	728.00	0.00	728.00
M	JJMR200300	CLIP, BUMPER	10.00	2.00	0.00	20.00
M	KS 86514 A7 000	BRACKET -FR BUMPER S	1.00	12.00	0.00	12.00
M	KS 86513 A7 000	BRACKET-FR BUMPER SI	1.00	12.00	0.00	12.00
M	KS 92102 A7 101	LAMP ASSY-HEAD,RH	1.00	1870.00	0.00	1870.00
M	KS 66321 A7 000	PANEL - FENDER, RH	1.00	435.00	0.00	435.00
M	KS 86812 A7 000	RHF WHEEL GUARD ASSY	1.00	109.00	0.00	109.00
M	WRT900437	WHEEL ASSY	1.00	1460.00	0.00	1460.00
M	KS 64101 A7 001	CARRIER ASSY-FR END	1.00	776.00	0.00	776.00
P	JJMZ313950	COOLANT	4.00	26.00	0.00	104.00
Z	NOTES	ACCIDENT ON 10/12/18 ALONG AMA83 ANG MO KIO INDUSTRIAL PARK 2 BLK 5022 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # YL9606J TP INS: EQ INSURANCE				

Not Authorised
14/12/18
3 day.
Beforepaint!
600
900
60
840

Estimate

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirm & accepted by

Authorized signatory and company stamp

Parts	5,526.00
Labour	0.00
Standard Menu	0.00
Specialist Job	4,920.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	10,446.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.