COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 2996H **DATE 12/27/2018 10:17**

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover			$ 544.50	
	Front Bumper Grille (RH)			$ 41.60	
	Front Bumper Bracket (RH)			$ 24.60	
	Headlamp (RH)			$ 1,388.00	
	Front Fender (RH)			$ 566.30	
	Front Fender Shield (RH)			$ 174.90	
	Front Wheel Hub Cap (RH)			$ 107.10	
	SUB TOTAL			**$ 2,847.00**	
	LESS 20%			$ 569.40	
	DISCOUNTED TOTAL			**$ 2,277.60**	
	Front Fender Advertisement Logo (RH)			$ 100.00	**Nett**
	Front Door Advertisement Logo (RH)			$ 100.00	**Nett**
	TOTAL			**$ 200.00**	
	Labour Charge				
	Panel Beating (Repair)			$ ~~500.00~~ 300	
	Spray Painting Charge			$ ~~750.00~~ 400	
	Wiring Charge			$ ~~50.00~~ 20	
	Tuff Kote			$ ~~50.00~~ 20	
	FRT Wheel Alignment			$ ~~80.00~~ X	
	TOTAL LABOUR			**$ 1,430.00**	
	ESTIMATE TOTAL			**$ 3,907.60**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.