SMRT AUTOMOTIVE

# SMRT Accident Vehicle Repair Estimates


| SMRT Automotive Services Pte Ltd |
|---|
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592 |
| Estimator Telephone Number : 68662623 |
| Accident Reporting Number : 68662672 |


**Date Generated :** 18/12/2019

**User ID :** CatherineLee

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price $ | Discount (%) | Final Price ($) | ARC Check | Surveyor Check | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | A634491210 | EXHAUST PIPE | 1.00 | $6,225.00 | 10.00 | $5,602.50 | Replace | Replace | OO |
| | | A6345016424 | COOLING WATER PIPE FEED | 2.00 | $433.25 | 10.00 | $779.85 | Replace | Replace | OO |
| | | A001501882 | RADIATOR HOSE | 2.00 | $108.88 | 10.00 | $195.98 | Replace | Replace | OO |
| | | A4572010231 | COOLING WATER OUTLET | 2.00 | $350.00 | 10.00 | $630.00 | Replace | Replace | OO |
| | | A6219970090 | CLAMP | 2.00 | $82.50 | 10.00 | $148.50 | Replace | Replace | OO |
| | | N00000000146 8 | CLAMP 60-85X13MM | 2.00 | $15.00 | 10.00 | $27.00 | Replace | Replace | OO |
| | | N00000000353 0 | CLAMP 65-85X13MM | 2.00 | $15.75 | 10.00 | $28.35 | Replace | Replace | OO |
| | | A0008321794 | MOLDED HOSE | 2.00 | $113.25 | 10.00 | $203.85 | Replace | Replace | OO |
| | | | ENGINE ASSEMBLY RECOND | 1.00 | $23,130.44 | 10.00 | $20,817.40 | Replace | Replace | BR |
| | | | ATTACHMENT AIF FILTER M10 | 1.00 | $5.25 | 10.00 | $4.72 | Replace | Replace | NPC |
| | | A0029970452 | HOSE | 1.00 | $767.50 | 10.00 | $690.75 | Replace | Replace | OO |
| | | N00000000678 | CLAMP | 1.00 | $11.00 | 10.00 | $9.90 | Replace | Replace | NPC |
| | | A00052801B5 | RUBBER MOUNTING | 4.00 | $55.00 | 10.00 | $198.00 | Replace | Replace | TN |
| | | N00000000213 6 | CLAMP | 1.00 | $11.75 | 10.00 | $10.58 | Replace | Replace | NPC |
| | | N00000000068 0 | CLAMP | 5.00 | $27.50 | 10.00 | $123.75 | Replace | Replace | NPC |
| | | A0180944302 | AIR CLEANER | 1.00 | $1,370.00 | 10.00 | $1,233.00 | Replace | Replace | OO |
| | | A6345280404 | SCOOP | 1.00 | $290.00 | 10.00 | $261.00 | Replace | Replace | OO |
| | | A6385283708 | AIR PIPE | 1.00 | $937.50 | 10.00 | $843.75 | Replace | Replace | OO |
| Total | | | | | 41,057.00 | | 38,646.97 | | | |

P- 646085
- 20%
$ 1728.68
L - 5610
$ 7,338.68
L/S = $ 7,350.00

86,260.14#

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: