S. REC. BY: | REF: CS/SM019000360/ Utd3ek Special Instructions:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time: 7/1/19 @ 2.28pm

Estimated Cost: Bill to:

OD / TP / WS / TF RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBL 7550X Insured: GBB 7835C

at Workshop m/s: Ben Huck Hin Tel: 628 1 6520

of No. 6 Death Lane 1

Policy No: Claim No: CMTD1803120/AGC

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 20/07/2018

CA / REV / REP. / REV 24 HRS 1up H.O.D. Endorsement: 8/1/2019

Date/Time: 2.42pm @ 7/1/19 Person Contacted: Raymond Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBL 7550X - X
	GBB 7835C - X

REF: SMO

ASSIGNMENT

From: Date: 8/1/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBL 7550X

at Workshop m/s: Ben Huck Hin

of: No. 6 Defu Lane 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 18L.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Cups

Vehicle: IN / OUT

Date: Person Contacted

Veh No: FBL 7550X Yr Regn: 12/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Kawasaki ZZR 1400M 1441

Colour: Blue A/C: Insured / Std / NI / NA

Sp Reading: T/Radio: Insured / Std / NI / NA

Eng/No:

Ch/No: JKBZXT40EFA017060

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70ZR17

R: 160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or roadstone.

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 20/7/18 D.O.I. 8/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt, N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair. LTA 876 Sys. Sale.
14/10/19	L/S $ 11,800 confirmed with Raymond. (Red: 13706 50 537)
	FBL 7418 Estimate.

RECEIVED 15 OCT 2019

Date/Time, File Pass to? 1) 15/10 Typist

Date/Time, File Return to? 2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ Tech. Invs ($) ☐ Weekend ($)

Survey Fee: 450

Transportation: ( ) S + RS ( ) Photos ( ) Others

TOTAL 450

Report Format : TP

Lump Sum / I.B.I: ($ 11,800/-)

Denise Tay (LKKAuto)

From: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>
Sent: Tuesday, 15 October 2019 1:28 PM
To: Denise Tay (LKKAuto)
Cc: Teo, Grace
Subject: RE: CMTD1803120/AGC - SUV(LKK)/ Accident Involving GBB7835C & FBL7550X on 20/07/2018

Dear Denise

CMTD1803120 is our old case so it is not created in Merimen.

Please submit the survey report on previous method basis.

Thank you.

Best Regards
Agnes Chan
Claims Divison
D: 6329 5327| **T:** 6461 6555| **F:** 6221 3147

Innovation for Wellbeing
SOMPO
A Century of Trust

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission[1] & Product Purchase[2] via Sompo SG

Download now @ Download on the App Store or GET IT ON Google Play

[1] For Travel, Personal Accident & Home Insurance | [2] For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.
Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Tuesday, 15 October, 2019 11:19 AM
To: Teo, Grace <grace.teo@sompo.com.sg>
Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>
Subject: RE: CMTD1803120/AGC - SUV(LKK)/ Accident Involving GBB7835C & FBL7550X on 20/07/2018

Dear Grace,

Nivitha (LKK Auto)

From:	Teo, Grace <grace.teo@sompo.com.sg>
Sent:	Monday, 7 January 2019 2:28 PM
To:	Raymond; admin-d@lkkauto.com; assignments@lkkauto.com
Cc:	Chan, Shu Hui Agnes; Ye, Yong Kang Melvin; Henry, Irene James
Subject:	CMTD1803120/AGC - SUV(LKK)/ Accident Involving GBB7835C & FBL7550X on 20/07/2018
Attachments:	11223_Claim File.pdf

Without Prejudice

Our Claim Reference: CMTD1803120/AGC
Your Reference: FBL7550X

Hi Raymond,

We acknowledged receipt of your claim documents.

Please be informed that Ms. Agnes Chan is the handler of this case.

As agreed, we shall appoint **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO,**

Please make arrangement to conduct the survey for FBL7550X on a without Prejudice Basis and any admission of liability basis.

Please submit with your report to my colleague, Ms Agnes Chan.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | **T**: 6461 6555 | **F**: 6221 3147

SOMPO INSURANCE A Century of Trust

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission[1] & Product Purchase[2] via Sompo SG

Download now @ App Store or Google Play

[1] For Travel, Personal Accident & Home Insurance | [2] For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.
Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

---

From: Raymond [mailto:raymond@bhh.com.sg]
Sent: Saturday, January 05, 2019 2:32 PM
To: Claims - Motor Survey
Subject: Accident Involving FBL7550X & GBB7835C on 20/07/2018

Dear Sir / Madam,

We attached the third party claim documents for your perusal.

Appreciate for you to arrange for the pre-repair survey.

Thanks

Best Regards,
Raymond
Ban Hock Hin Co., Pte Ltd
Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969
Visit us at http://www.bhh.com.sg
Facebook: http://www.facebook.com/bhhsg

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.s

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	FBL7550X
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	KAWASAKI
Vehicle Model :	ZZR1400 M
Chassis No. :	JKBZXT40EFA011060
Propellant :	Petrol
Engine No. :	ZXT40EE009738
Engine Capacity :	1441 cc
Maximum Power Output :	-
Maximum Laden Weight :	443 kg
Unladen Weight :	250 kg
Year Of Manufacture :	2013
Original Registration Date :	10 Dec 2013
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
Quota Premium :	$1,782.00
COE Expiry Date :	09 Dec 2023
Road Tax Expiry Date :	09 Dec 2018
Inspection Due Date :	09 Dec 2018
Intended Transfer Date :	07 Jan 2019
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 10 Dec 2018 to 09 Jun 2019)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	229.00	-	229.00
Total Amount Payable :			**254.00**

Amount Payable (From 10 Dec 2018 to 09 Dec 2019)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	458.00	-	458.00
Total Amount Payable :			**483.00**

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1176D
Vehicle Details	
Vehicle No.:	FBL7550X
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jan 2019
Vehicle Make:	KAWASAKI
Vehicle Model:	ZZR1400 M
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	ZXT40EE009738
Chassis No.:	JKBZXT40EFA011060
Maximum Power Output:	-
Open Market Value:	$14,535.00
Original Registration Date:	10 Dec 2013
First Registration Date:	10 Dec 2013
Transfer Count:	4
Actual ARF Paid:	$2,181.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Dec 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	$1,782.00
COE Rebate Amount:	$876.00
Total Rebate Amount:	**$876.00**

The information contained herein is correct as at 09 Jan 2019

OK

(/listing/usedbike/kawasaki-kawasaki-zx1000n-h2-ninja/10308/)

SGD$37500

Reg : 17/11/2015

Type: Sport Bikes

998cc

-

Kawasaki H2 Ninja for Sale! Prices are negotiable. Trade in or Loan available. Viewing will be at Dynasty Motor Pte Ltd @ Kaki Bukit, Synergy @ KB, 25 Kaki Bukit Road 4 #01-82 S'pore 417800.

Posted on : 09/01/2019

★ PAID AD ★ DEALER AD

■ COMPARE DETAILS > (/LISTING/USEDBIKE/KAWASAKI-KAWASAKI-ZX1000N-H2-NINJA/10308/)

Kawasaki ZG1400GTR Concours (/listing/usedbike/kawasaki-kawasaki-zg1400gtr-concours/7631/)

(/listing/usedbike/kawasaki-kawasaki-zg1400gtr-concours/7631/)

SGD$19800

Reg : 21/01/2013

Type: Sport Tourers

1352cc

-

Well taken care by previous owner. Please visit the bike at I Motoring showroom location at Block 1008 Bukit merah Lane 3 #01-14 Singapore 159722.

Posted on : 09/01/2019

★ PAID AD ★ DEALER AD

■ COMPARE DETAILS > (/LISTING/USEDBIKE/KAWASAKI-KAWASAKI-ZG1400GTR-CONCOURS/7631/)

Kawasaki Z800 (/listing/usedbike/kawasaki-kawasaki-z800/9030/)

Kawasaki ZX14R Ninja (/listing/usedbike/kawasaki-kawasaki-zx14r-ninja/1627/)

(/listing/usedbike/kawasaki-kawasaki-zx14r-ninja/1627/)

SGD$22800

Reg : 06/04/2013

Type: Sport Bikes

1441cc

-

Kawasaki ZZR1400 ABS Sale. Leo Vince endcan included. Prices are negotiable. Trade in or Loan available. Viewing will be at Dynasty Motor Pte Ltd @ Bukit Batok

Posted on : 25/12/2018

★ PAID AD ★ DEALER AD

■ COMPARE DETAILS > (/LISTING/USEDBIKE/KAWASAKI-KAWASAKI-ZX14R-NINJA/1627/)

Kawasaki ZX14R Ninja (/listing/usedbike/kawasaki-kawasaki-zx14r-ninja/8351/)

(/listing/usedbike/kawasaki-kawasaki-zx14r-ninja/8351/)

SGD$18300

Reg : 07/12/2007

Type: Sport Bikes

1352cc

-

Kawasaki ZX14R Ninja for Sale! Prices are negotiable. Trade in or Loan available. Viewing will be at Dynasty Motor Pte Ltd @ Kaki Bukit, Synergy @ KB, 25 Kaki Bukit Road 4 #01-82 S'pore 417800.

Posted on : 24/12/2018

★ PAID AD ★ DEALER AD

■ COMPARE DETAILS > (/LISTING/USEDBIKE/KAWASAKI-KAWASAKI-ZX14R-NINJA/8351/)

Kawasaki Z1000SX (/listing/usedbike/kawasaki-kawasaki-z1000sx/3774/)

(/listing/usedbike/kawasaki-kawasaki-z1000sx/3774/)

SGD$21800

Reg : 31/10/2014

Type: Sport Bikes

1043cc

-

Well taken care by the ex-owner. Interested and wants to know more details for the bike. Please Visit us and view at I - Motoring @ Blk 1008 Bukit Merah Lane 3 #01-14. Trade in / Loan available.

Posted on : 04/01/2019

★ PAID AD ★ DEALER AD

■ COMPARE DETAILS > (/LISTING/USEDBIKE/KAWASAKI-KAWASAKI-Z1000SX/3774/)

Kawasaki ZX14R Ninja (/listing/usedbike/kawasaki-kawasaki-zx14r-ninja/10566/)

(/listing/usedbike/kawasaki-kawasaki-zx14r-ninja/10566/)

SGD$17200

Reg : 26/03/2013

Type: Sport Bikes

1441cc

-

Kawasaki ZZR1400. COE till May 2023 Very fast machine. Good condition. Loan available, welcome trade in. Come visit us at Sin Boon Motor. Interested buyers are welcome to negotiate.

Posted on : 02/01/2019

★ PAID AD ★ DEALER AD

■ COMPARE DETAILS > (/LISTING/USEDBIKE/KAWASAKI-KAWASAKI-ZX14R-NINJA/10566/)

Kawasaki ZG1400GTR Concours (/listing/usedbike/kawasaki-kawasaki-zg1400gtr-concours/10214/)

Your NCD will be affected due to late reporting
Actual e-Filling Submission Date & Time: 11/12/2018 09:05

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/12/2018 16:44
Date Of Accident	20/07/2018 08:50
Exact Location Of Accident	TPE PUNGGOL TOWARDS CHANGI
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBL7550X
Insured/Policyholder	
Name Of Registered Owner	KELANA BIN ALI
NRIC No	S7011176D
Email Address	DYFAMILY8@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90260414
Alternative Phone No	OFFICE-90260414
Vehicle Particulars	
Manufacturer	KAWASAKI
Model	ZZR1400-1.4
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	PNMC2018-00002571
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD HADI BIN SAMSIDI
NRIC No	S9334720Z
Date Of Birth	22/09/1993
Occupation	INDOOR
Date Of Driving Pass	20/07/2012
Driving Experience	6 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86888303
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 104 TANAH MERAH BESAR ROAD #02-37
Postcode	498841
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	DRIZZING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG TPE PUNGGOL TOWARDS CHANGI IN LANE 2 WHEN SUDDENLY A COMPANY VAN SWERVE IN MY LANE FROM THE 3RD LANE. IT COLLIED WITH MY MOTORCYCLE ON MY LEFT AND IT INJURED MT LEFT LEG AND HAND. I WENT TO SEE THE DOCTOR AFTER THE ACCIDENT. AT THE TIME THE ACCIDENT HAPPENED, IT WAS DRIZZLING HEACILY WITH HEAVY TRAFFIC.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB7835C
Vehicle Make/Model/Colour	OPEL / COMBO / GREY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	FOOK SHIAN MING
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1	
Name	MUHAMMAD HADI BIN SAMSIDI
Approximate Age	25
Injuries Sustain	LEFT LEG AND HAND
Injured person in which vehicle?	FBL7550X
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 104 TANAH MERAH BESAR ROAD #02-37
Postcode	498841

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore (**"GIA"**) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the **"Personal Information"**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **"Insurers"**), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the **"Purposes"**)

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 10/12/2018 @ 4pm	Reporting Centre Personnel's Signature Name: Tan Chee Kok NRIC/FIN No.: G7715226W

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along TPE Punggol towards changi in lane 2 when suddenly a company van swerve in my lane from the ~~left the~~ 3rd lane. It collide with my motorcycle on my left and it injured my left leg and hand. ~~A~~ I went to see the doctor after the accident.
At the time the accident happen, it was drizzling heavily with heavy traffic

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 10/12/2018 @ 4pm	Reporting Centre Personnel's Signature Name: Tan Chee Lock NRIC/FIN No.: G7715738R

BAN HOCK HIN Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : **33421**

Customer :

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

MOTOR CLAIMS DEPT

Not Approved
2/1
8/1/19
2/s = 11,800
The pre-Approval
Sty.

DATE : 02/01/2019
CLAIM NO. : 11223
POLICY NO. : PNMC2018-00002571

FROM : RAYMOND

VEHICLE NO. : FBL7550X
MAKE/MODEL : KAWA / 1400GTR M

S/N	Description	Action	Qty	Unit Price		Amount
1	AXLE WHEEL FRONT (25X195)	REPLACE	1.00	$252.00	AN	252.00 X
2	BEARING STEERING CONE	REPLACE	2.00	$112.00	AN	224.00 X
3	BOLT FLANGE	REPLACE	4.00	$4.00	AN	16.00 X
4	BOLT FLANGE 6X12	REPLACE	3.00	$4.00	AN	12.00 X
5	BOLT SCOKET (5X20)	REPLACE	2.00	$5.00	AN	10.00 X
6	BOLT SOCKET	REPLACE	8.00	$5.00	AN	40.00 X
7	BOLT SOCKET 6X14	REPLACE	6.00	$4.00	X see	24.00
8	BRACKET COMP. LH	REPLACE	1.00	$90.00	X Bent	90.00
9	BRACKET COWLING	REPLACE	1.00	$30.00	X Bent	30.00
10	BRACKET COWLING LOWER FRONT LH	REPLACE	1.00	$34.00	X Bent	34.00
11	BRACKET COWLING LOWER REAR LH	REPLACE	1.00	$41.00	X Bent	41.00
12	BRACKET DOWN SENSOR	REPLACE	1.00	$82.00	X AN	82.00 X
13	BRACKET METER	REPLACE	1.00	$616.00	Bent	616.00

S/N	Description	Action	Qty	Unit Price		Amount
14	BRACKET MIRROR	REPLACE	1.00	$313.00	CUT	313.00
15	BRACKET RADIATOR	REPLACE	1.00	$79.00	BM	79.00
16	BRACKET UNDER FORK	REPLACE	1.00	$2,674.00	SU	2,674.00 X
17	BRACKET UPPER COWLING	REPLACE	1.00	$15.00	AM	15.00 X
18	BULB (12V 55W) H11	REPLACE	2.00	$84.00	AM X	168.00
19	BULB (12V65W) H9	REPLACE	2.00	$112.00	AM X	224.00
20	CAP HOSE COOLING	REPLACE	1.00	$118.00	AM	118.00 X
21	COLLAR	REPLACE	4.00	$15.00	AM	60.00
22	COVER HEAT GUARD FRONT	REPLACE	1.00	$258.00	BRO	258.00
23	COVER HEAT GUARD LH	REPLACE	1.00	$198.00	BRO	198.00
24	COVER SIDE LH (BLACK)	REPLACE	1.00	$686.00	BRO	686.00
25	COVER SIDE RH (BLACK)	REPLACE	1.00	$686.00	R X	686.00
26	COWLING FRONT LH	REPLACE	85.03	$274.00	TOM	274.00
27	COWLING LOWER	REPLACE	1.00	$692.00	CM	692.00
28	COWLING LOWER LH	REPLACE	1.00	$692.00	CM	692.00
29	COWLING SIDE LH (BLUE)	REPLACE	1.00	$1,418.00	CM	1,418.00
30	COWLING UPPER (BLUE)	REPLACE	1.00	$2,035.00	BRO	2,035.00
31	DAMPER	REPLACE	2.00	$5.00	AM	10.00 X
32	DAMPER COWLING	REPLACE	4.00	$1.00	AM	4.00 X
33	DUCT AIR LH	REPLACE	1.00	$376.00	AM	376.00 X
34	FAN RADIATOR ASSY LH	REPLACE	1.00	$2,064.00	CM/JM	2,064.00
35	FAN RADIATOR ASSY RH	REPLACE	1.00	$1,430.00	AM	1,430.00 X

S/N	Description	Action	Qty	Unit Price		Amount
36	HOSE COOLING RADIATOR	REPLACE	1.00	$244.00	Dayle	244.00
37	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	16.00	$35.00	350	560.00
38	LAMP SIGNAL FRONT LH	REPLACE	1.00	$209.00	Cre	209.00
39	LAMP SIGNAL FRONT RH	REPLACE	1.00	$209.00	11	209.00
40	LENS HEADLAMP LH	REPLACE	1.00	$1,248.00	Cre	1,248.00
41	LENS HEADLAMP RH	REPLACE	1.00	$1,248.00	Cre	1,248.00
42	LEVER CLUTCH	REPLACE	1.00	$159.00	Sur	159.00
43	MIRROR LH	REPLACE	1.00	$436.00	Cre	436.00
44	MUDGUARD FRONT BLUE	REPLACE	1.00	$837.00	11	837.00
45	NUT 5MM	REPLACE	9.00	$3.00	11	27.00
46	PAD	REPLACE	1.00	$5.00	11	5.00
47	PAD (8X30X10)	REPLACE	1.00	$5.00	11	5.00
48	PAD (8X30X3)	REPLACE	1.00	$5.00	11	5.00
49	PAD COWLING LOWER LH	REPLACE	1.00	$79.00	Cre	79.00
50	PAD COWLING LOWER RH	REPLACE	1.00	$79.00	Cre	79.00
51	PAD HEADLIGHT	REPLACE	1.00	$15.00	Ner	15.00
52	PAD HEADLIGHT LH	REPLACE	1.00	$15.00	Ner	15.00
53	PAD RAD LH	REPLACE	1.00	$18.00	Ner	18.00
54	PAD RAD RH	REPLACE	1.00	$19.00	Ner	19.00
55	PAD SIDE COWLING RH P/N: 47721	REPLACE	1.00	$68.00	11	68.00
56	PAD TANK LH	REPLACE	1.00	$61.00	11	61.00

S/N	Description	Action	Qty	Unit Price	Amount
57	PAN INNER COWLING LH	REPLACE	1.00	$38.00	38.00
58	RADIATOR ASSY 3100	REPLACE	1.00	$3,654.00	3,654.00
59	RIVET	REPLACE	5.00	$6.00	30.00
60	RIVET P/N: 60423	REPLACE	11.00	$12.00	132.00
61	SCREW TAPPING 5X10	REPLACE	2.00	$3.00	6.00
62	SCREW TAPPING 5X16	REPLACE	15.00	$1.50	22.50
63	STAY RADIATOR	REPLACE	1.00	$36.00	36.00
64	TRIM RADIATOR (LONG)	REPLACE	1.00	$35.00	35.00
65	TRIM RADIATOR (SHORT)	REPLACE	2.00	$12.00	24.00
66	WASHER	REPLACE	2.00	$2.50	5.00
67	WASHER (6.5X16X1)	REPLACE	6.00	$1.00	6.00
68	WASHER NYLON	REPLACE	10.00	$2.50	25.00
69	WASHER NYLON (5.3X11.5X1.5)	REPLACE	2.00	$1.00	2.00

SUB TOTAL	$25,506.50
GST @ 7 %	$1,785.46
GRAND TOTAL	**$27,291.96**

50% deposit required before ordering of parts.

Validity: 30 days

16259.5
10%
14633.55
14983.55
1198

For & on Behalf of

BAN HOCK HIN CO PTE LTD

BAN HOCK HIN CO PTE LTD

RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

TÜV SÜD ISO 9001
CERT NO.: 2002-1-0283
ISO 9001 : 2015

BAN HOCK HIN Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 33421 - Rev. 1

Customer :

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

MOTOR CLAIMS DEPT

DATE : 02/01/2019
CLAIM NO. : 11223
POLICY NO. : PNMC2018-00002571

FROM : RAYMOND

VEHICLE NO. : FBL7550X
MAKE/MODEL : KAWA / 1400GTR M

S/N	Description	Action	Qty	Unit Price	Amount
1	BOLT SOCKET 6X14	REPLACE	6.00	$4.00 Disc %: 10.00	21.60
2	BRACKET COMP. LH	REPLACE	1.00	$90.00 Disc %: 10.00	81.00
3	BRACKET COWLING	REPLACE	1.00	$30.00 Disc %: 10.00	27.00
4	BRACKET COWLING LOWER FRONT LH	REPLACE	1.00	$34.00 Disc %: 10.00	30.60
5	BRACKET COWLING LOWER REAR LH	REPLACE	1.00	$41.00 Disc %: 10.00	36.90
6	BRACKET METER	REPLACE	1.00	$616.00 Disc %: 10.00	554.40
7	BRACKET MIRROR	REPLACE	1.00	$313.00 Disc %: 10.00	281.70
8	BRACKET RADIATOR	REPLACE	1.00	$79.00 Disc %: 10.00	71.10
9	BULB (12V 55W) H11	REPLACE	2.00	$84.00 Disc %: 10.00	151.20
10	BULB (12V65W) H9	REPLACE	2.00	$112.00 Disc %: 10.00	201.60
11	COLLAR	REPLACE	4.00	$15.00 Disc %: 10.00	54.00
12	COVER HEAT GUARD FRONT	REPLACE	1.00	$258.00 Disc %: 10.00	232.20
13	COVER HEAT GUARD LH	REPLACE	1.00	$198.00 Disc %: 10.00	178.20
14	COVER SIDE LH (BLACK)	REPLACE	1.00	$686.00 Disc %: 10.00	617.40

bizSAFE 3

TÜV SÜD ISO 9001

S/N	Description	Action	Qty	Unit Price	Amount
15	COWLING LOWER	REPLACE	1.00	$692.00 Disc %: 10.00	622.80
16	COWLING LOWER LH	REPLACE	1.00	$692.00 Disc %: 10.00	622.80
17	COWLING SIDE LH (BLUE)	REPLACE	1.00	$1,418.00 Disc %: 10.00	1,276.20
18	COWLING UPPER (BLUE)	REPLACE	1.00	$2,035.00 Disc %: 10.00	1,831.50
19	FAN RADIATOR ASSY LH	REPLACE	1.00	$2,064.00 Disc %: 10.00	1,857.60
20	HOSE COOLING RADIATOR	REPLACE	1.00	$244.00 Disc %: 10.00	219.60 ?
21	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	10.00	$35.00	350.00
22	LAMP SIGNAL FRONT LH	REPLACE	1.00	$209.00 Disc %: 10.00	188.10
23	LENS HEADLAMP LH	REPLACE	1.00	$1,248.00 Disc %: 10.00	1,123.20
24	LENS HEADLAMP RH	REPLACE	1.00	$1,248.00 Disc %: 10.00	1,123.20
25	MIRROR LH	REPLACE	1.00	$436.00 Disc %: 10.00	392.40
26	PAD COWLING LOWER LH	REPLACE	1.00	$79.00 Disc %: 10.00	71.10
27	PAD COWLING LOWER RH	REPLACE	1.00	$79.00 Disc %: 10.00	71.10
28	PAD HEADLIGHT	REPLACE	1.00	$15.00 Disc %: 10.00	13.50
29	PAD HEADLIGHT LH	REPLACE	1.00	$15.00 Disc %: 10.00	13.50
30	PAD RAD LH	REPLACE	1.00	$18.00 Disc %: 10.00	16.20
31	PAD RAD RH	REPLACE	1.00	$19.00 Disc %: 10.00	17.10
32	PAN INNER COWLING LH	REPLACE	1.00	$38.00 Disc %: 10.00	34.20
33	RADIATOR ASSY	REPLACE	1.00	$3,654.00 Disc %: 10.00	3,288.60
34	RIVET	REPLACE	5.00	$6.00 Disc %: 10.00	27.00
35	RIVET P/N: 60423	REPLACE	11.00	$12.00 Disc %: 10.00	? 118.80
36	SCREW TAPPING 5X16	REPLACE	15.00	$1.50 Disc %: 10.00	20.25

bizSAFE 3

S/N	Description	Action	Qty	Unit Price	Amount
37	STAY RADIATOR	REPLACE	1.00	$36.00 Disc %: 10.00	32.40
38	WASHER (6.5X16X1)	REPLACE	6.00	$1.00 Disc %: 10.00	5.40
39	WASHER NYLON (5.3X11.5X1.5)	REPLACE	2.00	$1.00 Disc %: 10.00	1.80
40	COWLING FRONT LH P/N: 64164	REPLACE	1.00	$85.00 Disc %: 10.00	76.50

SUB TOTAL	$15,953.75
GST @ 7 %	$1,116.76
GRAND TOTAL	**$17,070.51**

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

BAN HOCK HIN CO PTE LTD

RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Address: No. 6, Defu lane 4, Singapore 539410 | ***Telephone:*** +65 6281 6520 | ***Web:*** www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWERSINGAPORE 048623

Ref : CS/SMO19000360/Utd3e2

Date : 25-10-2019

Code : SMO

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	GBB 7835C	**Veh. Inspected**	FBL 7550X
	Policy No.		**Coverage ($)**	0.00
	Claim No.	CMTD1803120/AGC	**Excess ($)**	0.00
	Assign From	GRACE TEO	**Assign Date**	07/01/2019

2.	Vehicle Particulars & Condition			
	Make & Model	KAWASAKI ZZR1400 M	**c.c**	1441
	Engine No.	HIDDEN	**Year of Reg.**	2013
	Chassis No.	JKBZXT40EFA011060	**Colour**	BLUE
	Odometer	-	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	GOOD		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	120/70 ZR17	ROADSTONE	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	160/60 ZR17	ROADSTONE	6 mm
	L/H Rear Tyre			mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	20/07/2018	**Inspection Date**	08/01/2019
	Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**5 Working Days**

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 7550X

Qty	Description of Parts	Condition	Estimate By Workshop ($)	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	AXLE WHEEL FRONT (25X195)	NOT NECESSARY	252.00	-
2	BEARING STEERING CONE @$112.00	NOT NECESSARY	224.00	-
4	BOLT FLANGE @$4.00	NOT NECESSARY	16.00	-
3	BOLT FLANGE 6X12 @$4.00	NOT NECESSARY	12.00	-
2	BOLT SOCKET (5X20) @$5.00	NOT NECESSARY	10.00	-
8	BOLT SOCKET @$5.00	NOT NECESSARY	40.00	-
6	BOLT SOCKET 6X14 @$4.00	NECESSARY	24.00	24.00
1	BRACKET COMP. LH	BENT	90.00	90.00
1	BRACKET COWLING	BENT	30.00	30.00
1	BRACKET COWLING LOWER FRONT LH	BENT	34.00	34.00
1	BRACKET COWLING LOWER REAR LH	BENT	41.00	41.00
1	BRACKET DOWN SENSOR	NOT NECESSARY	82.00	-
1	BRACKET METER	BENT	616.00	616.00
1	HOSE COOLING RADIATOR	DAMAGED	244.00	244.00
1	LAMP SIGNAL FRONT LH	CRACKED	209.00	209.00
1	LAMP SIGNAL FRONT RH	NOT NECESSARY	209.00	-
1	LENS HEADLAMP LH	CRACKED	1,248.00	1,248.00
1	LENS HEADLAMP RH	CRACKED	1,248.00	1,248.00
1	LEVER CLUTCH	SERVICEABLE	159.00	-
1	MIRROR LH	CRACKED	436.00	436.00
1	MUDGUARD FRONT BLUE	TO REPAIR SEE LABOUR	837.00	-
9	NUT 5MM @$3.00	NOT NECESSARY	27.00	-
1	PAD	NOT NECESSARY	5.00	-
1	PAD (8X30X10)	NOT NECESSARY	5.00	-
1	PAD (8X30X3)	NOT NECESSARY	5.00	-
1	PAD COWLING LOWER LH	CRACKED	79.00	79.00
1	PAD COWLING LOWER RH	CRACKED	79.00	79.00
1	PAD HEADLIGHT	NECESSARY	15.00	15.00
1	PAD HEADLIGHT LH	NECESSARY	15.00	15.00
1	PAD RAD LH	NECESSARY	18.00	18.00
1	PAD RAD RH	NECESSARY	19.00	19.00
1	PAD SIDE COWLING RH	NOT NECESSARY	68.00	-
1	PAD TANK LH	NOT NECESSARY	61.00	-

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($)	Our Adjusted ($)
1	PAN INNER COWLING LH	DISTORTED	38.00	38.00
1	RADIATOR ASSY	BENT	3,654.00	3,100.00
5	RIVET @$6.00	NECESSARY	30.00	30.00
11	RIVET @$12.00	NOT NECESSARY	132.00	-
2	SCREW TAPPING 5X10 @$3.00	NOT NECESSARY	6.00	-
15	SCREW TAPPING 5X16 @$1.50	NECESSARY	22.50	22.50
1	STAY RADIATOR	DISTORTED	36.00	36.00
1	TRIM RADIATOR (LONG)	NOT NECESSARY	35.00	-
2	TRIM RADIATOR (SHORT) @$12.00	NOT NECESSARY	24.00	-
2	WASHER @$2.50	NOT NECESSARY	5.00	-
6	WASHER (6.5X16X1) @$1.00	NECESSARY	6.00	6.00
10	WASHER NYLON @$2.50	NOT NECESSARY	25.00	-
2	WASHER NYLON (5.3X11.5X1.5) @$1.00	NECESSARY	2.00	2.00
1	BRACKET MIRROR	CUT	313.00	313.00
1	BRACKET RADIATOR	BENT	79.00	79.00
1	BRACKET UNDER FORK	SERVICEABLE	2,674.00	-
1	BRACKET UPPER COWLING	NOT NECESSARY	15.00	-
2	BULB (12V 55W) H11 @$84.00	NOT NECESSARY	168.00	-
2	BULB (12V 65W) H9 @$112.00	NOT NECESSARY	224.00	-
1	CAP HOSE COOLING	NOT NECESSARY	118.00	-
4	COLLAR @$15.00	NECESSARY	60.00	60.00
1	COVER HEAT GUARD FRONT	BROKEN	258.00	258.00
1	COVER HEAT GUARD LH	BROKEN	198.00	198.00
1	COVER SIDE LH (BLACK)	BROKEN	686.00	686.00
1	COVER SIDE RH (BLACK)	TO REPAIR SEE LABOUR	686.00	-
1	COWLING FRONT LH	TORN	274.00	85.00
1	COWLING LOWER	CRACKED	692.00	692.00
1	COWLING LOWER LH	CRACKED	692.00	692.00
1	COWLING SIDE LH (BLUE)	CRACKED	1,418.00	1,418.00
1	COWLING UPPER (BLUE)	BROKEN	2,035.00	2,035.00
2	DAMPER @$5.00	NOT NECESSARY	10.00	-
4	DAMPER COWLING @$1.00	NOT NECESSARY	4.00	-
1	DUCT AIR LH	NOT NECESSARY	376.00	-
1	FAN RADIATOR ASSY LH	CRACKED / JAMMED	2,064.00	2,064.00
1	FAN RADIATOR ASSY RH	NOT NECESSARY	1,430.00	-

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($)	Our Adjusted ($)
	LESS 10% DISCOUNT		-	-1,625.95
			24,946.50	14,633.55
	LABOUR LABOUR - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED. INCLUSIVE OF THE REPAIR OF MUDGUARD FRONT BLUE AND COVER SIDE RH (BLACK).		560.00	350.00
			560.00	350.00
	GRAND TOTAL		**25,506.50**	**14,983.55**

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**11,800.00**

Report Ref No. CS/SMO19000360/Utd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.