NISSAN
SKM 4252 P

SKM 4252 P

SLJ 8406 R

# Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

| | |
|---|---|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 0996G |

## Vehicle Details

| | |
|---|---|
| Vehicle No.: | SKM4252P |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 26 Feb 2018 |
| Vehicle Make: | NISSAN |
| Vehicle Model: | ALMERA 1.5 4AT ABS AIRBAG 2WD 4DR |
| Primary Colour: | Blue |
| Manufacturing Year: | 2012 |
| Engine No.: | HR15920848B |
| Chassis No.: | MNTBBAN17Z0000542 |
| Maximum Power Output: | 73.0 kW (97 bhp) |
| Open Market Value: | $14,615.00 |
| Original Registration Date: | 27 Feb 2014 |
| First Registration Date: | 27 Feb 2014 |
| Transfer Count: | 0 |
| Actual ARF Paid: | $9,615.00 |

## Intended PARF Rebate Details

| | |
|---|---|
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 26 Feb 2024 |
| PARF Rebate Amount: | $7,211.00 |

## Intended COE Rebate Details

| | |
|---|---|
| COE Expiry Date: | 26 Feb 2024 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |

| | |
|---|---|
| COE Period(Years): | 10 |
| QP Paid: | $77,201.00 |
| COE Rebate Amount: | $46,320.00 |
| **Total Rebate Amount:** | **$53,531.00** |

The information contained herein is correct as at 26 Feb 2018

**OK**

AIG

HOTLINE TEL: (65) 6415 2000
FAX: (65) 6415-3723

# CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1990
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MX.1

AUTOPLUS (A)

**CERTIFICATE NO.** 2100365547-03000

**OWN DAMAGE EXCESS** $$800.00 (T)
**WINDSCREEN EXCESS** $$100.00
(the policies will offset from 1st November 2002)

**SUM INSURED** Market Value
**INSURING WITH COE/PARF** Yes

1 ) **VEHICLE REGISTRATION NO.** SKM4252P

2 ) **NAME OF INSURED** Xu Xinqiao

3 ) **EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT** 27 Feb 2017

4 ) **DATE OF EXPIRY OF INSURANCE** 26 Feb 2018

5 ) **PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE * SUBJECT TO AGE CONDITION :All Age Condition**

a) The Insured
b) Any other person who is driving on the Insured's order or with his permission
This policy will indemnify the Insured or any authorised driver only if he/she meets the age conditions.
A Young and/or Inexperienced Driver Excess ("YIDR") of $$1,000.00, in additional to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6 ) **LIMITATION AS TO USE ***

Use only for social, domestic and pleasure purposes and for the Insured's business.
The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

SOLE AGENT'S WORKSHOP : For new vehicles less than 3 years from initial registration, you have the option for claims-related repairs to be done at Sole Agent's workshop.
APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)
1. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 2. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
3. Ethoz - 30 Bukit Batok Crest (Tel:66547777) 4. DPS Body & Paint (Subsidiary of C &C) - 209 Pandan Gardens (Tel: 65684501)
5. Kan Fook Sing Motor - 61 Defu Lane 17 (Tel: 67479560) 6. Lai Huat (Meng Koei) Motor - 21 Sin Ming Ind (Tel: 64538110)
7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)
9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

**LOSS OF USE** Loss of Use 10 Days (1600cc) - Refer to policy wordings for details

**NAMED DRIVER** NA

**HIRE PURCHASE COMPANY / EMPLOYER'S LOAN** DBS BANK LTD

* *Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.*

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 22 Jan 2017

**AIG Asia Pacific Insurance Pte. Ltd.**

[illegible]
ONG TUCK SOON
371 ALEXANDRA ROAD
809-01 AIA ALEXANDRA
SINGAPORE 159963
SP-ABUNDANTLIFE

**AUTHORISED REPRESENTATIVE**

ORIGINAL


Copyright © 2013 AIG Asia Pacific Insurance Pte. Ltd.

**AUTOBAY TOWING**
1 Kaki Bukit Avenue 6
#01-55 AutoBay @ Kaki Bukit
Singapore 417883
Tel: 9015 8686 (Ah Boon)

(TWIN CAR)

# CASH SALE

No. _____

Sold to: SKM 4252P

Date: 26/2/18

| Item | Quantity | Description | Unit Price | Amount |
|---|---|---|---|---|
| | | Auto Hub to Ubi Ofc | | $100 |
| | | | | |
| | | Reporting Two Trips | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

E. & O. E.

| | |
|---|---|
| Sub Total : | |
| GST Tax : | |
| Total : | $100 |

Issued by: _____

CROWN

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

XU XINQIAO
87 WEST COAST DRIVE #02-14
SINGAPORE 128015

Contact : 65676261 91598016, 97616508

## TAX INVOICE

Date : 26/09/2018
Date in : 26/02/2018
Vehicle Num. : SKM4252P
Make/Model : NISSAN ALMERA 1.5 4AT ABS AIRBAG 2WD 4DR-2012
Chassis/Eng# : MNTEBAN17Z0000542/HR15920848B
Accident Date : 26/02/2018
Claim No : CLM14016
Reference : FEB-1:/2018
Policy No. : 2100365547-03000 (26/02/2018)

---

| | Amount S$ |
|---|---|
| LUMPSUM REPAIR BILL<br>AS PER SURVEYOR REPORT<br>REF : 0583-18-TCA DATED 24/09/2018<br>BY PAR AUTOMOTIVE CONSULTANCY | 19,300.00 |

---

E. & O.E.

| | |
|---|---|
| Sub S$ : | 19,300.00 |
| Add GST ( 7 % ) S$ : | 1,351.00 |
| Total Amount S$ | 20,651.00 |

for TWINCAR AUTOMOTIVE PTE LTD

# TWINCAR RENTAL

**Business Registration Number : 53092815M**
Blk 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921
Tel: 68420051 Fax : 67410510 email: sales@n51.com.sg

Invoice To :

XU XINQIAO
87 WEST COAST DRIVE
#02-14
SINGAPORE 128015

## INVOICE

Invoice No. 13-2265

Date 14/3/2018

| Hirer's Car No. | VHA No. | Terms |
|---|---|---|
| SKM4252P | 71608 | CASH |

| No. of Day | Description | Per Day | Amount (S$) |
|---|---|---|---|
| 16 | Car Rental from the period of 26/02/2018 to 14/03/2018.<br>Vehicle no. SKT6872A | 120.00 | 1,920.00 |
| | Singapore Dollars One Thousand Nine Hundred and Twenty Only | | |
| | | **Total** | **S1,920.00** |

TWINCAR RENTAL

TWINCAR RENTAL

Authorised Signature

# TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave. 2 #01-18
Singapore 417921 Tel: 6744 0510 / 6842 0051

VHA No: 71608 (7C)

ROC NO. 53092815M

## VEHICLE RENTAL AGREEMENT

**HIRER'S PARTICULAR**

Name: (as in I/C) XU XINQIAO

NRIC/PASSPORT No: S6880996G

Address (Res): 27 WEST COAST DRIVE #02-17 S (128015)

Name & Address of Employer:

Occupation: Driving Exp:

Driving Licence No: D/L Type: Local / International

Pass Date: Date of Birth: 29/12/1968

Tel: (O) (R) 6567 6261 HP 9159 8016

**ADDITIONAL DRIVER'S PARTICULARS**

Name: (as in I/C)

NRIC/PASSPORT No:

Address (Res):

Driving Licence No: D/L Type: Local / International

Pass Date: Date of Birth:

Occupation: Driving Exp:

Vehicle No: SKT6872A Replace Veh No: SKM4252P

Mileage Out: Mileage Out:

Make & Model: Auto / Manual Group:

OUT: Date 26 FEB 2018 Time: 10:15HRS

HIRE/PERIOD EXPIRY

NON-WAIVER EXCESS : $

**CHARGES**

| | | | | | |
|---|---|---|---|---|---|
| Daily | @ $ 120 | per day | 16 | 1920 | 00 |
| Weekly | @ $ | per week | | | |
| Monthly | @ $ | per month | | | |
| Hours | @ $ | per hour | | | |
| Others | @ $ | | | | |
| CDW | @ $ | per day/month | | | |
| PAI | @ $ | per day/month | | | |
| Delivery Service | | | | | |
| | | SUB-TOTAL $ | | | |

**PETROL LEVEL**

| | | | | | | |
|---|---|---|---|---|---|---|
| Out | E | 1/4 | 1/2 | 3/4 | F | |
| In | E | 1/4 | 1/2 | 3/4 | F | |

| | | |
|---|---|---|
| EXTENSION | | |
| Collection Service | | |
| Misc. | | |
| TOTAL CHARGE $ | 1920 | 00 |

Rented out by:

Hirer's Signature

Addition Driver's Signature

**VEHICLE CHECKLIST**

INDICATE: A - ACCIDENTS S - SCRATCHES D - DENTS




**ACCESSORIES CHECK**

| | | |
|---|---|---|
| ☐ Ashtray | ☐ Cig Lighter | ☐ S/Tyre |
| ☐ STD Tools | ☐ Jack | ☐ Hub Caps |
| ☐ Radio / Cass | ☐ CD | ☐ Cartidges |

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCAR RENTAL in connection with this Agreement is true.

*** IMPORTANT**

1. ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE TAHN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
2. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
3. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
4. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
5. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

| DATE IN | TIME IN | MILEAGE | CHECKED BY | REMARKS | |
|---|---|---|---|---|---|
| 14/03/2018 | 13:45HRS | | | | SIGNATURE OF HIRER/DRIVER |

# PAR Automotive Consultancy

Regn No: 52986974L

Thomson Rd Post Office PO Box 329 Singapore 915701. Tel : 645 31173, Fax : 645 36131.


Report No: 0583-18-TCA

24 September 2018

## ACCIDENT VEHICLE SURVEY REPORT

Xu Xinqiao
87 West Coast Drive #02-14
Singapore 128015

### VEHICLE INFORMATION:

| | | | |
|---|---|---|---|
| *Vehicle Reg No.:* | SKM4252P | *Odometer:* | 66899km |
| *Make & Model:* | Nissan Almera 1.5 | *Colour:* | Blue |
| *Chassis number:* | MNTBBAN17Z0000542 | *Date of accident:* | 26/02/2018 |
| *Year of Regn.:* | 27/02/2014 | *Date inspected:* | 01/03/2018 |
| *Repairer at:* | Twincar Automotive Pte Ltd<br>2 Kaki Bukit Ave 2 #01-17<br>Kaki Bukit Auto Hub<br>Singapore 417921 | Date inspected (After Repair): | 14/03/2018 |

### RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

### REMARKS:

We have inspected the above-mentioned vehicle on a **"Without Prejudice"** basis.

# PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0583-18-TCA

24 September 2018

Xu Xinqiao
87 West Coast Drive #02-14
Singapore 128015

**INVOICE No.** **0583-18-TCA**

Vehicle No. SKM4252P

| S/NO. | SERVICES RENDERED | Amount due |
|---|---|---|
| 1 | Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection). | |
| | | $1,237.00 |
| | **Total amount payable** | **$1,237.00** |

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

**PAR Automotive Consultancy**

# PAR Automotive Consultancy

Regn No: 52936974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.


Report No: 0583-18-TCA

24 September 2018

## ACCIDENT VEHICLE SURVEY REPORT

Xu Xinqiao
87 West Coast Drive #02-14
Singapore 128015

### VEHICLE INFORMATION:

| | | | |
|---|---|---|---|
| *Vehicle Reg No.:* | SKM4252P | *Odometer:* | 66899km |
| *Make & Model:* | Nissan Almera 1.5 | *Colour:* | Blue |
| *Chassis number:* | MNTBBAN17Z0000542 | *Date of accident:* | 26/02/2018 |
| *Year of Regn.:* | 27/02/2014 | *Date inspected:* | 01/03/2018 |
| *Repairer at:* | Twincar Automotive Pte Ltd<br>2 Kaki Bukit Ave 2 #01-17<br>Kaki Bukit Auto Hub<br>Singapore 417921 | *Date inspected (After Repair):* | 14/03/2018 |

### STATIC CHECKS, where applicable:

| | |
|---|---|
| *Steering :* | serviceable |
| *Footbrake :* | serviceable |
| *Handbrake :* | serviceable |
| *Paintwork :* | Good |
| *General condition :* | Good |

### TIRE CONDITION:

| | LH / Make | RH / Make | Size |
|---|---|---|---|
| *Front:* | 6mm/Falken | 6mm/Falken | 195/55R16 |
| *Rear:* | 6mm/Falken | 6mm/Falken | 195/55R16 |

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a **"Without Prejudice"** basis.

# PAR Automotive Consultancy

## Parts and Labour Assesment

**PARTS**

| Description of part | Qty | Condition | | Repairer's estimate | Our adjustment | |
|---|---|---|---|---|---|---|
| AIRCON CONDENSER AIR GUIDE L/R | 2 | warped | | 80.60 | 80.60 | ✗ SVC |
| FRONT BUMPER FOGLAMP COVER L/R | 2 | fractured | | 105.00 | 105.00 | ✗ SVC ✓ |
| FRONT BUMPER FOGLAMP L/R | 2 | fractured | | 643.20 | 643.20 | ✗ SVC |
| FRONT BUMPER REINFORCEMENT LH BRACKET | 1 | bent | 374.90 | 514.10 | 514.10 | ✗ SVC ✓ |
| FRONT BUMPER REINFORCEMENT RH BRACKET | 1 | bent | 374.90 | 514.10 | 514.10 | ✓ |
| FRONT BUMPER TOW HOOK COVER | 1 | fractured | | 25.50 | 25.50 | ✓ |
| FRONT RH CHASSIS SUB FRAME | 1 | repair | | 407.30 | 0.00 | ✗ R |
| RADIATOR LOWER MEMBER GARNISH | 1 | deformed | | 38.00 | 38.00 | ✓ |
| REAR EXHAUST RUBBER MOUNTING | 2 | distorted | | 34.20 | 34.20 | ✗ SVC |
| REAR EXHAUST SILENCER BOX | 1 | bent | | 545.10 | 545.10 | ✗ SVC |
| REAR RH CHASSIS SUB FRAME | 1 | repair | | 180.50 | 0.00 | ✗ R |
| REAR RH FLOOR EXTENSION PANEL | 1 | repair | | 86.50 | 0.00 | ✗ R |
| REAR SPARE TYRE INNER UPHOLSTERY BOARD COVER | 1 | fractured | | 189.50 | 189.50 | ✗ NN |
| | | Subtotal before discount | | S$ 3,363.60 | S$ 2,689.30 | |
| Percentage discount 30% and 30% | | | | S$ 1,009.08 | S$ 806.79 | |
| | | **Sub-total 1** | | S$ 2,354.52 | S$ 1,882.51 | |
| FRONT BONNET MECHANISM LOCK | 1 | bent | | 71.10 | 71.10 | ✗ SVC |
| FRONT BONNET RUBBER GUIDE STOPPER L/R | 2 | deformed | | 30.00 | 30.00 | ✗ SVC |
| FRONT BUMPER | 1 | squashed | 323.70 | 518.00 | 518.00 | ✓ |
| FRONT BUMPER INNER GARNISH | 1 | warped | | 58.30 | 58.30 | ✓ |
| FRONT BUMPER INNER SPONGE | 1 | deformed | 108 | 188.80 | 188.80 | ✓ |
| FRONT BUMPER LOWER COVER | 1 | deformed | | 60.50 | 60.50 | ✗ SVC |
| FRONT BUMPER REINFORCEMENT | 1 | bent | | 468.60 | 468.60 | ✗ SVC ✓ |
| FRONT CHASSIS FRAME LOWER BRACKET L/R | 1 ~~2~~ | bent | 30 | 60.00 | 60.00 | ✓ (RH) |
| FRONT GRILLE | 1 | fractured | 264 | 775.90 | 775.90 | ✓ |
| FRONT GRILLE 'LOGO' EMBLEM | 1 | necessary | | 59.70 | 59.70 | ✓ |
| FRONT HEADLAMP L/R | 2 | fractured | 546.40 | 1,798.20 1697.80 | 1,798.20 | ✗ SVC ✓ |
| FRONT HEADLAMP PANEL L/R | 2 | repair | | 70.20 | 0.00 | ✗ R |
| FRONT RH FENDER | 1 | buckled | 326.70 | 603.10 | 603.10 | ✗ R ✓ |
| FRONT RH FENDER INNER SHIELD | 1 | fractured | | 138.10 | 138.10 | ✗ SVC |
| FRONT TOP PANEL | 1 | bent | | 294.20 | 294.20 | ✗ ~~SVC~~ R |
| RADIATOR LOWER MEMBER | 1 | bent | | 80.10 | 80.10 | ✗ ~~SVC~~ R |
| REAR BOOTLID | 1 | buckled | 638.90 | 846.00 | 846.00 | ✓ |
| REAR BOOTLID 'ALMERA' EMBLEM | 1 | necessary | | 52.10 | 52.10 | ✓ |
| REAR BOOTLID 'LOGO' EMBLEM | 1 | necessary | | 52.10 | 52.10 | ✓ |
| REAR BOOTLID HINGES L/R | 2 | bent | | 176.00 | 176.00 | ✓ |
| REAR BOOTLID MECHANISM LOCK | 1 | bent | | 64.50 | 64.50 | ✓ |
| REAR BOOTLID MECHANISM LOCK STRIKER | 1 | bent | | 57.90 | 57.90 | ✗ SVC B |
| REAR BOOTLID OUTER GARNISH | 1 | fractured | 264.30 | 358.90 | 358.90 | ✓ |
| REAR BOOTLID WEATHERSTRIP | 1 | deforme | | 101.50 | 101.50 | ✓ |
| REAR BUMPER | 1 | squashed | | 541.20 | 541.20 | ✓ |
| REAR BUMPER BRACKET L/R | 2 | bent | | 173.20 | 173.20 | ✗ SVC ✓ |

# PAR Automotive Consultancy

| | | | | |
|---|---|---|---|---|
| REAR BUMPER CORNER BRACKET L/R | 2 | bent | 61.80 | 61.80 |
| REAR BUMPER END SEAL COVER L/R | 2 | deformed | 67.00 | 67.00 |
| REAR BUMPER INNER SPONGE | 1 | deformed | 106.70 | 106.70 |
| REAR BUMPER SIDE RETAINER L/R | 2 | necessary | 62.20 | 62.20 |
| REAR END PANEL | 1 | buckled | 398.30 | 398.30 |
| REAR END PANEL ANTENNA SENSOR | 1 | shorted | 51.50 | 51.50 |
| REAR END PANEL INNER TOP GARNISH | 1 | fractured | 109.70 | 109.70 |
| REAR EXHAUST GASKET | 1 | necessary | 10.00 | 10.00 |
| REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R | 2 | deformed | 352.60 | 352.60 |
| REAR FENDER L/R | 2 | buckled | 1,819.40 | 1,819.40 |
| REAR SPARE TYRE PANEL | 1 | buckled | 597.50 | 597.50 |
| REAR SPARE TYRE RETAINER LOCK | 1 | bent | 48.20 | 48.20 |
| REAR TAILLAMP INNER PANEL L/R | 2 | buckled | 329.60 | 329.60 |
| REAR TAILLAMP L/R | 2 | fractured | 528.60 | 528.60 |
| REAR TYRE JACK | 1 | bent | 192.00 | 192.00 |
| WIPER WASHER TANK WITH MOTOR | 1 | deformed | 238.80 | 238.80 |
| | | Subtotal before discount | S$ 12,672.10 | S$ 12,601.90 |
| Percentage discount 10% and 10% | | | S$ 1,267.21 | S$ 1,260.19 |
| | | **Sub-total 2** | S$ 11,404.89 | S$ 11,341.71 |
| AIRCON CONDENSER AIR GUIDE CLIPS L/R - SET | 2 | necessary | 60.00 | 40.00 |
| FRONT BUMPER CLIPS - SET | 1 | necessary | 50.00 | 50.00 |
| FRONT BUMPER LOWER COVER CLIPS - SET | 1 | necessary | 40.00 | 40.00 |
| FRONT BUMPER SIDE RETAINER L/R | 2 | necessary | 44.20 | 44.20 |
| FRONT GRILLE CLIPS - SET | 1 | necessary | 30.00 | 30.00 |
| FRONT NUMBER PLATE | 1 | bent | 25.00 | 25.00 |
| FRONT NUMBER PLATE HOLDER | 1 | front | 50.00 | 50.00 |
| FRONT RH FENDER INNER SHIELD CLIPS - SET | 1 | necessary | 50.00 | 50.00 |
| RADIATOR COOLANT - BOT | 1 | reuse | 80.00 | 0.00 |
| REAR BOOTLID OUTER GARNISH CLIPS - SET | 1 | necessary | 30.00 | 30.00 |
| REAR BOOTLID REVERSE CAMERA | 1 | shorted | 800.00 | 800.00 |
| REAR BUMPER CLIPS - SET | 1 | necessary | 50.00 | 50.00 |
| REAR BUMPER END SEAL COVER CLIPS L/R - SET | 2 | necessary | 60.00 | 60.00 |
| REAR BUMPER REVERSE SENSOR - SET | 1 | shorted | 350.00 | 350.00 |
| REAR END PANEL INNER TOP GARNISH CLIPS - SET | 1 | necessary | 30.00 | 30.00 |
| REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET | 2 | necessary | 60.00 | 60.00 |
| REAR SPARE TYRE | 1 | reuse | 280.00 | 0.00 |
| REAR TAILLAMP CLIPS L/R - SET | 2 | necessary | 60.00 | 60.00 |
| REAR WARNING TRIANGLE SIGN ASSY | 1 | reuse | 120.00 | 0.00 |
| REAR WINDSCREEN GLASS SEALANT | 1 | necessary | 100.00 | 100.00 |
| | | Subtotal before discount | S$ 2,369.20 | S$ 1,869.20 |
| | | **Sub-total 3** | S$ 2,369.20 | S$ 1,869.20 |
| | | **Parts-total** | **S$ 16,128.61** | **S$ 15,093.42** |

# PAR Automotive Consultancy

**LABOUR**

| | | | |
|---|---|---|---|
| To remove, change air con parts, vacuums, refill air con gas. | 180.00 | 0.00 | |
| To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor. | 200.00 | 140.00 | 150 |
| To remove and refit rear windscreen(to FR) | 150.00 | 120.00 | |
| To remove, install engine with transmission. (to FR) | 450.00 | 0.00 | |
| To remove, reinstall front suspension undercarriage parts. (to FR) | 600.00 | 0.00 | |
| To remove, reinstall rear suspension and undercarriage part. (to FR) | 500.00 | 0.00 | |
| To road test driving, check and resetting wheel alignments system. | 180.00 | 0.00 | |
| To remove, reinstall petrol tank. (to FR) | 100.00 | 80.00 | |
| To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR) | 150.00 | 120.00 | |
| To send vehicle for cleaning, shampoo, upholstery and cushion seat. | 200.00 | 150.00 | |
| To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper. | 2,000.00 | 1,320.00 | 900 |
| To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper. | 1,400.00 | 1,320.00 | 900 |
| To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident. | 180.00 | 120.00 | |
| To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. | 4,800.00 | 3,750.00 | 1600 |
| To mount vehicle on to Car 'O' Liner. | 400.00 | 400.00 | |
| To apply anti-rust chemical on repaired and replaced panel. | 150.00 | 150.00 | |
| **Labour Total** | **S$ 11,640.00** | **S$ 7,670.00** | |
| **Parts & Labour Total** | **S$ 27,768.61** | **S$ 22,763.42** | |

Results of inspection of the accident vehicle are as shown above.

12 days

We have taken into consideration the age and condition of the vehicle in our recommendation.

**Hence, the recommended cost of repairs based on Lump Sum repairs is : S$ 19,300.00 and the recommended number of working days for the repairs is within 19 day(s).**

B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser