Surveyor [illegible] | REF: ASM(AXA) | 09/04 COE XPIRY. 2021/JAN

ASSIGNMENT

From: | Date: 17-01-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 4053L

at Workshop m/s Accord Auto

of Blk 1009 Bukit Merah Lane 3 # 01-80

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition) after 3pm

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 26K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SMA 4053L Yr Regn: 2011 JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN JETTA 1.4 c.c 1390

Colour BLACK A/C: Insured / Std / NI / NA

Sp.Reading 128 551 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ1KZAM144201

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 16/01/19 D.O.I. 17/01/19

Survey held at ACCORD AUTO

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	repair limit 7k

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp ($) $ + RS $

☐ Interview ($) Photos

☐ Tech. Invs ($) Others

☐ Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)