Surveyor: Tanghin | REF: A24 | 180 | 74 a3 | Cx

ASSIGNMENT

From: | Date: 18012019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKP 8940U

at Workshop m/s: Volkswagen

of: 247 Alexandra Rd

Insured:

Policy No.:

Claims No.:

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $5716.

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SKP8940U. | Yr Regn: 2014 Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Golf SR HD | C.C 1395

Colour: Blue | A/C: Insured / Std / NI / NA

Sp.Reading: 47445. | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ1KZFW048343

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18.

R: 〃 〃.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	18/1/19 @ 1140

Survey held at: VW Alexander

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Rebate $43,262

Date/Time, File Pass to? (1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? (2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech Invs ($) ☐ : Weekend ($)

Survey Fee:

Transportation:) S + RS S1

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)