ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised
L/Sup 8 ?
Resurvey After Paint
4 days

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date :	15/01//2019
Vehicle No :	SJC1399J
Veh Make/Model :	Honda Fit 1.3G A
YOM :	2007
Chassis No :	GE61020693
Date of Accident :	12/01/2019

No	Qty	Description	Amount $	
		List Items:-		
1	1	Rear RH door	$ 746.10	✓
2	1	Rear RH door outer moulding	$ 50.60	X
3	1	Rear RH door frame black sticker (center)	$ 36.20	—
4	1	Rear RH door frame black sticker (rear)	$ 36.20	—
5	1	Rear RH door outer handle	$ 75.60	X
6	1	Rear RH door lock	$ 231.60	X
7	1	Rear RH door lock striker	$ 25.10	X
8	1	Rear RH door regulator	$ 374.20	?
9	1	Rear RH door weatherstrip	$ 100.20	?
10	1	Rear RH door inner trim board	$ 495.00	X
11	1	Rear RH fender	$ 652.40	X
12	1	Rear RH fender spalsh shield	$ 32.60	X
13	1	Rear bumper	$ 497.20	X
14	2	Rear bumper side retainer	$ 33.00	X
15	1	RH rocker panel	$ 387.20	X
		Total - List Item	**$ 3,773.20**	
		Less 20%	**$ 754.64**	
		Total	**$ 3,018.56**	
		Special Nett Items:-		
1	1 Set	Rear reverse sensor	$ 380.00	X
2	1	Rear RH wheel rim	$ 682.40	250SN
3	10	Rear RH door inner trim board clip	$ 35.00	X
4	10	Rear RH fender spalsh shield clip	$ 35.00	X
5	10	Rear bumper clip	$ 35.00	X
		Total - SN Item	**$ 1,167.40**	
		Balance b/f	**$ 4,185.96**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date :	15/01//2019
Vehicle No :	SJC1399J
Veh Make/Model :	Honda Fit 1.3G A
YOM :	2007
Chassis No :	GE61020693
Date of Accident :	12/01/2019

No	Qty	Description	Amount $	
		Balance c/f	**$ 4,185.96**	
		Labour Charges:-		
1		Spray painting on all affected area.	$ 1,100.00	800
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	$ 1,200.00	500
3		To apply anti rust treatment.	$ 120.00	30
4		To check wiring system & light.	$ 80.00	20
5		To check & adjust wheel alignment.	$ 120.00	60
6		To remove and replace reverse sensor.	$ ~~ 120.00	
7		To remove and replace tire, rim and on wheel balancing.	$ 120.00	20
8		To transfer rear RH door inner compartment, mechanism, assy &etc., to new door.	$ 80.00	60
9		To transfer rear RH door windscreen glass to new door.	$ 60.00	
		Total - L/C	**$ 3,000.00**	
		Sub-Total	**$ 7,185.96**	
		7% GST	**$ 503.02**	
		Total	**$ 7,688.98**	