ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised **ESTIMATE**

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Lt Lup 87
Resurvey After Paint
5 days

Date :	22/01/2019
Vehicle No :	SJQ1317Y
Veh Make/Model :	Toyota Vios E 1.5 A
YOM :	2009
Chassis No :	MR053HY9305109433
Date of Accident :	20/01/2019

No	Qty	Description	Amount $	
		List Items:-		
1	1	Boot lid	$ Bu 678.00	—
2	1	Boot lid center garnish	$ Sn 395.91	X
3	1	Boot lid "VIOS" emblem	$ Ne 71.50	—
4	1	Boot lid "E" emblem	$ Ne 81.50	—
5	1	Boot lid logo	$ Ne 61.42	—
6	1	Boot lid lock	$ Ne 97.31	—
7	1	LH tail lamp	$ Sn 127.69	X
8	1	LH tail lamp gasket	$ Sn 48.70	X
9	1	RH tail lamp	$ Sn 187.60	X
10	1	RH tail lamp gasket	$ Sn 48.60	X
11	1	Rear bumper	$ Bu 379.81	—
12	2	Rear bumper side retainer	$ N/S Bu 70.57	—
13	2	Rear bumper side bracket	$ Sn 49.18	X
14	10	Rear bumper clip	$ Ne 48.00	—
15	1	Rear bumper reflector (LH)	$ CM 76.35	—
16	1	Rear bumper reflector (RH)	$ Sn 76.35	X
17	1	LH air duct	$ Sn 96.17	X
18	1	RH air duct	$ Sn 96.17	X
19	1	End panel	$ 495.90	?
20	1	End panel top garnish	$ Ne 156.81	—
21	6	End panel top garnish clips	$ Ne 28.80	—
22	1	Floor panel	$ R 697.84	X
		Total - List Item	**$ 4,070.18**	
		Less 25%	**$ 1,017.55**	
		Total	**$ 3,052.64**	
		Balance b/f	**$ 3,052.64**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date :	22/01/2019
Vehicle No :	SJQ1317Y
Veh Make/Model :	Toyota Vios E 1.5 A
YOM :	2009
Chassis No :	MR053HY9305109433
Date of Accident :	20/01/2019

No	Qty	Description	Amount $	
		Balance c/f	**$ 3,052.64**	
		Special Nett Items:-		
1	1	Rear number plate with holder	$ CRA 55.00	45sn
2	1 Set	Rear reverse sensor	$ SRA 380.00	200sn
3	1	Boot lid compartment waterproof sealant	$ NN 200.00	X
		Total - SN Item	**$ 635.00**	
		Labour Charges:-		
1		Spray painting on all affected area.	$ 900.00	600l
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	$ 1,100.00	600l
3		To apply anti rust treatment.	$ 120.00	30l
4		To check wiring system & light.	$ 80.00	20l
5		To remove and replace reverse sensor.	$ 120.00	50l
6		To check and test boot lid water leaking.	$ 100.00	20l
7		To adjust exhaust silencer system.	$ NN 150.00	X
		Total - L/C	**$ 2,570.00**	
		Sub-Total	**$ 6,257.64**	
		7% GST	**$ 438.03**	
		Total	**$ 6,695.67**	