

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

LONPAC

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
 ACCIDENT DATE : 26/01/2019@2040HRS
 VRN : SJX2059Z
 MODEL : Kia Cerato Forte Koup
 TP VRN : GQ1888B

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
--	------------	-----------------	----------------	------------------

PARTS REPLACEMENT

1. Body Repair

1 Front Bumper <i>pg</i>	1	\$	688.00	\$	688.00
2 Front Bumper Clips <i>me</i>	10	\$	6.00	\$	60.00
3 Front Bumper Outer Bracket LH/RH <i>me</i>	1pc 2	\$	<u>59.00</u>	\$	118.00 X
4 Front Bumper Lower Grille X	1	\$	249.00	\$	249.00
5 Front Centre Grille <i>CA</i>	1	\$	251.00	\$	251.00
6 Front Bumper Undertray X	1	\$	112.00	\$	112.00
7 Fog Lamp RH X	1	\$	316.00	\$	316.00
8 Headlamp RH <i>BPO</i>	1	\$	595.00	\$	595.00
9 Headlamp Lower Bracket RH <i>FA</i>	1	\$	61.00	\$	61.00
10 Front Fender RH <i>repair</i>	Repair	\$	-	\$	-
11 Front Fender Shield RH <i>turn</i>	1	\$	121.00	\$	121.00
12 Front Fender Shield Clips RH <i>me</i>	10	\$	6.00	\$	60.00
13 Bonnet <i>MA</i>	1	\$	962.00	\$	962.00
14 Bonnet Hinge LH/RH X	2	\$	79.00	\$	158.00
15 Washer Tank <i>sch</i>	1	\$	92.00	\$	92.00
16 Towing Fees	s/nett	\$	50.00	\$	50.00

Discount 10%

\$ (384.30)

TOTAL \$ 3,508.70

2. Labor Charges

1 Panel beat, cut, weld, re-align and replace damaged Front parts of affected area	<i>650</i>	\$	1,000.00
2 Spray painting on Front portion of affected area	<i>750</i>	\$	1,000.00
3 Check wiring, re-align Headlamp and ensure proper function		\$	300.00
4 Refill compressor oil, vacuum and refill aircond gas		\$	180.00

Resul
Hp 90010068 Sub Total : \$ 2,260.00

Grand Total : \$ 5,768.70
 Add 7% GST : \$ 403.81
 Nett Total : \$ 6,172.51

No. of repair days: 5

5 days
43
30/01/19 @ 1240
Resumy after repair