Rasu | REF: | 2991C

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 32K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No SKW 9915A Yr Regn. 2011 JUN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA CIVIC 1.8LA c.c 1799

Colour BLACK A/C: Insured / Std / NI / NA

Sp.Reading 156494 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMFD1630AS200487

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm

D.O.A. 01/02/19 D.O.I. 18/02/19

Survey held at KOH MOTOR

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit 3K
	refer to email

Date/Time, File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation ($ + RS SI

Add Fee: ☐ Site Insp ($) ☐ Interview ($) ☐ Tech Invs ($) ☐ Weekend ($)

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)