Surveyor: Taufikh   REF: 14 Ch 2531/71.D

ASSIGNMENT

From: Date:	Veh No: SMD 8282A Yr Regn: 2017 Mod.
Estimated Cost	Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
OD (KFK) / WS / TP RES / OD RES / EVA / INV / MV	Make: BMW 216D c.c: 1496.
To inspect Vehicle No:	Colour: Grey. A/C: Insured / Std / NI / NA
at Workshop m/s	Sp.Reading: 41972. T/Radio: Insured / Std / NI / NA
of	Eng/No:
Insured	C/No: WBA2E32080 5H46076.
Policy No	Gen. Cond: Good / Fair / Poor / Burnt
Claims No	Steering: Inorder / Jammed / Leaked / Burnt or
Sum Insured: Excess:	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / S/Rim / STD A/Rim or
Make of Veh:	Tyre Size: F: 205/55R17
	R: ~
(Policy Condition) N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Remark: The veh had commenced its repair at the time of inspection.	Front Rear
Bal. or Market Value:	R/Bal. 6 mm R/Bal. 6 mm
IDAC Accident Rport: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	D.O.A. D.O.I. 11/3/19
Est. Repairs: days Res.: Yes or No	Survey held at PML
Lum Sum: % 3 Val.: Yes or No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time   Action / Instruction

Date/Time: File Pass to?
1)
Date/Time: File Return to?
2)

: Preli. Report
: Final Report

Days Of Repair:
Resurvey No. of Trip:

Add Fee: Site Insp ($)
Interview ($)
Tech. Invs ($)
Weekend ($)

Survey Fee:
Transportation
5+RS SI
Photos
Other
Total

Report Format:
Lump Sum / LB: ($)