Taughlin | REF: EQ

ASSESSMENT

Date: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop no:

of:

Insured:

Policy No:

Claim No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: $145K.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time: Action / Instruction

Veh No: SLF413 | E Yr Regn: 2016 Aug.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Land Rover Discovery Sport c.c: 1999

Colour: Grey. A/C: Insured / Std / NI / NA

Sp.Reading: 48342 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SALCA2AG9GH566213.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SPRim / STD A/Rim or

Tyre Size: F: 235/55R19

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A.: D.O.I.: 4/3/19 @ 2.30pm

Survey held at: Weames 45 Lay Kee

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Rebate $108,984

Date/Time: File Pass to?

1) ☐ : Preli. Report

☐ : Final Report

Date/Time: File Return to?

2)

Report Format

Lump Sum / I.B.I: B

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp ($

☐ Interview ($

☐ Tech Insp ($

☐ Weekend ($

Survey Fee:

Transportation

) S + P: $

) Photos

) Other

) TOTAL