INS CASE OWNER: CC 3, CTI 1900 3166 , 1/4 pos" IDAC:

ASSIGNMENT

Surveyor: Amk DOI: 19/7/19 Date / Time: 19/7/19

Registered to Merimen:

Pre-assign / CCU / FTE GBG 5507L

Insured Vehicle No. : Claim No. : GRM1962008670217

Name of Insured : Leong Guan Food Trading P/L Policy No. :

Insured Tel No. : HP: Make / Model :

Excess Sec II :S$ D.O.A : 18/07/19 Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : OI GIA REPORT: YES / NO , TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % Final ? Yes / No

SHC 8014Y →

INSRS: WSP: Tel: Liability: RMKS:

INSRS: WSP: Tel: Liability: RMKS:

INSRS: WSP: Tel: Liability: RMKS:

INSRS: WSP: Tel: Liability: RMKS:

Date/ Time	
16/4 CM	SHC8014Y, [illegible]
	GBG 5507L - X
23/5/19	FILE PAS TO MAIL TO CLOSE

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	22/7/19 23/7/19

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)		
After call ltr to OI:	✓	
Authorisation To Act:	✓	
Release Voucher:	✓	
Final Repair Bill:	✓	
Car Rental Invoice:	✓	
Towing Invoice		
LTA / GIA :	✓	
Medical Bill:		
PIR:		
Mandate/Reject Instruction:		
LOD	✓	
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S$ (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 16/5/19 Confirm with William Email ✓ Call ☐

Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 27	If NO or B 28, Ass. Lia :
Repair Cost: (w/GST)	S$ 2247.00	
Loss of Rental (LOR):	S$ 443.38 (2.5 days) × $177.43	
Loss of Use (LOU):	S$ – ($ x days)	
Loss of Income (LOI):	S$ 125.00 ($ 50 x 2.5 days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ✓ [Tick only one]	
GIA/LTA Search	S$ 7.49	
Medical:	S$ –	1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$ – (e.g. Tow/ Independent)	2) Report Format: TP
Legal Cost	S$ –	3) Survey fee: $440
Total:	S$ 2825.07 Global Sum S$: 2800.00	

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1:	S$ 2800.00	Name 1:	Comfort Delgro Engineering Pte Ltd
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

23/7/19

Surveyor: Kelvin

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

at

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Model Value:

ICAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Cum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SH C8014Y Yr Regn: 28 May, 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / TOW / Prime Mover / Truck / Trailer or

Make: Mercedes Benz E220 cc 2143

Colour: L/Blue A/C: Inoperd / Std / Nil / NA

Sp.Reading: 699136 T/Radio: Inoperd / Std / Nil / NA

Eng/No:

C/No: WDD2120012B178538

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoperd / Jammed / Leaked / Burnt or

Brake: Inoperd / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	18/2/19	D.O.I.	19/2/19

Survey held at CDGE (Loyang)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	CTI
	4/2
	L/S - $2100 (Red $2126 | 50%)

Date/Time, File Post to?

1) : Prell. Report

: Final Report

Date/Time, File Return to?

2)

Report Format

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp ($) : Interview ($) : Tech Insp ($) : Treatment ($)

Survey Fee:

Transportation:

$ + RS $

Photo

Draft

LKK Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA

Our ref: CC3/CTI19003166/K1pa3

Date: 22/02/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SHC 8014Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.02.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S$	4,426.00	
Revised Estimate Amount	: S$	2,100.00	
"Check" Items Amount	: S$	-	
Total (Including Check Items)	: S$	2,100.00	
Market Value	: S$	-	(est.)
LTA Reimbursement Value	: S$	-	(est.)
Nett Value	: S$	-	(est.)

Description of Damage:
The vehicle sustained damages at the Rear N/S Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 2.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8014Y **DATE 19/2/2019 9:43**

MAKE :

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			$ 1,510.00
	Rear Bumper Reinforcement			$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH)		$ 135.00	$ 270.00
	Rear Bumper Bracket Top (LH/RH)		$ 125.00	$ 250.00
	Rear Bumper Retainer Mounting (LH/RH)		$ 115.00	$ 230.00
	Rear Bumper Lower Cover			$ 325.00
	SUB TOTAL			**$ 3,735.00**
	LESS 20%			$ 747.00
	DISCOUNTED TOTAL			**$ 2,988.00**
	Rear Bumper Sensor			**$ 388.00** Nett
	Labour Charge			
	Panel Beating			$ ~~400.00~~ 200
	Spray Painting Charge			$ 400
	Wiring Charge			$ ~~30.00~~
	Remove/Refix Reverse Sensor			$ ~~120.00~~
	TOTAL LABOUR			**$ 850.00**
	ESTIMATE TOTAL		4426	**$ 4,226.00**

Kalish 10194

19/2/19 1125L

2 Days

4/5

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

CHMA

VEHICLE NO : SHC 8014Y **DATE 19/2/2019 9:43**

MAKE :

Chuang

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			$ 1,510.00
	Rear Bumper Reinforcement ?			$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH) ?		$ 135.00	$ 270.00
	Rear Bumper Bracket Top (LH/RH) ?		$ 125.00	$ 250.00
	Rear Bumper Retainer Mounting (LH/RH) ?		$ 115.00	$ 230.00
	Rear Bumper Lower Cover			$ 325.00
	Rear boot lid X repair			
	SUB TOTAL			**$ 3,735.00**
	LESS 20%			$ 747.00
	DISCOUNTED TOTAL			**$ 2,988.00**
	Rear Bumper Sensor			**$ 388.00** Nett
	Labour Charge			
	Panel Beating			$ ~~400.00~~ 200
	Spray Painting Charge		~~500~~	$ 400
	Wiring Charge			$ ~~30.00~~ X
	Remove/Refix Reverse Sensor			$ ~~120.00~~ 2
	TOTAL LABOUR			**$ 850.00**
	ESTIMATE TOTAL			**$ 4,226.00**

Kalvin 18/19

19/2/19 1125L

2 Days

4/5

After Repair photo

LMK Auto Consultants hence notify the Repairer of the following:

Authorised by:

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

COMFORTDELGRO

Date/Time: 19.02.2019 11:13 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305270293

TOMER

MS COMFORT TRANSPORTATION PTE LTD

TOMER NO. 7010045

RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755 (O)

(P)

DOUNT CARD NO.

REGN NO.: SHC8014Y	MILEAGE
MAKE: MERCEDES BENZ	FUEL E 1/2 F
MODEL: E220CDI(E6)	DATE/TIME IN: 18.02.2019 18:45
YR OF MANU: 28.05.2015	TARGET DATE
CHASSIS CODE: WDD2120012B178538	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 18.02.2019
NATURE: 3P 18.02.2019

S/NO	LABOR CODE	DESCRIPTION



OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wledgement Slip

e No.: SHC8014Y CHIANG

of Service Advisor

Signature/Date

eturned to Service Reception upon collection

Exit Pass

Vehicle No.: SHC8014Y

Name of Service Advisor

Date

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305270293

Date : 21/02/19

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHC8014Y

18/02/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: CHINA GBG5507L

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable) $2100.00
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : **CHIANG**

Tel : 62148314

Fax : 65468156

Signature :

Name : Kalvin

Date : 21/2/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Mei Kwan (LKKAuto)

From:	Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent:	Monday, 15 April, 2019 12:52 PM
To:	Mei Kwan (LKKAuto); Admin A; CS A Team
Cc:	Elaine Cheong; Hsiao Tong (LKKAuto); Alfred Toh
Subject:	RE: Direct Settlement - Accident Involving GBG5507L (OI: SNM19D200867C02/7) and SHC8014Y (TP : LKK REF - CC3/CTI19003166/K1pa3) on 18/02/2019
Attachments:	REPORT OF GBG5507L.pdf
Categories:	HMK

LKK REF - CC3/CTI19003166/K1pa3
CTI REF – SNM19D200867C02/7 (GBG5507L)

Dear Mei Kwan/Hsiao Tong

We refer to your emails pertaining to the above matter.

Attach herewith Insured's SAS report of your attention and necessary action.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID : (65) 6389 6183
FAX: (65) 6224 7478
W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Monday, 15 April, 2019 11:45 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBG5507L (OI: SNM19D200867C02/7) and SHC8014Y (TP : LKK REF - CC3/CTI19003166/K1pa3) on 18/02/2019
Importance: High

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Kindly take note that the case handler in-charge Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

---

Jia Le (LKK Auto)

From:	Jia Le (LKK Auto)
Sent:	Thursday, 16 May 2019 2:19 PM
To:	William Tan Thoo Seng
Cc:	Hsiao Tong (LKKAuto)
Subject:	RE: Your Ref: SHC8014Y *Our Ref: CC3/CTI19003166/K1pa3 [ACCIDENT INVOLVING GBG5507L & SHC8014Y ON 18/02/2019]
Attachments:	SHC 8014Y.pdf

WITHOUT PREJUDICE

Dear Sirs/Mdm,

DV attached.

Thank you.

Best Regards,
Carlor Chan | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: William Tan Thoo Seng [mailto:williamtan@cdge.com.sg]
Sent: Thursday, 16 May 2019 11:00 AM
To: Jia Le (LKK Auto)
Cc: Hsiao Tong (LKKAuto)
Subject: Re: Your Ref: SHC8014Y *Our Ref: CC3/CTI19003166/K1pa3 [ACCIDENT INVOLVING GBG5507L & SHC8014Y ON 18/02/2019]

Without Prejudice.

Dear Jia Le

We are glad to accept your global offer at $2,800.00.

Kindly forward your D.V. .

Thank you.

Best Regards
William Tan
Claims Department | ComfortDelgro Engineering Pte Ltd
Off : 62148737 | Fax : 62141843

From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Sent: Thursday, 16 May 2019 10:34:26 AM
To: William Tan Thoo Seng
Cc: Hsiao Tong (LKKAuto)
Subject: Your Ref: SHC8014Y *Our Ref: CC3/CTI19003166/K1pa3 [ACCIDENT INVOLVING GBG5507L & SHC8014Y ON 18/02/2019]

WITHOUT PREJUDICE

Dear Sirs/Mdm,

ACCIDENT INVOLVING GBG 5507L & SHC 8014Y ON 18/02/2019

We refer to the above matter.

We propose settlement at a global sum of **$2,800.00(all-in).**

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Carlor Chan | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents herein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

GENERAL INSURANCE ASSOCIATION
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: 196550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCD619022940 Vehicle Registration No: SHC8014Y

Name(as shown in NRIC) : NEO BAN SENG NRIC/FIN/Passport No : _____

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : _____ Singapore( )

Contact (Tel) : _____ Mobile No. : _____

Email Address : _____

Date of Accident : 18/02/2019 Time of Accident : 16:45

Place of Accident : ADMIRALTY RD W TOWARDS WOODLANDS AVE 10

Insurance Company : India International Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

ENCLOSED AMENDED POLICE REPORT NO: T/20190220/2060

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: JANET
NRIC/FIN No.:
Date: 21.02.2019

Address	BLK 497A TAMPINES STREET 45 #10-08
Postcode	520497
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes,Please state which Police Station	
Police Station Name	TAMPINES NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	**ROAD**: BLK 461 TAMPINES STREET 44 #01-56 , **POSTCODE:** 520461 , **COUNTRY**: SINGAPORE
Police Station Contact	**TEL NO**: 1800-7818999 - **FAX NO**: 67838603
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20190220/2000

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG5507L
Vehicle Make/Model/Colour	TOYOTA DYNA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ZHANG WEI
NRIC/Passport Number	
Contact Number	G8666145X
Address	
Postcode	

SINGAPORE POLICE FORCE

T/20190220/2060

Report No. T/20190220/2060

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
20/02/2019 12:26		10

Informant's Particulars

Name of Informant: NEO BAN SENG			Address: APT BLK 497A TAMPINES STREET 45 #10-08 SINGAPORE 520497	
ID Type / ID No.: NRIC NO / S1426371C			Contact No.: Home/Office:	Mobile: 97559984
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 58	Date of Birth: 08/04/1960	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,2,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/02/2019 16:45	Type of Location: T-Junction

Location:
Along Road 1
ADMIRALTY ROAD WEST

junction of Woodlands Ave 10

Weather: Clear	Road Surface: Dry	Road Speed Limit:
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear		Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBG5507L	Lorry	TOYOTA	DYNA	Silver	Slightly Damaged	0
SHC8014Y	Car	MERCEDES BENZ	E220	White	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

CONTINUATION OF REPORT

Driver					
Name	ZHANG WEI			ID No.	G8666145X
Related Vehicle	GBG5507L (Lorry)			Contact No.	98917791
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL	

Driver					
Name	NEO BAN SENG			ID No.	S1426371C
Related Vehicle	SHC8014Y (Car)			Contact No.	97559984
Hospital/Clinic	A LIFE CLINIC PTE LTD			Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	20/02/2019		Date Discharge	20/02/2019	
No. of Days granted Medical Leave		07	Degree of Injury	Slight	

Brief Details.

On 18.02.2019 at about 1645hrs, I was driving my vehicle (SHC8014Y) along Admiralty Road West junction of Woodlands Ave 10 alone when the traffic light turned amber. I stopped my vehicle in a stationary position when a lorry collided into the rear portion of my vehicle. As nobody required any Ambulance Service, we exchange particulars and left the scene.

On 20.02.2019 at about 1100hrs, I went to A Life Clinic Pte Ltd to seek medical treatment and was given 7 day s of out patient leave. That is all.

S1426371C

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Staff Sgt TAN HOCK CHYE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 20/02/2019 12:26
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt MOHAMAD ZULFAZDLI BIN ABDULLAH Contact No.: 65476204	Classification Of Case:

Authentication Stamp
NP168

SINGAPORE POLICE FORCE

SHC 8014 Y

SHC8014Y


GBG
5507L

LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES
S / No. 9000286777

GBG
5507L

REPUBLIC OF SINGAPORE
DRIVING LICENCE
G8665145X
ZHANG WEI
19 Mar 1997
05 Oct 2016

SHC 8014 Y

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref : CC3/CTI19003166/K1pa3n2

Date : 24-05-2019

Code : CTI

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	GBG 5507L	**Veh. Inspected**	SHC 8014Y
	Policy No.	DMCVSN3053631800	**Coverage ($)**	0.00
	Claim No.	SNM19D200867C02/7	**Excess ($)**	0.00
	Assign From		**Assign Date**	19/02/2019

2.	Vehicle Particulars & Condition			
	Make & Model	MERCEDES BENZ E220	**c.c**	2143
	Engine No.	HIDDEN	**Year of Reg.**	2015
	Chassis No.	WDD2120012B178538	**Colour**	WHITE
	Odometer	699136	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	FAIR		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	225/55 R16	WEST LAKE	7 mm
	L/H Front Tyre	225/55 R16	WEST LAKE	7 mm
	R/H Rear Tyre	225/55 R16	WEST LAKE	7 mm
	L/H Rear Tyre	225/55 R16	WEST LAKE	7 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	18/02/2019	**Inspection Date**	19/02/2019
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**2 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8014Y

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,510.00	1,510.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	1,150.00	-
2	REAR BUMPER BRACKET LOWER (LH/RH) @$135.00	CRACKED	270.00	270.00
2	REAR BUMPER BRACKET TOP (LH/RH) @$125.00	SERVICEABLE	250.00	-
2	REAR BUMPER RETAINER MOUNTING (LH/RH) @$115.00	SERVICEABLE	230.00	-
1	REAR BUMPER LOWER COVER	CUT	325.00	325.00
1	REAR BOOT LID (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-747.00	-421.00
			2,988.00	1,684.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER SENSOR (SN)	SHORTED	388.00	388.00
			388.00	388.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		400.00	200.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.	NOT NECESSARY	30.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			1,050.00	630.00
	GRAND TOTAL		**4,426.00**	**2,702.00**

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**2,100.00**

Report Ref No. CC3/CTI19003166/K1pa3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.