Assignment: Pasu | REF: III | 8086C

ASSIGNMENT

From: | Date: 28/02/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 3665A

at Workshop m/s: MBM Wheelpower

160 ~~176~~ Sin Ming Drive # 06-15 #06

Insured:

Policy No:

Claims No:

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S | O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR. Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SLR 3665A | 1st Regn: 2017 Auch

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA CHR HYBRID 1.8G | c.c: 1797

Colour: BLACK | A/C: Insured / Std / NI / NA

Sp.Reading: 30248 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 24X10 2018479

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / A/Rim / STD A/Rim or

Tyre Size: F: 225/50R18

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 21/02/19 | D.O.I. 28/02/19

Survey held at: MBM WHEEL POWER

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp ($) S + RS S

☐ Interview ($) Photo

☐ Tech. Invs ($) Other

☐ Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL