INS. CASE OWNER: NORSIAH | CC 6 /AIG1900 2506, UK3532 | LKK: IDAC:

ASSIGNMENT

Surveyor: Mahmus DOI: 25/7/19 Date / Time : 25/7/19.

Registered in Merimen: 25/7/19.

Pre-assign / CCU / FTE

Insured Vehicle No. : SJX 8762M. Claim No. : 7456202323/19

Name of Insured : ANTHONY MALLEY Policy No. :

Insured Tel No. : HP: Make / Model :

Excess See II :S$ D.O.A : 17/7/19 Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If **NO**. Driver Name / Age : OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

FBH 1551D → → →

INSRS: WSP: BHH Tel : Liability : RMKS:

INSRS: WSP: Tel : Liability : RMKS:

INSRS: WSP: Tel : Liability : RMKS:

INSRS: WSP: Tel : Liability : RMKS:

Date/ Time	
	FBH1551D - X SJX8762M - X
	- NO OI GIA (SENT OUT 1ST LETTER)
	- OI VIDEO UPLOADED IN MERIMEN
	OI REPORTED TP CLAIM.
	- FINALIZED
	- ORIGINAL TP LOD IN
30/07/19 @ 4PM	- SPOKE TO OI. CONFIRMED ACCIDENT DETAILS & DISPUTED ON CAUSALITY. INFORMED TP CLAIM. OI SAID VIDEO PROVIDED TO RC. NO UPDATE FROM C/UC W/ REGARDS TO HIS CLAIM. SEND EMAIL TO OI TO NOTIFY TP CLAIM.
22/08/19	- EMAIL TO AIG TO REBOOT CLAIM
	- AIG APPROVED TO REBOOT CLAIM
04/10/19	- EMAIL TO TP REBOOT CLAIM

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	30/07/19 - VIC

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)		
After call ltr to OI: EMAIL	✓	
Authorisation To Act:	✓	
Release Voucher:	✓	
Final Repair Bill:	✓	
Car Rental Invoice:		
Towing Invoice		
LTA / GIA:	✓	
Medical Bill:		
PIR:	✓	
Mandate/Reject Instruction:	✓	
LOD		
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE Date/Time: Sent By: VIC

FINALIZATION Date/Time: Confirm with: Approved by: Confirm by:

Repair Cost: L/S S$ 790.00 (4 days) Reduction: 60 % 06/11/19 Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: Confirm with Email ☐ Call ☐

Final Liability: % 0 (Agreed / Assessed) BOLA S/N No. : 33 If NO or B 28, Ass. Lia :

Repair Cost: S$ — CTP OUTSTANDING OI

Loss of Rental (LOR): S$ — (days) OI VIDEO IN

Loss of Use (LOU): S$ — (S x days) OI CHANGING

Loss of Income (LOI): S$ — (S x days) LANE.

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ **[Tick only one]**

COPY SENT 7/11/19

GIA/LTA Search S$ —

Medical: S$ — 1) Claim status: Normal/Reject/Private Settle

Disbursement: S$ — (e.g. Tow/ Independent) 2) Report Format:

Legal Cost S$ — 3) Survey fee: $820.00

Total: S$ **Global Sum S$:**

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1:	S$ —	Name 1:	—
Payee 2: (Strike if N.A.)	S$ —	Name 2:	—
Payee 3: (Strike if N.A.)	S$ —	Name 3:	—

(08/11/13) wef

ASS. REC. BY: Marcus

REF: A147

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBH 1551D

at Workshop m/s BHH

of

Insured: SJX 8262M

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 3800

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 4 days Res.: **Yes** or **No**

Lum Sum: % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS 0288/K Vehicle: **IN / OUT**

Date: Person Contacted:

Veh No: FBH 1551D Yr Regn: 3/13

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: Yamaha YBR c.c 124

Colour Red A/C: **Insured / Std / NI / NA**

Sp.Reading 99014 T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: LBPKE178SD0009993

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 2.25-18

R: 90/90-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	mm	L/Bal.	mm
D.O.A.	12/2/19	D.O.I.	25/2/19

Survey held at

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or Mstd / O/S Body

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	LTA 769 4yrs. Nett 3031
	LG $790.00
	CROD: $1,208.00 (60%)

Date/Time, File **Pass** to? ☐ : **Preli. Report**

1) ☐ : **Final Report**

Date/Time, File **Return** to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL

BAN HOCK HIN Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 33680

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

Not Authorised
Leak
2/S $790
4 day.
Thought. After rep
25/2/19

DATE : 19/02/2019
CLAIM NO. : 11274
POLICY NO. : AVFMSB0000591803

FROM : RAYMOND

VEHICLE NO. : FBH1551D
MAKE/MODEL : YAM / YBR125

S/N	Description	Action	Qty	Unit Price		Amount
1	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	$180.00	SU	180.00
2	BUSH SWINGARM (METAL) P/N: 29093	REPLACE	2.00	$5.00	11	10.00
3	BUSH SWINGARM (RUBBER) P/N: 29092	REPLACE	2.00	$12.00	11	24.00
4	CLIP TUBE INNER FORK P/N: 35796	REPLACE	2.00	$5.00	11	10.00
5	COVER SIDE LH (BLACK) P/N: 45775	REPLACE	1.00	$118.00	1	118.00
6	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	$90.00	CU	90.00
7	COVER TANK SIDE LH (RED) P/N: 49207	REPLACE	1.00	$119.00	CU	119.00
8	CRASH BAR P/N: 35878	REPLACE	1.00	$195.00	Bent	195.00
9	FOOTREST FRONT P/N: 42064	REPLACE	1.00	$80.00	To.1	80.00
10	GUIDE AIR LH P/N: 48403	REPLACE	1.00	$23.00	11	23.00
11	HANDLE SEAT P/N: 42567	REPLACE	1.00	$98.00	SCR	98.00
12	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	8.00	$35.00	200	280.00
13	LEVER BRAKE P/N: 26343	REPLACE	1.00	$19.00	SCR	19.00

112

S/N	Description	Action	Qty	Unit Price		Amount
14	LEVER CLUTCH P/N: 52644	REPLACE	1.00	$19.00	SER	19.00
15	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	$98.00	CW	98.00
16	OIL FORK (UNICORN) MR-10 P/N: 54320	REPLACE	1.00	$10.00	11	10.00
17	PROTECTOR MUFFLER (REAR) P/N: 27115	REPLACE	1.00	$32.00	Bey	32.00
18	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	$14.00	To.1	14.00
19	SEAL OIL (18X24X4) SWINGARM BUSH P/N: 29094	REPLACE	2.00	$8.00	11	16.00
20	SEAL OIL (30X41X10) FORK P/N: 13451	REPLACE	2.00	$24.00	11	48.00
21	STEERING CONE SET P/N: 41793	REPLACE	1.00	$68.00	11	68.00
22	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE *	2.00	$16.00	1m	32.00 S.N
23	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	REPLACE *	1.00	$16.00	1m	16.00 S.N
24	SWING ARM P/N: 25340	REPLACE	1.00	$138.00	11	138.00
25	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE.	*	1.00	$35.00		35.00
26	TUBE INNER FORK P/N: 27114	REPLACE	2.00	$98.00	1	196.00
27	VISOR P/N: 43130	REPLACE	1.00	$30.00	CM	30.00

SUB TOTAL	$1,998.00
GST @ 7 %	$139.86
GRAND TOTAL	**$2,137.86**

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

BAN HOCK HIN CO PTE LTD

RAYMOND

LKK Auto Consultants needs notify the Repairer of the following:
- To remove [illegible] painting
- To [illegible] paint during survey
- Parts [illegible]
- [illegible] "Without Prejudice" basis
- No [illegible] is allowed
- Supplementary [illegible] must be issued and is subject to final approval from Insurance Company

Acknowledge & Accepted By

Acknowledged by Repairer
Signature:
Date:

P-794
102
714.60
997.6
798

This quotation is sent via email / LAN-Fax and will bear a computer generated signature

BAN HOCK HIN Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 33680 - Rev. 1

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 19/02/2019
CLAIM NO. : 11274
POLICY NO. : AVFMSB0000591803

FROM : RAYMOND

VEHICLE NO. : FBH1551D
MAKE/MODEL : YAM / YBR125

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	$90.00 Disc %: 10.00	81.00
2	COVER TANK SIDE LH (RED) P/N: 49207	REPLACE	1.00	$119.00 Disc %: 10.00	107.10
3	CRASH BAR P/N: 35878	REPLACE	1.00	$195.00 Disc %: 10.00	175.50
4	FOOTREST FRONT P/N: 42064	REPLACE	1.00	$80.00 Disc %: 10.00	72.00
5	HANDLE SEAT P/N: 42567	REPLACE	1.00	$98.00 Disc %: 10.00	88.20
6	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	1.00	$200.00	200.00
7	LEVER BRAKE P/N: 26343	REPLACE	1.00	$19.00 Disc %: 10.00	17.10
8	LEVER CLUTCH P/N: 52644	REPLACE	1.00	$19.00 Disc %: 10.00	17.10
9	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	$98.00 Disc %: 10.00	88.20
10	PROTECTOR MUFFLER (REAR) P/N: 27115	REPLACE	1.00	$32.00 Disc %: 10.00	28.80
11	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	$14.00 Disc %: 10.00	12.60
12	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	2.00	$16.00	32.00
13	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	REPLACE	1.00	$16.00	16.00

S/N	Description	Action	Qty	Unit Price	Amount
14	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE.		1.00	$35.00	35.00
15	VISOR P/N: 43130	REPLACE	1.00	$30.00 Disc %: 10.00	27.00

SUB TOTAL	$997.60
GST @ 7 %	$69.83
GRAND TOTAL	**$1,067.43**

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

BAN HOCK HIN CO PTE LTD

RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Acknowledge & Accepted By

BAN HOCK HIN Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : **33680**

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

Not Allowed
Leak
2/5 8
4 day.
The pbl. After rep
25/2/19

DATE : 19/02/2019
CLAIM NO. : 11274
POLICY NO. : AVFMSB0000591803

FROM : RAYMOND

VEHICLE NO. : FBH1551D
MAKE/MODEL : YAM / YBR125

S/N	Description	Action	Qty	Unit Price		Amount
1	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	$180.00		180.00 ?
2	BUSH SWINGARM (METAL) P/N: 29093	REPLACE	2.00	$5.00	11	10.00 ✗
3	BUSH SWINGARM (RUBBER) P/N: 29092	REPLACE	2.00	$12.00	11	24.00 ✗
4	CLIP TUBE INNER FORK P/N: 35796	REPLACE	2.00	$5.00		10.00 ?
5	COVER SIDE LH (BLACK) P/N: 45775	REPLACE	1.00	$118.00	1	118.00 ✗
6	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	$90.00	cn7	90.00
7	COVER TANK SIDE LH (RED) P/N: 49207	REPLACE	1.00	$119.00	cn	119.00
8	CRASH BAR P/N: 35878	REPLACE	1.00	$195.00	Bert	195.00
9	FOOTREST FRONT P/N: 42064	REPLACE	1.00	$80.00	To.1	80.00
10	GUIDE AIR LH P/N: 48403	REPLACE	1.00	$23.00		23.00 ?
11	HANDLE SEAT P/N: 42567	REPLACE	1.00	$98.00	SCR	98.00
12	LABOUR * P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	8.00	$35.00	200	280.00
13	LEVER BRAKE P/N: 26343	REPLACE	1.00	$19.00	SCR	19.00

112

S/N	Description	Action	Qty	Unit Price		Amount
14	LEVER CLUTCH P/N: 52644	REPLACE	1.00	$19.00	S&R	19.00
15	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	$98.00	CM	98.00
16	OIL FORK (UNICORN) MR-10 P/N: 54320	REPLACE	1.00	$10.00	CM	10.00
17	PROTECTOR MUFFLER (REAR) P/N: 27115	REPLACE	1.00	$32.00	Bey	32.00
18	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	$14.00	To.1	14.00
19	SEAL OIL (18X24X4) SWINGARM BUSH P/N: 29094	REPLACE	2.00	$8.00		16.00 ?
20	SEAL OIL (30X41X10) FORK P/N: 13451	REPLACE	2.00	$24.00		48.00 ?
21	STEERING CONE SET P/N: 41793	REPLACE	1.00	$68.00		68.00 ?
22	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	2.00	$16.00	1	32.00
23	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	REPLACE	1.00	$16.00	1	16.00
24	SWING ARM P/N: 25340	REPLACE	1.00	$138.00	11	138.00 X
25	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE.		1.00	$35.00		35.00
26	TUBE INNER FORK P/N: 27114	REPLACE	2.00	$98.00	2	196.00 X
27	VISOR P/N: 43130	REPLACE	1.00	$30.00	CM	30.00

SUB TOTAL	$1,998.00
GST @ 7 %	$139.86
GRAND TOTAL	**$2,137.86**

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

BAN HOCK HIN CO PTE LTD

RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0288K
Vehicle Details	
Vehicle No.:	FBH1551D
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	YAMAHA
Vehicle Model:	YBR 125 MANUAL
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	E3J2E008393
Chassis No.:	LBPKE1785D0009993
Maximum Power Output:	-
Open Market Value:	$1,267.00
Original Registration Date:	21 Mar 2013
First Registration Date:	21 Mar 2013
Transfer Count:	1
Actual ARF Paid:	$191.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	$1,895.00
COE Rebate Amount:	$769.00
Total Rebate Amount:	**$769.00**

The information contained herein is correct as at 26 Feb 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	FBH1551D
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	YAMAHA
Vehicle Model :	YBR 125 MANUAL
Chassis No. :	LBPKE1785D0009993
Propellant :	Petrol
Engine No. :	E3J2E008393
Engine Capacity :	124 cc
Maximum Power Output :	-
Maximum Laden Weight :	285 kg
Unladen Weight :	124 kg
Year Of Manufacture :	2013
Original Registration Date :	21 Mar 2013
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
Quota Premium :	$1,895.00
COE Expiry Date :	20 Mar 2023
Road Tax Expiry Date :	20 Mar 2019
Inspection Due Date :	20 Mar 2020
Intended Transfer Date :	22 Feb 2019
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 20 Mar 2019. You may renew the road tax from 21 Dec 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 20 Mar 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 21 Mar 2019 to 20 Sep 2019)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	32.00	-	32.00
Total Amount Payable :			**57.00**

Amount Payable (From 21 Mar 2019 to 20 Mar 2020)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	64.00	-	64.00
Total Amount Payable :			**89.00**

You may print this page for reference.

OK Print

Bike model
Yamaha YBR125

Type
Any

Price From
Any

Price To
Any

Class
Any

MORE SEARCH OPTIONS

SEARCH VIEW ALL (/LISTING/USEDBIKES/LISTING/)

SEARCH

Yamaha YBR125 (/listing/usedbike/yamaha-yamaha-ybr125/10196/)

(/listing/usedbike/yamaha-yamaha-ybr125/10196/)

SGD$2200

Reg : **17/08/2010**

Type: **Street Bikes**

124cc

72400km

Posted on : 19/02/2019

★ PAID AD ★ DIRECT SELLER

COMPARE DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YBR125/10196/)

Yamaha YBR125 (/listing/usedbike/yamaha-yamaha-ybr125/11413/)

(/listing/usedbike/yamaha-yamaha-ybr125/11413/)

SGD$4800

Reg : 28/06/2014

Type: Street Bikes

124cc

-

Trade in/Loan, many other brand new and used motorcycles available. Come visit us at Ban Hon Brothers (Agencies) Pte Ltd. Block 5022, Ang Mo Kio Industrial Park 2 #01-19 Singapore 569525.
Well Maintained. COE till 2024.

Posted on : 14/02/2019

★ PAID AD ★ DEALER AD

COMPARE DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YBR125/11413/)

Yamaha YBR125 (/listing/usedbike/yamaha-yamaha-ybr125/3497/)

(/listing/usedbike/yamaha-yamaha-ybr125/3497/)

-

Reg : 14/07/2010

Type: Street Bikes

124cc

43000km

Road tax just renewed and passed inspection. Wonderful Yamaha YBR125. COE till Jul 2020. New "o" ring chain and sprocket, tyres. Aug: Just change lube oil, spark plug, new pair of fork and m...

Posted on : -

★ PAID AD ★ DIRECT SELLER

COMPARE DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YBR125/3497/)

Yamaha YBR125 (/listing/usedbike/yamaha-yamaha-ybr125/3917/)

View Received Message

This mail is associated with :

***SMH7433S (7456203433SG)**
[SJX8262M]
TP
BAN HOCK HIN CO PTE LTD
Feb 12 2019 12:00AM

Ban Hock Hin Co. Pte Ltd

Reply | Reply All | Mark as Unread | Print Message | Delete Message | Forward

From **AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG)**, sent on **26/02/2019 10:09 AM.**
To LKK_HQ
Subject **No OI GIA Report**

Hi,

Please be informed that no OI GIA report received till date.

Please find OI details below for your further action.

OI name: ANTHONY MALLEK

Address:

1 PECK HAY ROAD CASA CAIRNHILL
#05-04
SINGAPORE 228305

Contact No: 96178262

Regards,
Sheng Yang

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19003506/Ujb3

27 February, 2019

ANTHONY MALLEK
1 PECK HAY ROAD CASA CAIRNHILL
#05-04
SINGAPORE 228305

Dear Sirs,

ACCIDENT INVOLVING FBH 1551D AND SJX 8262M ON 12.02.2019 ALONG/ AT KIM SENG PROMENADE

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any mendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Joy Irene
Claims
Tel : 6841 2409
Fax: 6741 4108
Email : joyirene@lkkauto.com

c.c. Claims Manager
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

MCC419020327 / Cycle & Carriage Industries Pte Ltd - Pandan Loop
ENTRY DATE & TIME: 13/02/2019 16:31
SUBMITTED BY: Lim Xin Yi

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	13/02/2019 16:31
Date Of Accident	12/02/2019 19:20
Exact Location Of Accident	KIM SENG PROMENADE/GREAT WORLD CITY TOWER CP ETR
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJX8262M
Insured/Policyholder	
Name Of Registered Owner	ANTHONY MALLEK
NRIC No	S2608852F
Email Address	NOEMAIL TONYM@sph.com.sg
Mobile Phone No	(LOCAL) +65-96178262
Alternative Phone No	Office-96178262
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	GLC200
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700088549-01
Cover Note Number	
Driver	
Name of Driver	ANTHONY MALLEK
NRIC No	S2608852F
Date Of Birth	05/11/1954
Occupation	INDOOR
Date Of Driving Pass	31/12/1991
Driving Experience	27 YEARS AND 1 MONTH

Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	SNN HAO
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Kim Seng Promenade, slowed down, signalled right and was about to turn right into the carpark when Car B (motor-cycle) tried to overtake my car from the right and knocked into the right front door of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4553 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cycleandcarriage.com.sg

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name:
NRIC/FIN No.:

Accident Sketch Plan

Vic (LKKAuto)

From:	Vic (LKKAuto)
Sent:	Friday, 4 October, 2019 12:12 PM
To:	Raymond
Cc:	Admin A; Vic (LKKAuto)
Subject:	RE: Accident Involving FBH1551D & SJX8262M on 25/02/2019 *** LKK REF: CC6/AIG19003506/Uhb3
Attachments:	Video.WMV; video (1).WMV

Without Prejudice

Dear Raymond,

We refer further to our below email.

Please be informed that our principal had further reviewed the matter and based on the available information and evidence at hand, it was observed that our Insured was travelling within its lane when signalled to turn right towards the car park entrance when your client overtook from the right. Oru Insured was ahead and your client should have keep a proper safety distance and lookout for our turning vehicle. Please see attached video footage.

As such, we have our principal's instruction and that we are unable to look into your client's claim.

We will now close the matter in our end.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth· Print only when necessary·

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Raymond [mailto:raymond@bhh.com.sg]
Sent: Tuesday, 10 September, 2019 8:49 AM
To: Vic (LKKAuto)
Cc: Admin A

Vic (LKKAuto)

From: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Sent: Friday, 4 October, 2019 11:46 AM
To: Vic (LKKAuto)
Cc: Admin A
Subject: RE: <REJECTION APPROVAL> RE: Your Ref: 7456203433SG_ACCIDENT INVOLVING VEHICLES SJX 8262M AND FBH 1551D ON 12/02/2019 LKK REF CC6/AIG19003506/Uhb3

Dear Vic,

Please proceed.

Thank you

Kind regards
Norsiah

Norsiah Md Noor
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419-1606
Norsiah.MdNoor@aig.com | www.aig.com.sg

AIG 100 Celebrating 100 Years: Visit 100.aig to learn more.

Follow us:

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Vic (LKKAuto) [mailto:vicalpeh@lkkauto.com]
Sent: Friday, September 6, 2019 11:35 AM
To: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: [EXTERNAL] <REJECTION APPROVAL> RE: Your Ref: 7456203433SG_ACCIDENT INVOLVING VEHICLES SJX 8262M AND FBH 1551D ON 12/02/2019 LKK REF CC6/AIG19003506/Uhb3

This message is from an external sender; be cautious with links and attachments.

Dear Norsiah,

We refer to our below email.

For your approval and/or further instructions please.

Thank you.

Best Regards,
Vic Alpeh | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth· Print only when necessary·

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)
Sent: Thursday, 22 August, 2019 10:23 AM
To: Md Noor, Norsiah
Cc: Admin A; Vic (LKKAuto)
Subject: Your Ref: 7456203433SG_ACCIDENT INVOLVING VEHICLES SJX 8262M AND FBH 1551D ON 12/02/2019 LKK REF CC6/AIG19003506/Uhb3

Your Ref: 7456203433SG
Our Ref: CC6/AIG19003506/Uhb3

Dear Norsiah,

ACCIDENT INVOLVING VEHICLES SJX 8262M AND FBH 1551D ON 12/02/2019

We refer to the above matter.

It was reported by Insured that TP vehicle overtook him vehicle when making a turn towards the car park.

The Insured had strongly denied liability and provided a copy of their video footage which shows the entire incident (uploaded in merimen).

Based on the footage, Insured vehicle was within the lane when TP vehicle overtook his turning vehicle when the collision occurred.

As such, we would like to reject the TP claim.

For your approval and/or further instructions please.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth· Print only when necessary·

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Tuesday, 30 July, 2019 4:17 PM
To: tonym@sph.com.sg
Cc: Admin A; Vic (LKKAuto)
Subject: Your Ref: SJX 8262M_ACCIDENT INVOLVING SJX 8262M AND FBH 1551D ON 12/02/2019

Our Ref: CC6/AIG19003506/Uhb3

30 JULY 2019

MR ANTHONY MALLEK

Dear Sir,

ACCIDENT INVOLVING SJX 8262M AND FBH 1551D ON 12/02/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of FBH 1551D against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant. Unless proven otherwise.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **10/08/2019**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Vic Alpeh | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd *Save the Earth· Print only when necessary·*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

AUTHORISATION TO ACT

I, Ban Hock Hin Co Pte Ltd (the third party claimant) of 6 Defu Lane 4 Singapore 539410 (address), owner of FBH1551D (vehicle no.) hereby authorize Ban Hock Hin Co Pte Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. FBH1551D that was damaged pursuant to the accident which occurred on 12/02/2019 (date) along Kim Seng Promenade (location) involving vehicle no/s SJX8262M ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 21st (day) of March (month) 2019 (year)

BAN HOCK HIN CO. PTE LTD

Signed by "the third party claimant"
(with chop if applicable)

BAN HOCK HIN CO. PTE LTD

Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Ban Hock Hin Co. Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S$** 845.30 (Repair Cost), **S$** 80.00 (Loss of rental/use), **S$** 2.00 (Disbursement), for vehicle no. FBH1551D that was damaged pursuant to the accident which occurred on 12/02/2019 (date) along Kim Seng Promenade (location) involving vehicle no/s SJX8262M. This is pursuant to the inspection conducted on 25/02/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Ban Hock Hin Co Pte Ltd ("the third party claimant") of vehicle no. FBH1551D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to FBH1551D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21st (day) of March (month) **20**19 (year)

BAN HOCK HIN CO. PTE LTD

Signed by appointed surveyor

Signed by "the workshop" (with chop)

BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

TAX INVOICE

GST Reg No. : M2-0010542-7

Customer :
AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

Invoice No. : **LECR20036591-I11274**
Invoice Date : 06/03/2019
Payment Due Date : 05/04/2019

CLAIM NO. : 11274
POLICY NO. : AVFMSB0000591803
VEHICLE NO. : FBH1551D
MAKE/MODEL : YAM / YBR125

S/N	Description		Amount
1	LUMPSUM REPAIR		$790.00
		SUB TOTAL	$790.00
		GST @ 7 %	$55.30
		GRAND TOTAL	**$845.30**

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Printed by : RAYMOND

GENERAL INSURANCE ASSOCIATION
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-028050
Date of Request: 21/02/2019 Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 21/02/2019
Enquiry By Tan Chok Lok
TP Vehicle No. SJX8262M
Accident Date 12/02/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJX8262M	AIG Asia Pacific Insurance Pte. Ltd.	14/12/2018-13/12/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

GENERAL INSURANCE ASSOCIATION
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-028050
Date of Request: 21/02/2019 Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 21/02/2019
Enquiry By Tan Chok Lok
TP Vehicle No. SJX8262M
Accident Date 12/02/2019

DESCRIPTION	AMOUNT (S$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:
Date:
[X] GIRO [ ] Cash [ ] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Feb 2019 Edit Reg		25 Feb 2019 00:00 Edit Adj Rpt	**S$790.00** Edit Estimates	**S$790.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | **Reference** | **Claim Details** | **Documents** | Show All

CLAIM SUBFOLDER DETAILS **[Created by adjuster]**

Insured:	**ANTHONY MALLEK**, ID: S2608852F		
Main Claimant:	**BAN HOCK HIN CO PTE LTD**, Co. Reg. No.: 197000288K		
Vehicle Reg. No.:	**FBH1551D**	Date of Loss:	12/02/2019 00:00 - :59 [**70** Months and **22** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 7456203433SG	Policy/Cover Note No.:	1700088549 (Comprehensive)
Vehicle Reg. No. (Insured):	**SJX8262M**	Policy No. (Claimant):	AVFMSB0000591803
		Excess:	
Repairer:	**Ban Hock Hin Co. Pte Ltd (HQ)** No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	**AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **MdNoor, Norsiah**] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	**Allied World Assurance Company, Ltd (HQ)** - Tel: 62201188		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MARCUS CHUA**] ... [**Final Rpt** due 06/03/2019]		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

- AIG_SG (31/07/2019): **Re: <REQUEST FOR VIDEO FOOTAGE> Re: No OI GIA Report**
- AIG_SG (26/02/2019): **No OI GIA Report**
- AIG_SG (26/02/2019): **Request To Upload TP GIA Report**

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***FBH1551D (7456203433SG)**
[SJX8262M]
TP
BAN HOCK HIN CO PTE LTD
Feb 12 2019 12:00AM
[ANTHONY MALLEK]
Ban Hock Hin Co. Pte Ltd

Upload Documents | Upload Photos | Compose New Letter | Upload Video | Upload Audio

View: View in Browser

Video — 1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	22/08/19 10:03	**Video** Front video		Load WMV	
2	22/08/19 10:04	**video** BAck		Load WMV	

Assessment Reports — 1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	08/03/19 16:15	**Accident Statement** From:SC - Reg. No: SJX8262M, Claimant: ANTHONY MALLEK		Load HTM	

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/04/19 19:38	**General View**		Load JPG	✓
2	11/04/19 19:38	**General View**		Load JPG	✓
3	11/04/19 19:38	**General View**		Load JPG	✓
4	11/04/19 19:38	**General View**		Load JPG	✓
5	11/04/19 19:38	**General View**		Load JPG	✓
6	11/04/19 19:38	**General View**		Load JPG	✓
7	11/04/19 19:38	**General View**		Load JPG	✓
8	11/04/19 19:38	**General View**		Load JPG	✓
9	11/04/19 19:38	**General View**		Load JPG	✓
10	11/04/19 19:38	**General View**		Load JPG	✓
11	11/04/19 19:38	**General View**		Load JPG	✓
12	11/04/19 19:38	**General View**		Load JPG	✓
13	11/04/19 19:38	**General View**		Load JPG	✓
14	11/04/19 19:38	**General View**		Load JPG	✓
15	11/04/19 19:38	**General View**		Load JPG	✓
16	11/04/19 19:38	**General View**		Load JPG	✓
17	11/04/19 19:38	**General View**		Load JPG	✓
18	11/04/19 19:38	**General View**		Load JPG	✓
19	11/04/19 19:38	**General View**		Load JPG	✓
20	11/04/19 19:38	**General View**		Load JPG	✓
21	11/04/19 19:38	**General View**		Load JPG	✓
22	11/04/19 19:38	**General View**		Load JPG	✓
23	11/04/19 19:38	**General View**		Load JPG	✓
24	11/04/19 19:38	**General View**		Load JPG	✓
25	11/04/19 19:38	**General View**		Load JPG	✓
26	11/04/19 19:38	**General View**		Load JPG	✓
27	11/04/19 19:38	**General View**		Load JPG	✓
28	11/04/19 19:38	**General View**		Load JPG	✓
29	11/04/19 19:38	**General View**		Load JPG	✓
30	11/04/19 19:38	**General View**		Load JPG	✓
31	11/04/19 19:38	**General View**		Load JPG	✓

Video 1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
32	11/04/19 19:38	**General View**		Load JPG	
33	11/04/19 19:38	**General View**		Load JPG	
34	11/04/19 19:38	**General View**		Load JPG	
35	11/04/19 19:38	**General View**		Load JPG	
36	11/04/19 19:38	**General View**		Load JPG	
37	11/04/19 19:38	**General View**		Load JPG	
38	11/04/19 19:38	**General View**		Load JPG	
39	11/04/19 19:38	**General View**		Load JPG	
40	11/04/19 19:38	**General View**		Load JPG	
41	11/04/19 19:38	**General View**		Load JPG	
42	11/04/19 19:38	**General View**		Load JPG	
43	11/04/19 19:38	**General View**		Load JPG	
44	11/04/19 19:38	**General View**		Load JPG	
45	11/04/19 19:38	**General View**		Load JPG	
46	11/04/19 19:38	**General View**		Load JPG	
47	11/04/19 19:38	**General View**		Load JPG	
48	11/04/19 19:38	**General View**		Load JPG	
49	11/04/19 19:38	**General View**		Load JPG	
50	11/04/19 19:38	**General View**		Load JPG	
51	11/04/19 19:38	**General View**		Load JPG	
52	11/04/19 19:38	**General View**		Load JPG	
53	11/04/19 19:38	**General View**		Load JPG	
54	11/04/19 19:38	**General View**		Load JPG	
55	11/04/19 19:38	**General View**		Load JPG	
56	11/04/19 19:38	**General View**		Load JPG	
57	11/04/19 19:38	**General View**		Load JPG	
58	11/04/19 19:38	**General View**		Load JPG	
59	11/04/19 19:38	**General View**		Load JPG	
60	11/04/19 19:38	**General View**		Load JPG	
61	11/04/19 19:38	**General View**		Load JPG	
62	11/04/19 19:38	**General View**		Load JPG	
63	11/04/19 19:38	**General View**		Load JPG	
64	11/04/19 19:38	**General View**		Load JPG	
65	11/04/19 19:38	**General View**		Load JPG	
66	11/04/19 19:38	**General View**		Load JPG	
67	11/04/19 19:38	**General View**		Load JPG	
68	11/04/19 19:38	**General View**		Load JPG	
69	11/04/19 19:39	**Reinspection Photo**		Load JPG	
70	11/04/19 19:39	**Reinspection Photo**		Load JPG	
71	11/04/19 19:39	**Reinspection Photo**		Load JPG	
72	11/04/19 19:39	**Reinspection Photo**		Load JPG	
73	11/04/19 19:39	**Reinspection Photo**		Load JPG	
74	11/04/19 19:39	**Reinspection Photo**		Load JPG	
75	11/04/19 19:39	**Reinspection Photo**		Load JPG	
76	11/04/19 19:39	**Reinspection Photo**		Load JPG	
77	11/04/19 19:39	**Reinspection Photo**		Load JPG	
78	11/04/19 19:39	**Reinspection Photo**		Load JPG	
79	11/04/19 19:39	**Reinspection Photo**		Load JPG	
80	11/04/19 19:39	**Reinspection Photo**		Load JPG	
81	11/04/19 19:39	**Reinspection Photo**		Load JPG	
82	11/04/19 19:39	**Reinspection Photo**		Load JPG	
83	11/04/19 19:39	**Reinspection Photo**		Load JPG	
84	11/04/19 19:39	**Reinspection Photo**		Load JPG	

Video

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/02/19 18:26	**TP ESTIMATE- MARKED**		Load PDF	
2	26/02/19 18:26	**TP GIA REPORT**		Load PDF	
3	27/02/19 18:25	**Non reporting letter**		Load PDF	
4	30/07/19 16:17	**EMAIL TO OI**		Load PDF	
5	22/08/19 10:30	**EMAILS**		Load PDF	
6	04/10/19 12:13	**EMAIL FROM AIG**		Load PDF	
7	04/10/19 12:14	**EMAIL TO TP REJECT**		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19003506/UHB3S2
Date: 02/12/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700088549		
Claimant Vehicle No :	FBH1551D	**Insured Vehicle No :**	SJX8262M		
Date of Loss:	12/02/2019	Nature of Claim:	TP	Claim No:	7456203433SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**FBH1551D**		
Make & Model:	YAMAHA YBR125, 123cc (M)	Engine No:	E3J2E008393
Reg. Date:	21/03/2013 (Man. Year: 2013)	Chassis No:	LBPKE1785D0009993
Colour:	Red	Odometer:	99014 km
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	90/90-18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	**Repairer's**	**Adjuster's**	**Difference**	**Diff %**
Parts	1,683.00	762.60	920.40	54.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	315.00	235.00	80.00	25.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**1,998.00**	**997.60**	**1,000.40**	**50.07**
Approved Total (Overridden) (S$)		**790.00**		
(S$)	1,998.00	790.00	1,208.00	60.46
+ GST 7.00/7.00% (S$)	139.86	55.30	84.56	60.46
Nett Amount (S$)	**2,137.86**	**845.30**	**1,292.56**	**60.46**

INSPECTION

Date of Assignment:	25/02/2019		
Date Inspected:	25/02/2019	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA **Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET UNDER FORK	Serviceable	180.00 F	*- FL
2	2		*BUSH SWINGARM (METAL)	Not Necessary	10.00 F	*- FL
3	2		*BUSH SWINGARM (RUBBER)	Not Necessary	24.00 F	*- FL
4	2		*CLIP TUBE INNER FORK	Not Necessary	10.00 F	*- FL
5	1		*COVER SIDE LH (BLACK)	Repair	118.00 F	*- FL
6	1		*COVER TAIL LH (RED)	Cut	90.00 F	*90.00 FL
7	1		*COVER TANK SIDE LH (RED)	Cracked	119.00 F	*119.00 FL
8	1		*CRASH BAR	Bent	195.00 F	*195.00 FL
9	1		*FOOTREST FRONT	Torn	80.00 F	*80.00 FL
10	1		*GUIDE AIR LH	Not Necessary	23.00 F	*- FL
11	1		*HANDLE SEAT	Scratched	98.00 F	*98.00 FL
12	1		*LEVER BRAKE	Scratched	19.00 F	*19.00 FL
13	1		*LEVER CLUTCH	Scratched	19.00 F	*19.00 FL
14	1		*MUDGUARD FRONT (RED)	Cut	98.00 F	*98.00 FL
15	1		*OIL FORK (UNICORN) MR-10	Not Necessary	10.00 F	*- FL
16	1		*PROTECTOR MUFFLER (REAR)	Bent	32.00 F	*32.00 FL
17	1		*RUBBER FOOTREST FRONT	Torn	14.00 F	*14.00 FL
18	2		*SEAL OIL (18X24X4) SWINGARM BUSH	Not Necessary	16.00 F	*- FL
19	2		*SEAL OIL (30X41X10) FORK	Not Necessary	48.00 F	*- FL
20	1		*SET STEERING CONE	Not Necessary	68.00 F	*- FL
21	1		*SWING ARM	Not Necessary	138.00 F	*- FL
22	2		*TUBE INNER FORK	Repair	196.00 F	*- FL
23	1		*VISOR	Cracked	30.00 F	*30.00 FL
24	2		*STICKER (MCDONALDS) SIDE COVER / WINDSHEILD	Necessary	32.00 FS	*32.00 FS
25	1		*STICKER (MCDONALDS) WINDSHIELD V2	Necessary	16.00 FS	*16.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S$)	**1,683.00**	**842.00**
- List Item Discount on L Items 0.00/10.00% (S$)	0.00	79.40
Total Parts (S$)	**1,683.00**	**762.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**LABOUR - FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED.**	New	280.00	200.00
2	**TRANSPORT CHARGES - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE.**	New	35.00	35.00
		Gross Labour Cost (S$)	**315.00**	**235.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >