CandyMotor Workshop Pte Ltd (Reg: 201728110D)
25 Kaki Bukit Road 4, #01-83 Synergy @ KB Singapore 417800
Office: 9636 6740

Invoice

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TO: Allianz Malaysia Berhad

Invoice Number: #1253

Date: 30/01/2019

Item No.	Description	QTY	Unit Price (SGD)	
655064	Front Shield / Cut	1	470 ~~406~~	/
654982	Copertura Laterale Superior Escudo sx / Cut	1	233 ~~202~~	/
564983	Copertura Laterale Superior Escudo dx / Cut	1	233 ~~202~~	/
655043	RH Cover / Cut	1	180 ~~156~~	/
655044	LH Cover / Cut	1	180 ~~156~~	/
949436000	Footrest RH / Cut	1	32 ~~27~~	/
949435000	Footrest LH / Cut	1	32 ~~27~~	/
656523 (Bottom)	Spoiler / ~~CT~~ CRA.	1	222 ~~193~~	/
949413	LH Half Rear Fairing / Cut.	1	183 ~~159~~	/
655083 (Top Cover)	Copertura Anteriore Manubrio / Cut.	1	141 ~~122~~	/
6550825 (Handle Bar)	Manubrio Con PI / BT.	1	194 ~~168~~	/
646833	Fr. Br. Lever / Cut.	2	23 ~~20~~	/
58508R (Fork)	Forcella Anteriore Completa / BT.	1	751 ~~653~~	/
639185 (Headlamp)	Indicatore Direzione Anteriore dx / SCR.	1	50 ~~43~~	/
6241125	Top Frame X / Repair	1	X ~~X~~	172
6242885	Body Frame X / Repair.	1	X	1338
847308	Exhaust Pipe Protector / CA.	1	50 ~~43~~	/
	Exhaust Pipe / CRA	1	1177 ~~1070~~	/
	Check Fork	1	120	280
	Check Body 200	1	~~NA/X~~	380
	Labour	1	200.	250
		Total	520	6067

6464

~~2577~~ ~~4644~~ 4451
10%: ~~231.3~~ 263.6
~~2631.7~~ 3735.9
~~2700~~: ~~2100~~
~~4154.6~~
4255.9

3 Days.
Compensation P/P
After repair photos
Guo Qiang – 82880282
14/2/19.

Terms & Conditions:
* Goods & Services Sold are not returnable or exchangeable.
* Please inform us within seven (7) working days of any discrepancies.
* Cheque should be crossed and made payable to CANDYMOTOR WORKSHOP PTE LTD

For Bank Transfer or Cheque Payment:
Bank Name: DBS Bank
Bank Swift Code: DBSSSGSG
Account Number: 003-951714-9

CandyMotor Workshop Pte Ltd (Reg: 201728110D)
25 Kaki Bukit Road 4, #01-83 Synergy @ KB Singapore 417800
Office: 9636 6740

Authorized Signature

Goods Received in Good Condition

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 7686T

Qty	Description of Parts	Condition	Estimate By Workshop ($)	Cost Price ($)	Our Adjusted ($)
	REPLACEMENT OF PARTS				
1	FRONT SHIELD	CUT	470.00	-	470.00
1	COPERTURA LATERALE SUPERIOR ESCUDO SX	CUT	233.00	-	233.00
1	COPERTURA LATERALE SUPERIOR ESCUDO DX	CUT	233.00	-	233.00
1	RH COVER	CUT	180.00	-	180.00
1	LH COVER	CUT	180.00	-	180.00
1	FOOTREST RH	CUT	32.00	-	32.00
1	FOOTREST LH	CUT	32.00	-	32.00
1	SPOILER (BOTTOM)	CRACKED	222.00	-	222.00
1	LH HALF REAR FAIRING	CUT	183.00	-	183.00
1	COPERTURA ANTERIORE MANUBRIO (TOP COVER)	CUT	141.00	-	141.00
1	MANUBRIO CON PI (HANDLE BAR)	BENT	194.00	-	194.00
2	FR. BR. LEVER	CUT	23.00	-	23.00
1	FORCELLA ANTERIORE COMPLETA (FORK)	BENT	751.00	-	751.00
1	INDICATORE DIREZIONE ANTERIORE DA (HEADBIP)	SCRATCHED	50.00	-	50.00
1	TOP FRAME	TO REPAIR SEE LABOUR	172.00	-	-
1	BODY FRAME	TO REPAIR SEE LABOUR	1,338.00	-	-
1	EXHAUST PIPE PROTECTOR	CUT	50.00	-	50.00
1	EXHAUST PIPE	CRACKED	1,177.00	-	1,177.00
	LESS 10% DISCOUNT		-	-	-415.10
			5,661.00	-	3,735.90
	LABOUR				
	CHECK FORK		280.00	-	120.00
	CHECK BODY. INCLUSIVE OF THE REPAIR OF TOP FRAME AND BODY FRAME.		380.00	-	200.00
	LABOUR.		250.00	-	200.00
			910.00	-	520.00
	GRAND TOTAL		**6,571.00**	**-**	**4,255.90**

RECOMMENDED COST OF REPAIRS				**4,255.90**

Report Ref No. CS/TP19003537/Gqd3s2

Report Ref No. CS/TP19003537/Gqd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.