LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805   Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:	CS/TMI19003782/K1SD3E2
Date:	06/03/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MH001493
Claimant Vehicle No :	SHA3085K	**Insured Vehicle No :**	SJS9155J
Date of Loss:	27/02/2019	Nature of Claim:	TP Claim No: M1901218

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SHA3085K**		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDFU500920
Reg. Date:	15/01/2015 (Man. Year: 2014)	Chassis No:	KMHLB41UMFU062701
Colour:	Blue	Odometer:	503292 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Campeon 6 mm	Rear Left Side:	Campeon 6 mm
Front Right Side:	Campeon 6 mm	Rear Right Side:	Campeon 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	696.68	75.00	621.68	89.23
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,480.00	650.00	830.00	56.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S$)	**2,186.68**	**735.00**	**1,451.68**	**66.39**
+ GST 7.00/7.00% (S$)	153.07	51.45	101.62	66.39
Nett Amount (S$)	**2,339.75**	**786.45**	**1,553.30**	**66.39**

INSPECTION

Date of Assignment:	28/02/2019	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/02/2019	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2019)	
Parts: 143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SHA3085K)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***FRONT DOOR MIRROR LH**	Repair	670.00 FL	*- FL
2	1		***FRONT WHEEL HUB CAP LH**	Serviceable	107.10 FL	*- FL
3	1		***FRONT DOOR COMFORT LOGO LH**	Necessary	75.00 FS	*75.00 FS
4	1		***FRONT DOOR (LH) (NPA)**	Repair	-	*- FL
5	1		***FRONT FENDER (LH) (NPA)**	Repair	-	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Repairer's	Amount
Sub Total (S$)	852.10	75.00
- List Item Discount on L Items 20.00/20.00% (S$)	155.42	0.00
Total Parts (S$)	696.68	75.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	**OD/TP Case (Insurer)**	10.00	10.00
		Sub Total (S$)	**10.00**	**10.00**

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**PANEL BEATING**	New	500.00	200.00
2	**SPRAY PAINTING**	New	900.00	450.00
3	**FRT WHEEL ALIGNMENT**	New	80.00	0.00
	Gross Labour Cost (S$)		**1,480.00**	**650.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >