Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

RICO60 AUTO SERVICES

VECHICLE NUM:	SKE 1913 C
MAKE & MODEL:	HONDA CIVIC
MILEAGE:	
TYRE:	
CHASSIS NUM:	

NOP Adel
Hlah
2/5 to 1250
3 day.
11/3/19 Zh, HeAthing

ATTN:

NO.	DESCRIPTION - PARTS			QTY	PRICE	
1	REAR WINDSCREEN MOULDING		11	1	$ 148.60	X
2	REAR BOOTLID		11	1	$ 910.50	X
3	REAR BOOTLID LOGO		11	1	$ 60.70	X
4	REAR BOOTLID LAMP LH+RH		11	1	$ 320.70	X
5	REAR BOOTLID OPENER SWITCH		11	1	$ 113.40	X
6	REAR BOOTLID WEATHERSTRIP		11	1	$ 189.70	X
7	REAR BOOTLID INNER TRIM		11	1	$ 227.30	X
8	TAILLAMP RH	280.40	SCR	1	$ 709.20	/
9	TAILLAMP CLIP RH		11	1	$ 18.00	X
10	TAILLAMP PANEL RH		R	1	$ 384.00	X
11	REAR BUMPER	638	Dc / Repair	1	$ 857.70	/
12	REAR BUMPER BRACKET RH		11	1	$ 45.80	X
13	REAR BUMPER SIDE RETAINER RH	20.10	Bend	1	$ 63.50	/
14	REAR FENDER RH		PR	1	$ 1,167.40	X
15	REAR FENDER INNER TRIM RH		11	1	$ 753.00	X
16	REAR FENDER COWLING RH		11	1	$ 98.30	X
17	END PANEL		R	1	$ 689.00	X
18	END PANEL TOP GARNISH		11	1	$ 262.60	X
19	SPARE WHEEL PANEL		11	1	REPAIR	X
20	SPARE WHEEL PANEL TOP BOARD		11	1	$ 192.50	X
		P- 938.50				
		÷2 = 469.25				
		S.N 40.00	SUBTOTAL		$ 7,063.30	
		labour 770.00	LESS 20%		$ 1,412.66	
		Total $1279.25	PARTS TOTAL		$ 5,650.64	
	SPECIAL NETT			QTY	PRICE	
1	REAR NUMBER PLATE		11	1	$ 100.00	X
2	REVERSE SENSOR		11	2	$ 300.00	X
3	REAR END PANEL SEALANT		11	1	$ 100.00	X
4	REAR BUMPER CLIPS		Nil	10	$ 100.00	40
5	BOOTLID INNER TRIM CLIPS		11	10	$ 100.00	X
6	REAR FENDER INNER TRIM CLIPS		11	10	$ 100.00	X
7	REAR FENDER COWLING CLIPS		11	10	$ 100.00	X
			SPECIAL NETT TOTAL		$ 900.00	
	LABOUR			QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN			1	$ 2,500.00	300
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA			1	$ 1,200.00	400
3	TO RUST PROOF ACCIDENT AFFECTED AREA		11	1	$ 120.00	X
4	TO RNR REAR WINDSCREEN		11	1	$ 300.00	X

5	TO RNR REAR BOOT MECHANISM	11	1	$ 120.00	X
6	TO RNR REAR LUGGAGE COMPARTMENT	11	1	$ 400.00	X
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.		1	$ 120.00	50
8	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION		1	$ 120.00	20
9	TO CHECK WIRING LAYOUT AND TAILGATE LAMP FUNCTION		1	$ 120.00	
10	TO DO WATER LEAK TEST .	11	1	$ 120.00	X
	LABOUR TOTAL			$ 5,120.00	
	GRAND TOTAL COST			$ 11,670.64	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: