CITY CAB PTE LTD

REPAIR ESTIMATE*

AXA-LS

TS 1410

VEHICLE NO : SHC 7949G **DATE 11/3/2019**

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover			$ 544.50	
	Front Bumper Grille (RH)			$ 41.60	
	Front Bumper Bracket Top (RH) ?			$ 22.40	
	Front Bumper Bracket (RH) ?			$ 24.60	
	Headlamp (RH)			$ 1,388.00	
	Frt Wheel Hub Cap,RH			$ 107.10	
	Front RH Fender to repair				
	SUB TOTAL			**$ 2,128.20**	
	LESS 20%			$ 425.64	
	DISCOUNTED TOTAL			**$ 1,702.56**	
	Front Fender Advertisement Logo (RH)			$ 100.00	**Nett**
				$ 100.00	
	Labour Charge				
	Panel Beating			$ ~~400.00~~ 300	
	Spray Painting Charge			$ ~~600.00~~ 400	
	Tuff Kote			$ ~~50.00~~	
	Frt Wheel Alignment			$ ~~80.00~~	
	TOTAL LABOUR			**$ 1,130.00**	
	ESTIMATE TOTAL			**$ 2,932.56**	

Acknowledged by Repairer
Signature:
Date:

Kalirulla
11/3/19 1510 hrs.
2 Days
L/S
After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.