Assignor: Rosa | REF: NS/ INC19004694/Rlvd3,2

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

of:

Insured: SMH 9112S

Policy No: 5101430616 (22/6/18-21/6/19)

Claim No: MT/1035251-002

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

GA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHB 52882 Yr Regn: 2014 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Car / Prime Mover / Truck / Trailer or

Make: TOYOTA PRIUS C.C. 1798

Colour: MAROON A/C: Insured / Std / Nil / NA

Sp Reading: 495377 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: JTDKN36U305721308

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FALKEN

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	02/03/19	D.O.I.	12/03/19

Survey held at: SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHB 5282Z - NS/INC/17022776/Svbe2 DOA: 28/11/17 03/19/2020
	SMA 9112S -
6/5/19	LS $1500 (Rec 3683.38, 67%) confirmed by email

NTUC

SMA 9112S

6/5/19

RECEIVED 07 MAY 2019

Date/time, File Pass to? D: Date/Time, File Return to? D: 6/5 - typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. (1$) ☐ Interview (1$) ☐ Tech. Insp. (1$) ☐ Weekend (1$)

Survey Fee: Transportation: Photo: Other: GST:

Report Format: TP

Lump Sum / I.B.I. (1$): 1500/2

Veron Chen (LKKAuto)

From: MTCL@income.com.sg
Sent: Monday, 6 May 2019 2:25 PM
To: Veron Chen (LKKAuto)
Subject: FW: REQUEST FOR CLAIM NUMBER

Dear Veron

Claim created.
You may refer to the claim no below:-

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No
1	MT/1035251-002	SMRT TAXIS PTE LTD	SHB 5288Z	SMA 9112S

D.O.A	Time of Accident	Estimate	Tentative repair cost
9/3/2019	10:30	$5,483.38	$1,500.00

Josephine Cheah
Snr Administrator, Motor Insurance
www.income.com.sg

income made different

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Monday, 6 May 2019 10:18 AM
To: MTCL@income.com.sg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No
1		SMRT TAXIS PTE LTD	SHB 5288Z	SMA 9112S

D.O.A	Time of Accident	Estimate	Tentative repair cost
9/3/2019	10:30	$5,483.38	$1,500.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

Change Language | Change Password | Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.

Date of Accident 09/03/2019 08:03

Vehicle No.(For Motor) SMA9112S

Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	5101430616		CHEONG MUN CHOY, SUNNY (ZHANG MINCAI, SUNNY)	S7933654H	GPC	drivo PREMIUM	SMA9112S	SMA9112S	22/06/2018	21/06/2019

Continue

Veron Chen (LKKAuto)

From: Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis) <weisiong@smrt.com.sg>
Sent: Saturday, 4 May 2019 9:43 AM
To: Rasul (LKKAuto)
Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: RE: SHB5288Z
Attachments: 2040 - 5288.pdf

Hi Rasul,

Please find attached GIA report.

Regards,
Alex Lim Wei Siong
SMRT Automotive Services PTE LTD
Accident Reporting Center (Claims Dept)
6866 2682 | weisiong@smrt.com.sg
www.smrt.com.sg

-----Original Message-----
From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: 02/05/2019 16:30
To: Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Cc: Rasul (LKKAuto)
Subject: FW: SHB5288Z

Hi Alex,

Can you please help to forward the GIA report to Rasul?

Thanks & Regards
Poh Suan

-----Original Message-----
From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Thursday, 2 May 2019 3:17 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Cc: Veron Chen (LKKAuto)
Subject: RE: SHB5288Z

Hi Poh Suan,

I'm requesting Zhi Yang to forward to me the GIA report. Until now he haven't forward to me.
Could you kindly assist me to forward to me the GIA report

Best Regards,

Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----
From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Saturday, 27 April, 2019 10:37 AM
To: Rasul (LKKAuto)
Cc: SUR; CS A Team; 'Leong Chee kwong'; 'EE SIN GUAN'
Subject: SHB5288Z

Hi Rasul,

Attached herewith the repair estimate of SHB 5288Z having Case No: TAX/03/19/2040.

There is no change to the approved amount of $1,500 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----
From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Saturday, 27 April 2019 10:39 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: Scan Data from FX-D421D6

MSR119031805 / SMRT Automotive Services Pte Ltd - Woodlands
ENTRY DATE & TIME: 09/03/2019 12:13
SUBMITTED BY: B. Thaiyal Nayagi

Your NCD will be affected due to late reporting
Actual e-Filling Submission Date & Time: 12/03/2019 08:41

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/03/2019 12:13
Date Of Accident	09/03/2019 10:30
Exact Location Of Accident	WOODLANDS AVE 5
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHB5288Z
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	
Driver	
Name of Driver	YAM AH YENG
NRIC No	S0909684A
Date Of Birth	31/05/1949
Occupation	OUTDOOR
Date Of Driving Pass	20/05/1985
Driving Experience	33 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	4
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG WOODLANDS AVE 5 WITH 3 PASSENGERS (MALAY FEMALE) ON BOARD. SUDDENLY A VEHICLE SMA9112S WHICH WAS ON MY RIGHT CUT TOWARDS MY LANE ABRUPTLY AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA9112S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEONG MUN CHOY SUNNY

NRIC/Passport Number	S7933654H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the **"Personal Information"**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **"Insurers"**), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the **"Purposes"**)

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 9/3/2019	Reporting Centre Personnel's Signature Name: NRIC/FIN No.: 9/3/2019

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 9/3/2019	Reporting Centre Personnel's Signature Name: NRIC/FIN No.: 9/3/2019

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SHB5288Z
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1 :	Air-Con (Taxi)
Vehicle Scheme :	Taxi (Company)
Vehicle Make :	TOYOTA
Vehicle Model :	PRIUS TAXI (SMRT)
Chassis No. :	JTDKN36U305721308
Propellant :	Petrol-Electric
Engine No. :	2ZR6088635
Motor No. :	3JM5937067
Engine Capacity :	1798 cc
Power Rating :	60.0 kW
Maximum Power Output :	100.0 kW (134 bhp)
Maximum Laden Weight :	1805 kg
Unladen Weight :	1370 kg
Year Of Manufacture :	2013
Original Registration Date :	05 Mar 2014
Lifespan Expiry Date :	04 Mar 2022
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid :	$58,745.00
COE Expiry Date :	04 Mar 2022
Road Tax Expiry Date :	22 Jun 2019
PARF Eligibility Expiry Date :	04 Mar 2022
Inspection Due Date :	22 Jun 2019
Intended Transfer Date :	13 May 2019
CO2 Emission :	92.00 (g/km)
CEV/VES Rebate Utilised Amount :	$30,000.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 22 Jun 2019. You may renew the road tax from 23 Mar 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 22 Jun 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 23 Jun 2019 to 22 Dec 2019)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	510.00	-	510.00
Total Amount Payable :			**535.00**

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

From 18 Feb 2019, the Government has further reduced the annual special tax by $100 and $850 for diesel and diesel-hybrid cars and taxis respectively. The Government will also grant road tax rebates for diesel and diesel-hybrid buses and goods vehicles for a 3-year period from 1 Aug 2019. The current enquiry result does not include the revised special tax reduction and road tax rebate commencing 1 Aug 2019. Please refer to the Press Release for more information.

You may print this page for reference.

OK Print

Accident Photo

Accident Photo

Accident Photo

Accident Photo

SMRT AUTOMOTIVE

Case Details

Case Reference Number : TAX/03/19/2040
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5288Z

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-6043-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
Accident Date and Time : 09/03/2019 02:30 AM
Vehicle Age(In Months) : 60

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

				SMRT Recommendation								Surveyor Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit($)	List Price($)	Dis(%)	Final Price($)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price($)	Repair/Re
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	670.8	Replace
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace
One Time Key In	Main			DOOR LOCK FRT/RH	1	575.80	575.80	25.00	431.85	Replace	0	0	Not Giv
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair
One Time Key In	Main			DOOR HINGE UPPER RR/RH	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Giv

Total Spare Part Cost	2,410.88	Surveyor Total	790.80
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	1,744.09	Final Sur Total	632.64

				SMRT Recommendation								Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit($)	List Price($)	Dis(%)	Final Price($)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price($)	Repair/Rep
One Time Key In	Main			DOOR HINGE LOWER RR/RH	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Giv
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Giv
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace
One Time Key In	Main			PILLAR, CTR BODY	1	307.70	307.70	25.00	230.77	Replace	0	0	Not Giv

Total Spare Part Cost	2,410.88	Surveyor Total	790.80
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	1,744.09	Final Sur Total	632.64

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation($)	Surveyor Adjustment($)	Remarks
1	Main	TO REPAIR RH PORTION	676.00	300	
Total:			676.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation($)	Surveyor Adjustment($)	Remarks
1	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
2	Main	TO RESPRAY REAR DOOR RH	378.00	200	
3	Main	TO RESPRAY CENTER PILLAR RH	180.00	0	
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation($)	Surveyor Adjustment($)	Remarks
1	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	NECESSARY
2	Main	TO TRANSFER DOOR MECHANISM	240.00	60	
3	Main	TO WASH AND VACUUM	60.00	0	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			**696.88**	**356.88**	

Summary

	Estimator Assesment($)	Surveyor Assesment($)
Total Spare Part Detail	1,744.09	632.64
Total Labour Cost	676.00	300.00
Total Spray Painting	936.00	400.00
Other	696.88	356.88
Overall Total	4,052.97	1,689.52
Lump Sum Repair Option		✔
Lump Sum Total	0.00	1,700.00
Surveyor Approved Amount		1,700.00
No of Repair Days*	5	4
Remarks	-	RESURVEY AFTER REPAIR / LUMP SUM
Surveyor Name		Rasul

	Estimator Assesment($)	Surveyor Assesment($)
Signature		Rasul

Save Clear

Survey Date 11/03/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757706
FAX Number : 63685592
Estimator Telephone Number : 68862623
Accident Reporting Number : 68862672

Date Generated : 27/04/2019
User ID : PohSuan

Section A - Accident Details

Registration Number	SHB5288Z
Case Reference Number	TAX/03/19/2040
Registration Date	5/3/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YAM AH YENG
Type of Accident	Side Swipe
Accident Date and Time	9/3/2019 10:30 AM
Accident Reported Date and Time	9/3/2019 12:07 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100517
Special Instruction to ARC,If any	TP
Prepared Date and Time	11/3/2019 4:42 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	$676.00	$300.00
Total Spray Cost	$936.00	$400.00
Total Spare Part Cost	$2,410.88	$790.80
Total Other Cost	$696.88	$9.20
TOTAL COST	$4,719.76 5483.38	$1,500.00 (L/S)
Lump Sum Total	$0.00	$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Kim Ming Chin	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	11/03/2019 5:35 PM	11/03/2019 5:25 PM
Signature		Rasul
Remarks		RESURVEY AFTER REPAIR / LUMP SUM

SMRT AUTOMOTIVE

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63585582
Estimator Telephone Number 68992623
Accident Reporting Number 63663672

Date Generated : 27/04/2019
User ID : PehSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0383	Invoice Number	
Quotation Date	27.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	$676.00	$300.00
Total Labour	$676.00	$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	$378.00	$200.00
TO RESPRAY REAR DOOR RH	$378.00	$200.00
TO RESPRAY CENTER PILLAR RH	$180.00	$0.00 X nn
Total Spray Painting & Panel Beating	$936.00	$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
~~TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT~~ STICKER(NET)	$296.88 SN nec	$296.88
TO TRANSFER DOOR MECHANISM	$240.00	$60.00
TO WASH AND VACUUM	$60.00	$0.00 X nn
TO REPLACE SUNDRY PARTS	$100.00	$0.00 X nn
Lump Sum Adjustment by Surveyor	$0.00	($347.68)
Total Other Costs	$696.88	$9.20

790.80
+ 300.00
+ 756.88
1847.68
- 20%
1478.14
4s $1500/-

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price ($)	Discount (%)	Final Price ($)	Estimator Approved	Surveyor Approved
		67001-47070	DOOR FRT/RH	1.00	$894.40	25.00	$670.80	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	$60.00	0.00	$60.00	Replace	Replace nc
		69030-47070	DOOR LOCK FRT/RH	0.00	$575.80	0.00	$0.00	Replace	Not Given X nc
		67003-47080	DOOR RR/RH	1.00	$954.50	100.00	$0.00	Replace	Repair
		68730-12120	DOOR HINGE UPPER RR/RH	0.00	$81.70	0.00	$0.00	Replace	Not Given X
		68740-12120	DOOR HINGE LOWER RR/RH	0.00	$90.10	0.00	$0.00	Replace	Not Given X
		68630-47031	CHECK ASSY, RR DOOR,	0.00	$150.30	0.00	$0.00	Replace	Not Given X
			PIXEL STICKER	1.00	$60.00	0.00	$60.00	Replace	Replace nc
		61311-47030	PILLAR, CTR BODY	0.00	$307.70	0.00	$0.00	Replace	Not Given X nn
Total					$3,174.50		$790.80		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price $	Discount (%)	Final Price ($)	ARC Check	Surveyor Check
Total									

5483.38

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 6 May 2019 4:52 PM
To: Rasul (LKKAuto); Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Cc: SUR
Subject: RE: SHB5288Z-DOA: 9/3/2019

Dear Poh Suan,

WITHOUT PREJUDICE

Amount $1,500 confirmed @ 4 working days under lump sum repair.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----
From: Rasul (LKKAuto)
Sent: Thursday, 2 May 2019 3:17 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SHB5288Z

Hi Poh Suan,

I'm requesting Zhi Yang to forward to me the GIA report. Until now he haven't forward to me.
Could you kindly assist me to forward to me the GIA report

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----
From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Saturday, 27 April, 2019 10:37 AM
To: Rasul (LKKAuto)
Cc: SUR; CS A Team; 'Leong Chee kwong'; 'EE SIN GUAN'
Subject: SHB5288Z

Hi Rasul,

Attached herewith the repair estimate of SHB 5288Z having Case No: TAX/03/19/2040.

There is no change to the approved amount of $1,500 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----
From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Saturday, 27 April 2019 10:39 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: Scan Data from FX-D421D6

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6841 0055 FAX: 6841 6315
Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTUC INCOME INSURANCE CO-OPERATIVE LTD

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: NS/INC19004694/R1vd3s2

Date: 13-05-2019

Code: INC4

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SMA 9112S	**Veh. Inspected**	SHB 5288Z
	Policy No.	5101430616	**Coverage ($)**	0.00
	Claim No.	MT/1035251-002	**Excess ($)**	0.00
	Assign From		**Assign Date**	11/03/2019

2.	Vehicle Particulars & Condition			
	Make & Model	TOYOTA PRIUS	**c.c**	1798
	Engine No.	HIDDEN	**Year of Reg.**	2014
	Chassis No.	JTDKN36U305721308	**Colour**	MAROON
	Odometer	495377	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	FAIR		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	195/65R15	FALKEN	5 mm
	L/H Front Tyre	195/65R15	FALKEN	5 mm
	R/H Rear Tyre	195/65R15	FALKEN	5 mm
	L/H Rear Tyre	195/65R15	FALKEN	5 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	09/03/2019	**Inspection Date**	11/03/2019
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**4 Working Days**

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5288Z

Qty	Description of Parts	Condition	Estimate By Workshop ($)	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	DOOR FRT/RH (DISC 25%)	BENT	894.40	670.80
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	DOOR LOCK FRT/RH	SERVICEABLE	575.80	-
1	DOOR HINGE UPPER RR/RH	SERVICEABLE	81.70	-
1	DOOR HINGE LOWER RR/RH	SERVICEABLE	90.10	-
1	CHECK ASSY, RR DOOR,	SERVICEABLE	150.30	-
1	PILLAR, CTR BODY	NOT NECESSARY	307.70	-
1	DOOR RR/RH	TO REPAIR SEE LABOUR	954.50	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
			3,471.38	1,087.68
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF DOOR RR/RH.		676.00	300.00
	SPRAY PAINT.		936.00	400.00
	TO TRANSFER DOOR MECHANISM.		240.00	60.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			2,012.00	760.00
	GRAND TOTAL		**5,483.38**	**1,847.68**

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			**1,500.00**

Report Ref No. NS/INC19004694/R1vd3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.