HAN MOTOR REPAIR
ROC: 46643000X
BLK 1 SIN MING INDUSTRIAL SECTOR C
#01-121 Singapore 575636
Email: eshcorporate@gmail.com
TEL: 6458 3097 HP: 90998568

		(AIG)	Date: 26/03/2019	
	Our Ref: GBC5393T			
	Ericool Aircon & Engineering Pte Ltd			
	C/O: Han Motor Repair			
	Estimaste cost of repair for Citrogen Dispatch GBC5393T			
			TOTAL	
1PC	REAR BUMPER FASCIA	$ 950.00	$ 950.00	✓
1PC	REAR RH REFLECTOR	$ 65.00	$ 65.00	?
1PC	REAR BUMPER REINFORCEMENT	$ 520.00	$ 520.00	?
	TOTAL SPARE PARTS		$ 1,535.00	
	LESS : 10% **(1,535*0.1)**		$ (153.50)	
				$ 1,381.50
1 SET	REAR REVERSE SENSOR			SN $300.00 ?
				$ 1,681.50
	LABOUR			
	TO SPRAY AFFECTED AREA		200l	$ 400.00
	TO REMOVE & RENEW REAR BUMPER AND PANEL BEATING AFFECTED AREA		300l	$ 600.00
				$ 2,681.50

Not without Resurvey After Paint
2 days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: