Surveyor: Tanfm | REF: EQI

ASSIGNMENT

From: Date: 10.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YM 4179 C

at Workshop m/s Mova Automotive

of 15 Fan yong Road

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: (one After (10.00 am)

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 9/6K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "wp"

Vehicle: IN / OUT

Date: Person Contacted:

COE 2021 June

Veh No: YM 4179C. Yr Regn: 2006 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mitsubishi FE83 c.c 3908

Colour white A/C: Insured / Std / NI / NA

Sp.Reading 442080 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FE83PFA01227.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7.00-16

R: " " (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front			Rear		
R/Bal.	8	mm	R/Bal.	8/8	mm
L/Bal.	8	mm	L/Bal.	8/8	mm
D.O.A.			D.O.I.	10/4/19 @ 230pm	

Survey held at Mova Fan Yong

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

: Company Reg 4624R Rebate $992

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: S + RS, SI

Photos

Others

TOTAL