N/SISM

Not Authorised

Resurvey B4 paint

Ex $500

RC AUTO

Blk 18, Sin Ming Industrial Estate Sector A #01-43, Singapore 575676
Tel : 6458 8878 Fax : 6458 2246
Reg. No. 53199168K

MSIG INSURANCE (SINGAPORE)PTE LTD Date : 4/4/2019

POLICY NUMBER:D300104384

TYPE OF CLAIM:OWN DAMAGE CLAIM

Quantity	Description/Particular	Unit Price	Amount		
	FRONT HEADLAMP	Not in	3210	00	
	FRONT BUMPER		Bu 1550	00	
	FRONT FENDER		Bu 905	00	
	FRONT SENSOR		342	00	?
	SPORTS RIM		Not 1150	00	
	FRONT HEADLAMP SUPPORT		70	00	?
		TOTAL$	7227	00	
		LESS10%	6504.3	00	
	SPRAY PAINTING		500	00	450
	LABOUR TO RENEW ABOVE PARTS		400	00	360
	WHEEL ALIGNMENT		60	00	
	TO CHECK WIRING		50	00	20
	GRAND TOTAL	$	7514	30	

Received the above goods in good order and condition

for RC AUTO

RC AUTO
160, Sin Ming Drive
#06-20 Sin Ming AutoCity
Singapore 575722
HP: 9761 9383
Email: rcauto5555@gmail.com

Authorised Signature

Received by

E.&.O.E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: