GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
GREEN FOREST LANDSCAPE PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TPAIG.
Vic

09th APRIL 2019

Accident date: 08th APRIL 2019
Estimated repair cost for vehicle no: SMG5742T TOYOTA AXIO 1.5X A '09

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet		$980.20
2	1	Front headlamp -LH		$681.80
3	1	Front support panel side cover		$161.10
4	1	Front bumper Distorted		$480.75
5	2	Front Bumper Side Bracket LH Dmgd	$161.10	~~$322.20~~
6	8	Front bumper clips	$12.90	~~$103.20~~
7	1	Front Grille		$381.40
8	1	Front Grille emble logo		$61.00
9	4	Front Grille clips	$12.90	$51.60
10	1	Front bumper inner sponge		$182.80
11	1	Front L/H fender Repair		$591.40
12	1	Front L/H fender inner shiled Detached		$182.25
13	1	Front L/H fender inner shiled clips		~~$50.00~~
14	1	Front L/H rim		~~$450.00~~
15	1	front L/H tyre		$300.00

Subtotal :-	$4,979.70

1442.80
1082.10
S.N: 400

Labour charges

To remove & re-fix front windscreen	$100.00 ✓
Gum	$50.00 ✓
To Check Wiring System	~~$6.00~~ 30
Tuff kote	$120.00 ✓
Panel beating	~~$800.00~~ 300
Spray painting	~~$800.00~~ 400
	730
Subtotal :-	**$1,876.00**
Total:-	**$6,855.70**

total : 2212.10
2/s : 1750
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: