Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5372C

AAD1904-088

Not Authorised

Resurvey B4 paint

Vehicle No.:	**SHD 5372C**
Chassis No.:	JTDKB3FUX03079139
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS
Date of Accident :	9.4.2019
Third Party Insurer :	**III**
Date of Registration :	17/1/2019

	PART		**LIST**
1	1 REAR BUMPER	$	Bn 458.60 ✓
2	1 REAR BUMPER RE-INFORCEMENT	$	Bn 318.80 ✓
3	1 REAR BUMPER TOWING COVER	$	Nil 14.70 ✓
4	1 REAR BUMPER UNDER COVER (BLACK)	$	Sn 552.60 ✗
5	1 REAR BUMPER SIDE RETAINER LH	$	Sn 112.70 ✗
6	1 REAR BUMPER SIDE RETAINER RH	$	Sn 112.70 ✗
7	1 REAR TAILGATE	$	Bn 1,547.27 ✓
8	1 REAR TAILGATE OUTER GARNISH	$	Nil/Cn 905.10 ✓
9	1 COVER, REAR COMBINATION LAMP, RH	$	Sn 54.70 ✗
10	1 COVER, REAR COMBINATION LAMP, RH	$	Sn 54.70 ✗
11	1 GARNISH, BACK DOOR SIDE, LH	$	Sn 93.60 ✗
12	1 GARNISH, BACK DOOR SIDE, RH	$	Sn 93.60 ✗
13	1 BOARD ASSY, BACK DOOR TRIM	$	Sn 254.40 ✗
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	$	Sn 51.20 ✗
15	1 REAR TAILGATE WEATHERSTRIP	$	Sn 365.20 ✗
16	1 REAR END PANEL	$	Bn 602.10 ✓
17	1 TAILLAMP LOWER RH	$	Sn 548.40 ✗
18	1 TAILLAMP UPPER RH	$	Sn 557.90 ✗
19	1 REAR BUMPER SIDE RH	$	Mbem 232.00 ✓
20	1 REAR BUMPER SIDE LH	$	Sn 232.00 ✗
21	1 TAILLAMP LOWER LH	$	Sn 548.40 ✗
22	1 TAILLAMP UPPER LH	$	Sn 557.90 ✗
23	1 PAN, REAR FLOOR	$	R 572.10 ✗
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	$	R 77.00 ✗
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	$	R 192.90 ✗
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	$	R 77.00 ✗
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	$	R 192.90 ✗
28	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	$	R 290.50 ✗

Trans-cab Auto Services Pte Ltd **AAD1904-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5372C

29	1 REAR FENDER LH		$	817.50	X
30	1 REAR FENDER RH		$	817.50	X
			$	**11,305.97**	
		25%	**$**	**2,826.49**	
			$	**8,479.48**	

Specical Nett

1	1SET PARKING AID		$	700.00	250sn
2	1SET REAR BUMPER CLIP		$	22.00	—
3	2 REAR WINDSCREEN SELANT		$	80.00	40sn
4	1 WINDSCREEN MOULDING		$	100.00	—
5	1 REAR WINDSCREEN INNER SPONGE SEAL		$	100.00	30sn
6	1 REAR TAILGATE TOYOTA LOGO		$	47.00	—
7	1 REAR TAILGATE WORDING 'PRIUS'		$	52.90	—
8	1 REAR TAILGATE WORDING 'HYBRID'		$	53.50	—
9	1 REAR TAILGATE STICKER 'TRANS-CAB'		$	80.00	30sn
10	1 REAR TAILGATE STICKER '6555-3333'		$	80.00	30sn
11	1 REAR BUMPER PROTECTOR		$	100.00	X
		TOTAL	**$**	**1,415.40**	
		TOTAL PARTS	**$**	**9,894.88**	

LABOUR

Putty And Spray Painting Of The Affected Portion.	$	4,200.00	760l ~~660l~~
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	$	4,200.00	600l
To Rust-Proofing Of The Affected Areas.	$	170.00	~~60~~ 30l
To reinstall rear bumper parking sensor.	$	170.00	50l

Trans-cab Auto Services Pte Ltd **AAD1904-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5372C

To transfer of Tailgate fittings, attachments and perform water seepage test.	$		170.00	60/
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	$	nn	170.00	X
To repair and realign rear exhaust pipe.	$	nn	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	$		170.00	60/
To transfer of rear windscreen fittings and conduct water seepage test.	$		170.00	120/
To check steering geometry and computer wheel alignment	$	nn	220.00	X
To transfer of Rear fender fittings, attachments and perform water seepage test.	$	nn	170.00	X
TOTAL	**$**		**10,150.00**	
Over All Total	**$**		**28,524.36**	

(PART-BY-PART) Repair Days ~~20~~ **DAYS**

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: