COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4302L **DATE 15/4/2019 9:54**

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			$ 538.80
	Front Bumper Bracket Top (LH)			$ 22.40
	Headlamp (LH)			$ 797.90
	Front Fender (LH)			$ 593.00
	Front Fender Shield (LH)			$ 86.00
	Front Fender Signal Lamp (LH)			$ 45.40
	Front Fender Retainer			$ 9.20
	Front Door (LH)			$ 1,345.00
	Front Door Protector (LH)			$ 74.90
	Front Wheel Hub Cap (LH)			$ 145.00
	SUB TOTAL			**$ 3,657.60**
	LESS 20%			$ 731.52
	DISCOUNTED TOTAL			**$ 2,926.08**
	Front Door Comfort Logo (LH)			**$ 75.00** Nett
	Labour Charge			
	Panel Beating			$ ~~800.00~~ 400
	Spray Painting Charge			$ ~~900.00~~ 600
	Wiring Charge			$ ~~30.00~~ X
	Tuff Kote			$ ~~50.00~~ 2
	FRT Wheel Alignment			$ ~~120.00~~ X
	TOTAL LABOUR			**$ 1,900.00**
	ESTIMATE TOTAL			**$ 4,901.08**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "[illegible]" basis
- No illegal modification
- Supplementary [illegible] is subject to [illegible]

Acknowledged by: [illegible]
Signature:
Date:

Kah Hin 1CC14

15/4/19 1400hrs

3 Pgs.

L/s

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.