Surveyor QQ. | REF: AIG | 8309D

ASSIGNMENT

From: | Date: 7.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKJ 1883D

at Workshop m/s Volkswagen

of 1 Kampong Ampat

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: 4 pm (waiting) Edmund

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: $49k.

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "up"

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SKJ1883D | Yr Regn: 27 Feb 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or A7 1.4

Make: Volkswagen Golf c.c 1395

Colour white | A/C: Insured / Std / NI / NA

Sp.Reading 178281 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZAUZDW050156

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/35 R19 | R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	07-05-19

Survey held at w/s 4pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	repair limit $5000.

Date/Time, File Pass to? 1) | ☐ : Preli. Report | ☐ : Final Report

Date/Time, File Return to? 2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL