COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC8267J **DATE 13/05/2019 13:42**

MAKE :

MODEL : HYUNDAI i40 **3P - LONPAC** FAUZY

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper Xrepair			$ 553.00	
	Rear Bumper Clip 10 pcs x			$ 22.00	
	SUB TOTAL			**$ 575.00**	
	LESS 20%			$ 115.00	
	DISCOUNTED TOTAL			**$ 460.00**	
				$ 30.00	**Nett**
	Rear Bumper Rubber Mat x			$ 50.00	**Nett**
	Rear Bumper Reverse Sensor x			$ 135.70	**Nett**
				$ 215.70	
	Labour Charge				
	Panel Beating			$ ~~300.00~~ 200	
	Spray Painting Charge			$ ~~300.00~~ 200	
	Wiring Charge			$ ~~30.00~~ x	
	Remove/Refix Reverse Sensor			$ ~~80.00~~ x	
	TOTAL LABOUR			**$ 710.00**	
	ESTIMATE TOTAL			**$ 1,385.70**	

Kahi 1000
13/5/19 1300h
2 hrs.
4 hrs.
After Repair pls

Acknowledgement
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.