COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

4/Sum

AXA

VEHICLE NO : SHD 4183M **DATE 13/5/2019 11:09**

Like

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille			$ 282.10	
	Radiator Grille U Moulding			$ 108.90	
	Front Bumper Cover			$ 538.80	
	Front Bumper Bracket Top (LH)			$ 22.40	
	Front Bumper Bracket (LH)			$ 20.10	
	SUB TOTAL			**$ 972.30**	
	LESS 20%			$ 194.46	
	DISCOUNTED TOTAL			**$ 777.84**	
	Front Number Plate			$ 25.00	**Nett**
	Front No Plate Trim Cover			$ 30.00	**Nett**
				$ 55.00	
	Labour Charge				
	Panel Beating			$ ~~400.00~~ 300	
	Spray Painting Charge			$ ~~300.00~~ ~~500~~ 400	
	TOTAL LABOUR			**$ 700.00**	
	ESTIMATE TOTAL			**$ 1,532.84**	

Kalvin 1111(K)

13/5/19 1415h.

2 Bgs

4/5

After Repair photo

Acknowledged by repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.