pass Go tomorrow.

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SLU430P
Chassis No:
Engine No:

Date : 03.06.2019

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Scuderia Bumper / CRA	Damaged	$12,900.00	$11,610.00
2	1	Front Bumper Bracket X	Necessary	$ 2,190.00	$ 1,971.00
3	1	Front Right Radiator Fan X	Cracked	$ 3,650.00	$ 3,285.00
4	1	Front Right Radiator Housing X	Cracked	$ 750.00	$ 675.00
5	1	Front Sensor Set X	Faulty	$ 990.00	$ 891.00
				$20,480.00	$18,432.00

12K

10% . 10800

Total (Parts): **$20,480.00** Less 10% **$18,432.00**

Labour Charges

6	To fix & dismantle and remove damaged parts and affected Front Left affected damaged portion.	$ 800.00	$ 640.00 20 e
7	To apply anti rust coat and afftected areas	$ -	$ -
8	To check wiring	$ -	$ -
9	Welding and cutting of affected panels, including chassis alighment.	$ 1,200.00	$ 960.00 300
10	Spray painting for Front Left affected parts.	$ 100.00	$ 80.00 X
11	To apply waterproofing sealer on end panels	$ 120.00	$ 96.00 X
12	Diagnose ECU system and reset error code.		

Total Labour: **$ 2,220.00** Less 20% **$ 1,776.00**

Total cost of repairs (Total cost of parts + Total Labour Cost) **$22,700.00** **$20,208.00**

LUMPSUM LESS 20% $ 16,166.40

11300

20% : 9000