22/03/2010

ASS. REC. BY: | REF: CS/FCI/9608692/KL/vd3n2 | Special Instruction:

Surveyor: Kalvin CWS

ASSIGNMENT (Office)

From (Person): Karen Tan of FCI Date/Time: 12.03pm 0/6/5/19

Estimated Cost: Bill to:

OD / ~~TP~~ / ~~WS~~ / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1038U Insured: SH 8346H

at Workshop m/s Premier Automotive Tel: 6214 8880

of 23 Changi South Ave 2 #03-02

Policy No: Claim No: D19UD3249MPSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 14/5/2019

CA / REV / REP. / REV 24 HRS (up)

Date/Time: 12.11pm 16/5/19 Person Contacted: Mr. Liew H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction Estimate ✓
	SHD 1038U - CS/FCI/8014872/KL/vbn2 DOA: 14/8/2018
	SH 8346H - CS/FCI/2002950/KL/vr2 DOA: 8/2/2012
17/5/19	Email preli revised to FCI

Insurer: Kelvin | REF:

From: | Date:

Estimated Cost:

OD / TP INS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: | Person Contacted: | Vehicle: IN / OUT

Veh'No: SHJ 1038H | Yr Regn: 22 Dec 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/T / Prime Mover / Truck / Trailer or

Make: KIA Optima | c.c: 1685

Colour: Silver | A/C: Ins / Std / NI / NA

Sp.Reading: 455174 | T/Radio: Ins / Std / NI / NA

Eng/No:

C/No: KNAGM413MF565 7928

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inop / Jammed / Leaked / Burnt or

Brake: Inop / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Rim or

Tyre Size: F: 205/65 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Achilles

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	18/5/19	D.O.I.	16/5/19

Survey held at Prenser

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or n/s Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
22/5/19	Estimate 4/S $900/ 2dr. (Rec 4748.20, 84%) FCI

RECEIVED 22 MAY 2019

Date/Time, File Pass to? | : Prell. Report | : Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: : Site Insp ($) : Interview ($) : Tech. Insp ($) : Assistance ($)

Survey Fee:	140
Transportation:	50
S + R/S SI	50
Photos	22
Others	
TOTAL	262

2) 22/5 - typist

CWS

4/S $900/2

LVV Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19003249MFSH

Our ref: CS/FCI19008692/K1vd3

DATE: 17/5/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1038U

We thank you for your instruction on 16/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/5/2019 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S$5,648.20
Revised Estimate Amount	:S$1,203.30
"Check" Items Amount	: S$
Book Value	: S$
LTA Reimbursement Value	: S$
Nett Value	: S$

Description of Damage:
The vehicle sustained damages at the n/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kalvin Ang
Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

MS FirstCapital

MS First Capital Insurance Limited Co.Reg. No. 199000106C GST Reg. No. M2-0001676-9
6 Raffles Quay #21-00 Singapore 048580
Tel: (65) 6222 2311 Fax: (65) 6222 3547
Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877
Tel: (65) 6507 3848 Fax: (65) 6507 3849
www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date	15-05-2019	**Our Ref No.**	D19003249MFSH
Accident Date	14-05-2019	**Claim Type.**	Third Party
Insured Vehicle	SH8346H	**Third Party Vehicle.**	SHD1038U
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02		
Contact Person.	LIEW HAI LEONG		
Contact No.	62148880/ 65446689	**Fax No.**	62141511
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	**Fax No.**	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	**Attention.**	NIL
Cc : TP Solicitor	NA	**TP Solicitor Fax No.**	NA
Officer Incharge	KARENT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 17 May 2019 11:50 AM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003249MFSH/1, SHD 1038U
Attachments: SHD 1038U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 1038U
Date of survey: 16/5/2019
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 16 May 2019 1:08 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003249MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha| Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 16 May 2019 12:03 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003249MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:	22 Dec 2015 / 09:09:12	Receipt No.:	AACCK001-AX239-151222-000014
Asset Type:	Vehicle	Transaction Amount:	$68,909.00
Asset ID:	SHD1038U	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151222090912509742		

Vehicle No.:	SHD1038U
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	22 Dec 2015
Original Registration Date:	22 Dec 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5657928
Engine No.:	D4FDFH314500
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	$22,359.00
Minimum PARF Benefit:	$13,981.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	22 Dec 2015 09:09:12
COE No.:	2015122201003537W
COE Expiry Date:	21 Dec 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	$45,466.00
Lifespan Expiry Date:	21 Dec 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443
TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

15-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1038 U

1 pcs	Front bumper	$	531.00
1 pcs	Front n/s door glass	$	322.00
1 pcs	Front bumper n/s side retainer	$	16.00
1 pcs	Mouldingn/s front door frame	$	47.00
1 pcs	Front n/s fender inner shield	$	120.00
1 pcs	n/s mirror assy	$	590.00
2 pcs	Front & rear n/s wheel cover @ $116.00	$	232.00
		$	1,858.00
	Less 10%	$	185.80
		$	1,672.20

S/NETT

1 set	Front bumper clips	$	48.00
1 pc	Front n/s fender sticker	$	30.00
1 set	Front n/s fender inner shield clips	$	28.00
1 set	n/s door stickers	$	100.00
1 pc	Rear n/s fender sticker	$	60.00
	Sundry	$	50.00
	To check wheel alignment - Front & Rear	$	160.00
	To dismantle / refit the inner garnishes, inner trims, cushion seat, carpet, etc to facilitate repairs.	$	180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	$	1,200.00
	To putty and spray painting on front bumper, front n/s fender, n/s side mirror, front n/s door, rear n/s door, n/s rocker panel garnish, rear n/s fender, rear bumper, Front & rear n/s wheel cover, Front o/s pillar	$	2,000.00
	To apply rustproofing on the repaired and replaced panels.	$	120.00
		$	5,648.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref : CS/FCI19008692/K1vd3n2

Date : 23-05-2019

Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	SH 8346H	**Veh. Inspected**	SHD 1038U
	Policy No.		**Coverage ($)**	0.00
	Claim No.	D19003249MFSH	**Excess ($)**	0.00
	Assign From	KARENT	**Assign Date**	16/05/2019

2. Vehicle Particulars & Condition

	Make & Model	KIA OPTIMA	**c.c**	1685
	Engine No.	HIDDEN	**Year of Reg.**	2015
	Chassis No.	KNAGM414MF5657928	**Colour**	SILVER
	Odometer	455174	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	FAIR		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	205/65 R16	ACHILLES	7 mm
	L/H Front Tyre	205/65 R16	ACHILLES	7 mm
	R/H Rear Tyre	205/65 R16	ACHILLES	7 mm
	L/H Rear Tyre	205/65 R16	ACHILLES	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

	Accident Date	14/05/2019	**Inspection Date**	16/05/2019
	Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1038U

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	-
1	FRONT N/S DOOR GLASS	SERVICEABLE	322.00	-
1	FRONT BUMPER N/S SIDE RETAINER	SERVICEABLE	16.00	-
1	MOULDING N/S FRONT DOOR FRAME	CUT	47.00	47.00
1	FRONT N/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	N/S MIRROR ASSY	BROKEN	590.00	590.00
2	FRONT & REAR N/S WHEEL COVER @$116.00	TO REPAIR SEE LABOUR	232.00	-
1	FRONT N/S FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-185.80	-63.70
			1,672.20	573.30
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SET N/S DOOR STICKERS (SN)	NOT NECESSARY	100.00	-
1	REAR N/S FENDER STICKER (SN)	NOT NECESSARY	60.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			316.00	20.00
	LABOUR			
	TO CHECK WHEEL ALIGNMENT-FRONT & REAR.	NOT NECESSARY	160.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES,INNER LININGS,INNER TRIMS,CUSHION SEAT,CARPET,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME.ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,FRONT & REAR N/S WHEEL COVER AND FRONT N/S FENDER.		1,200.00	200.00

Report Ref No. CS/FCI19008692/K1vd3n2

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER,FRONT N/S FENDER,N/S SIDE MIRROR,FRONT N/S DOOR,REAR N/S DOOR,N/S ROCKER PANEL GARNISH,REAR N/S FENDER,REAR BUMPER,FRONT & REAR N/S WHEEL COVER,FRONT O/S PILLAR.		2,000.00	410.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			3,660.00	610.00
	GRAND TOTAL		**5,648.20**	**1,203.30**

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**900.00**

Report Ref No. CS/FCI19008692/K1vd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.