22/03/2018

ASS. REC. BY: | REF: cs/FCI1900900g/Gsd3 n2 | Special Instruction:

Surveyor: CWS Chong

## ASSIGNMENT (Office)

From (Person): Joanne Yong of FCI Date/Time: 14/5/19 @ 2.16pm

Estimated Cost: Bill to:

~~OD / TP~~ / ~~WS / TP RES~~ / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 3733B Insured: SH 7577P.

at Workshop m/s Volkswagen Tel: 69223502

of 1 Kempang Ampat

Policy No: Claim No: D1900315SMPSH

Sum Insured: Excess:

Make of Veh: D.O.A. 12/05/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS iwp

Date/Time: 14/5/19 @ 3.37pm Person Contacted: Steven. Vehicl IN / OUT

H.O.D. Endorsement:

| Date/Time | Action/Instruction Estimate ✓ |
|---|---|
| | SLA 3733B - cs3/MSG/TC08395/klgh3f2 DOA: 26/4/2017 |
| | SH 7577P - cs/FCI/RO215L4/Rlvd3n2 DOA: 23/11/2018 |
| 28/05/19 | @ 10:05 am revised PA to Joanne Yong via email. |
| | |
| | |
| | |

Surveyor: Ad. | REF: FCI | 6232F

# ASSIGNMENT

From: | Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Volkswagen

of

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLA3733B Yr Regn: 04 Feb 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Jetta 1.4 c.c. 1390

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 62879 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ168GM015539

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 6 mm | R/Bal. | 6 mm |
| L/Bal. | 6 mm | L/Bal. | 6 mm |
| D.O.A. | | D.O.I. | 22-05-19 |

Survey held at W/S 4pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| 06/06/19 | Confirmed P/P $ 5,328.26 @ 3 days with XGQ ($ 4,267.30 Rd - 45%) |

RECEIVED 06 JUN 2019

6/6/2019

Date/Time, File Pass to? 06/06/19

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($ ) ☐ : Interview ($ ) ☐ : Tech. Invs ($ ) ☐ : Weekend ($ )

Report Format :

Lump Sum / I.B.I: ($ 5,328.26 P/P)

| | |
|---|---|
| Survey Fee: | 170 |
| Transportation: | 50 |
| S + RS SI | 50+50 |
| Photos | 74 |
| Others | |
| TOTAL | 394 |

Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003155MFSH

Date: 22 May 2019

Our Ref: CS/FCI19009009/Gsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 3733B .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/05/2019 at the premises of M/s Volkswagen Centre Singapore and have the following to report:-

| | |
|---|---|
| Workshop Estimate Amount | : S$ 8,503.03 . |
| Revised Estimate Amount | : S$ 7,601.11 . |
| "Check" Items Amount | : S$ 901.92 . |
| Market Value | : S$ . |
| LTA Reimbursement Value | : S$ . |
| Nett Value | : S$ . |

**Description of Damage:**
The vehicle sustained damages at the rear portion.




**Comments/ Present Status:**
Damages Consistent.
Repair days: 3 Days

Yours faithfully,
Xing Guo Qiang
Automotive Assessor

MS FirstCapital

MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9
6 Raffles Quay #21-00 Singapore 048580
Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877
Tel: (65) 6507 3848 Fax: (65) 6507 3849
www.msfirstcapital.com.sg

## MOTOR SURVEY ASSIGNMENT

| | | | |
|---|---|---|---|
| **Date** | 13-05-2019 | **Our Ref No.** | D19003155MFSH |
| **Accident Date** | 12-05-2019 | **Claim Type.** | Third Party |
| **Insured Vehicle** | SH7577P | **Third Party Vehicle.** | SLA3733B |
| **Survey Location** | 1 KAMPONG AMPAT | | |
| **Contact Person.** | TANG SHU SHI | | |
| **Contact No.** | 69223502/ 0 | **Fax No.** | 62858620 |
| **Survey Type** | WITHOUT PREJUDICE: ACCIDENT NOT REPORTED: | | |
| **Appointed Surveyor** | LKK AUTO CONSULTANTS PTE LTD | | |
| **Contact Person** | NA | **Fax No.** | 68416315 |
| **Contact Number.** | NA | | |

**FOR DIRECT SETTLEMENT**

**Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.**

THIRD PARTY SURVEY REQUEST

| | | | |
|---|---|---|---|
| **Cc : Workshop** | VOLKSWAGEN CENTRE SINGAPORE | **Attention.** | NIL |
| **Cc : TP Solicitor** | NA | **TP Solicitor Fax No.** | NA |
| **Officer Incharge** | JOANNEY | | |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
**Sent:** Tuesday, 28 May 2019 10:05 AM
**To:** 'Joanne Yong Lai fong'; 'CWS Motor Claims'
**Cc:** 'Admin-D (LKKAuto)'; 'assignments'
**Subject:** RE: SURVEY ASSESSMENT - D19003155MFSH/1
**Attachments:** SLA 3733B - Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SLA 3733B.

Thank you.

Best Regards,

Shirley Hiew | Case Handler
**LKK Auto Consultants Pte Ltd**
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
**Sent:** Tuesday, 14 May, 2019 2:16 PM
**To:** ASSIGNMENTS@LKKAUTO.COM
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
**Subject:** PRI: SURVEY ASSESSMENT - D19003155MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

## Shirley Hiew (LKK Auto)

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
**Sent:** Thursday, 6 June 2019 2:31 PM
**To:** 'Tang, Shu Shi (VWG Singapore)'
**Cc:** 'steven.chee@vw.com.sg'; 'SUR'
**Subject:** RE: SLA3733B - finalized

Dear Shu Shi,

Confirmed final fig $ 5,328.26 @ 3 day of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----
From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 3 June 2019 12:27 PM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FW: SLA3733B - finalized

Dear Guo Qiang and Shirley,

FYNA.

Best Regards,

G.Nivitha| Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----
From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Monday, 3 June 2019 12:00 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: FW: SLA3733B - finalized

CS/FCI19009009/Gsd3

-----Original Message-----
From: Tang Shu Shi (VGS - SG/Singapore) <shushi.tang@vw.com.sg>
Sent: Friday, 31 May, 2019 3:21 PM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Chee Steven (VGS - SG/Singapore) <steven.chee@vw.com.sg>
Subject: SLA3733B - finalized

Hi,

Please see attached finalized.

COR: as per attached.

DOR: 3 working days.

Please note that the bumper is a improve parts and the bumper comes with factory fitted sensor, thus necessary to change.

Please revert.

Best Regards,

Tang Shu Shi
Insurance Service Advisor
Aftersales

Volkswagen Centre Singapore (Macpherson)
1 Kampong Ampat
Singapore 368314

DID: +65 6922-3502
Mobile: +65 9386-7833
Main Line : +65 6305-7299
Main Fax: +65 6285-8620
shushi.tang@vw.com.sg
https://www.volkswagen.com.sg/

Internal

---
This email has been checked for viruses by AVG.
https://www.avg.com

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|---|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 6232F |
| Vehicle No.: | SLA3733B |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 22 May 2019 |
| Vehicle Make: | VOLKSWAGEN |
| Vehicle Model: | JETTA GP 1.4 TSI 90 A/T HL HID 1634G5 |
| Primary Colour: | Black |
| Manufacturing Year: | 2015 |
| Engine No.: | CAXF83739 |
| Chassis No.: | WVWZZZ16ZGM015539 |
| Maximum Power Output: | 90.0 kW (120 bhp) |
| Open Market Value: | $21,562.00 |
| Original Registration Date: | 04 Feb 2016 |
| First Registration Date: | 04 Feb 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | $22,187.00 |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 03 Feb 2026 |
| PARF Rebate Amount: | $16,640.00 |
| COE Expiry Date: | 03 Feb 2026 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | $54,301.00 |
| COE Rebate Amount: | $36,380.00 |
| **Total Rebate Amount:** | **$53,020.00** |

The information contained herein is correct as at 22 May 2019

OK

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

# Certificate of Insurance

**ORIGINAL**

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

**VW DRIVEEASY**
**Comprehensive**

**Certificate No.** A 28681615 AVW

**Excess :** SGD500
**Windscreen Excess :** SGD100

1. **Index Mark and Registration Number of Vehicle**
   SLA3733B
2. **Name of Policyholder**
   Lim Ai Li Alice
3. **Effective Date of the Commencement of Insurance for the purposes of the Act**
   04/02/2019
4. **Date of Expiry of Insurance**
   03/02/2020
5. **Persons or Classes of Persons entitled to drive***
   Lim Ai Li Alice
   Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

   * Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. **Limitations as to use***
   Use only for social domestic and pleasure purposes and for the Policyholder's business.
   The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

   * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.**

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

2/1/2019
Signature / Date

**MSIG Insurance (Singapore) Pte. Ltd.**
Approved Insurers

Amy Ler
Senior Vice President, Agencies

Counter-Signatory:
**Winner Consultancy Pte. Ltd.**

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

VOLKSWAGEN CENTRE SINGAPORE
9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052

Volkswagen ŠKODA Commercial Vehicles

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

# Quotation
Non binding - Preview

Page 1/1

Ms.
ALICE
LIM AI LI
195A PUNGGOL ROAD
#12-504
Singapore 821195

| | |
|---|---|
| Document no. | |
| Document date | 13-05-2019 |
| Customer no. | 5211032101 |
| Customer GST-ID | |
| Dealer | 39999 |
| Job order number | 2019000581/ 1 |
| Job order date | 13-05-2019 |
| Service Advisor | SHU SHI TANG |

| License plate | Model code | First registration | VIN | Model | Mileage |
|---|---|---|---|---|---|
| SLA3733B | 1634G7 | 04-02-2016 | WVWZZZ16ZGM015539 | JETTA TSI High 90 D7F | 50,429 |

| Position no. | Description | Quantity | Unit | Unit price excl. GST | Tax code | Total amount excl. GST | Total amount incl. GST |
|---|---|---|---|---|---|---|---|
| | Labour | 4 | pcs. | 840.00 | #1 | 3,360.00 | 3,595.20 |
| | Spray Paint | 3 | pcs. | 800.00 | #1 | 2,400.00 | 2,568.00 |
| | Diagnostic and Programming | 1 | pcs. | 480.00 | #1 | 480.00 | 513.60 |
| | Check Short Circuit / Harness Check | 1 | pcs. | 280.00 | #1 | 280.00 | 299.60 |
| 5C6807417J GRU | Cover Rear Bumper | 1 | pcs. | 620.80 | #1 | 620.80 | 664.26 |
| 5C6807433J | Spoiler | 1 | pcs. | 460.31 | #1 | 460.31 | 492.53 |
| 5C6807305 | Bumper Reinforcement | 1 | pcs. | 603.37 | #1 | 603.37 | 645.61 |
| 5C6807375 | Guide Piece LHR bumper bracket | 1 | pcs. | 78.37 | #1 | 78.37 | 83.86 |
| 5C6807376 | Guide Piece RHR bumper bracket | 1 | pcs. | 78.37 | #1 | 78.37 | 83.86 |
| 5C6807863B | Attachment Strip Rear centre bracket | 1 | pcs. | 72.88 | #1 | 72.88 | 77.98 |
| 5C6945106B | Reflector RH | 1 | pcs. | 68.93 | #1 | 68.93 | 73.76 |
| | Ms First Capital Direct Settlement, DOA: 12/05/2019, TP Veh: SH7577P, Survey by: | | | | | | |

Quotation valid till 20-05-2019

| Tax Code | Labour | Material | GST % | GST | Total amount excl. GST | Total amount incl. GST |
|---|---|---|---|---|---|---|
| #1 | 760.00 | 7,743.03 | 7% | 595.21 | 8,503.03 | 9,098.24 |
| Total | 760.00 | 7,743.03 | | 595.21 | 8,503.03 | 9,098.24 |

2 Days.
28/5 before paint photos.
Guo Qiang – 82880282

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

22/5/19.

VOLKSWAGEN CENTRE SINGAPORE
9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052

Volkswagen ŠKODA Commercial Vehicles

# Tax invoice
Preview



Company
MS
FIRSTCAPITAL INSURANCE
6 RAFFKES QUAY
#21-00
Singapore 048580

Customer Details:
Ms.
ALICE
LIM AI LI
195A PUNGGOL ROAD
#12-504
Singapore 821195

| | |
|---|---|
| Document no. | |
| Document date | 31-05-2019 |
| Customer no. | 5211041856 |
| Customer GST-ID | 195000106C |
| Dealer | 39999 |
| Job order number | 2019000688/ 1 |
| Job order date | 22-05-2019 |
| Service Advisor | SHU SHI TANG |

| License plate | Model code | First registration | VIN | Model | Mileage |
|---|---|---|---|---|---|
| SLA3733B | 1634G7 | 04-02-2016 | WVWZZZ16ZGM015539 | JETTA TSI High 90 D7F | 50,429 |

| Position no. | Description | Quantity | Unit | Unit price excl. GST | Tax code | Total amount excl. GST | Total amount incl. GST |
|---|---|---|---|---|---|---|---|
| | Diagnostic and Programming | 1 | pcs. | 480.00 | #1 | 480.00 | 513.60 |
| | Check Short Circuit / Harness Check | 1 | pcs. | 280.00 | #1 | 280.00 | 299.60 |
| 5C6807421H GRU | Cover For Bumper Primed XR-230519 | 1 | pcs. | 1,365.12 | #1 | 1,365.12 | 1,460.68 |
| 5C6807433J | Spoiler CD-230519 | 1 | pcs. | 460.31 | #1 | 460.31 | 492.53 |
| 5C6807376 | Guide Piece RHR bumper bracket*XR-230519 | 1 | pcs. | 78.37 | #1 | 78.37 | 83.86 |
| 5C6919491D | Sensor Bracket XR-280519 | 1 | pcs. | 15.07 | #1 | 15.07 | 16.12 |
| 5C6919491E | Sensor Bracket XR-280519 | 2 | pcs. | 15.07 | #1 | 30.14 | 32.25 |
| 5C6919492D | Sensor Bracket XR-280519 | 1 | pcs. | 15.07 | #1 | 15.07 | 16.12 |
| D 180KU2A1 | 2k-Plastic Adhesive XR-280519 | 1 | pcs. | 74.29 | #1 | 74.29 | 79.49 |
| D 822150A1 | Bonding Agent For Plastic CD-290519 | 1 | pcs. | 56.90 | #1 | 56.90 | 60.88 |
| 5C6807305 | Bumper REINFORCEMENT*XR-280519 | 1 | pcs. | 603.37 | #1 | 603.37 | 645.61 |
| 5C6807863B | Attachment Strip REAR CENTRE BRACKET*XR-280519 | 1 | pcs. | 72.88 | #1 | 72.88 | 77.98 |
| 5C6807393E | Guide Piece TAILLIGHT LOWER BRACKET | 1 | pcs. | 78.37 | #1 | 78.37 | 83.86 |
| 5C6807394E | LH*XR-280519 Guide Piece TAILLIGHT LOWER BRACKET | 1 | pcs. | 78.37 | #1 | 78.37 | 83.86 |
| | RH*XR-280519 | | | | | | |
| | Labour | 1 | pcs. | 840.00 | #1 | 840.00 | 898.80 |
| | Spray Painting | 1 | pcs. | 800.00 | #1 | 800.00 | 856.00 |
| | Ms First Capital Direct Settlement | | | | | | |
| | DOA: 12/05/2019 | | | | | | |
| | TP Veh: SH7577P | | | | | | |
| | Survey by: GUOQIANG (LKK) | | | | | | |

| Tax Code | Labour | Material | GST % | GST | Total amount excl. GST | Total amount incl. GST |
|---|---|---|---|---|---|---|
| #1 | 760.00 | 4,568.26 | 7% | 372.98 | 5,328.26 | 5,701.24 |
| Total | 760.00 | 4,568.26 | | 372.98 | 5,328.26 | 5,701.24 |

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


**Affiliated to Federation Internationale Des Experts En Automobile**

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref : CS/FCI19009009/Gsd3n2

Date : 12-06-2019

Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

| | | | | |
|---|---|---|---|---|
| | **Insured Veh.** | SH 7577P | **Veh. Inspected** | SLA 3733B |
| | **Policy No.** | | **Coverage ($)** | 0.00 |
| | **Claim No.** | D19003155MFSH | **Excess ($)** | 0.00 |
| | **Assign From** | JOANNE YONG | **Assign Date** | 14/05/2019 |

## 2. Vehicle Particulars & Condition

| | | | | |
|---|---|---|---|---|
| | **Make & Model** | VOLKSWAGEN JETTA 1.4 | **c.c** | 1390 |
| | **Engine No.** | HIDDEN | **Year of Reg.** | 2016 |
| | **Chassis No.** | WVWZZZ16ZGM015539 | **Colour** | BLACK |
| | **Odometer** | 62879 | **Steering** | IN ORDER |
| | **Brakes** | IN ORDER | **Modification** | STANDARD ALLOY RIM |
| | **General** | GOOD | | |

## 3. Conditions of Tyres

| | | **Size** | **Make** | **Balance** |
|---|---|---|---|---|
| | **R/H Front Tyre** | 205/55 R16 | PIRELLI | 6 mm |
| | **L/H Front Tyre** | 205/55 R16 | PIRELLI | 6 mm |
| | **R/H Rear Tyre** | 205/55 R16 | PIRELLI | 6 mm |
| | **L/H Rear Tyre** | 205/55 R16 | PIRELLI | 6 mm |

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

## 5. General Information

| | | | | |
|---|---|---|---|---|
| | **Accident Date** | 12/05/2019 | **Inspection Date** | 22/05/2019 |
| | **Survey held at** | VOLKSWAGEN CENTRE SINGAPORE<br>1 KAMPONG AMPAT OFF MACPHERSON ROAD<br>SINGAPORE 368314 | | |

## 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R




## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 3733B

| Qty | Description of Parts | Condition | Estimate By Workshop ($)) | Our Adjusted ($) |
|---|---|---|---|---|
| | **REPLACEMENT OF PARTS** | | | |
| 1 | SPOILER (SN) | CUT | 460.31 | 460.31 |
| 1 | COVER REAR BUMPER (SN) | DEFORMED | 1,365.12 | 1,365.12 |
| 1 | BUMPER REINFORCEMENT (SN) | BENT | 603.37 | 603.37 |
| 1 | GUIDE PIECE LHR BUMPER BRACKET (SN) | NOT NECESSARY | 78.37 | - |
| 1 | GUIDE PIECE RHR BUMPER BRACKET (SN) | DEFORMED | 78.37 | 78.37 |
| 1 | ATTACHMENT STRIP REAR CENTRE BRACKET (SN) | BROKEN | 72.88 | 72.88 |
| 1 | REFLECTOR RH (SN) | NOT NECESSARY | 68.93 | - |
| 1 | SENSOR BRACKET (ADDITIONAL)(SN) | NECESSARY | 15.07 | 15.07 |
| 1 | SENSOR BRACKET (ADDITIONAL)(SN) | NECESSARY | 15.07 | 15.07 |
| 2 | SENSOR BRACKET (ADDITIONAL)(SN) | NECESSARY | 30.14 | 30.14 |
| 1 | 2K-PLASTIC ADHESIVE (ADDITIONAL)(SN) | NECESSARY | 74.29 | 74.29 |
| 1 | BONDING AGENT FOR PLASTIC (ADDITIONAL)(SN) | NECESSARY | 56.90 | 56.90 |
| 1 | TAILLIGHT LOWER BRACKET LH (ADDITIONAL)(SN) | DEFORMED | 78.37 | 78.37 |
| 1 | TAILLIGHT LOWER BRACKET RH (ADDITIONAL)(SN) | DEFORMED | 78.37 | 78.37 |
| | | | 3,075.56 | 2,928.26 |
| | **LABOUR** | | | |
| | LABOUR. | | 3,360.00 | 840.00 |
| | SPRAY PAINT. | | 2,400.00 | 800.00 |
| | DIAGNOSTIC AND PROGRAMMING. | | 480.00 | 480.00 |
| | CHECK SHORT CIRCUIT/HARNESS CHECK. | | 280.00 | 280.00 |
| | | | 6,520.00 | 2,400.00 |
| | **GRAND TOTAL** | | **9,595.56** | **5,328.26** |
| | **RECOMMENDED COST OF REPAIRS** | | | **5,328.26** |

Report Ref No. CS/FCI19009009/Gsd3n2

**XING GUO QIANG**

**M.MATAI, AMSAE-A**

**Automotive Assessor**

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.