ASS. REC. BY: REF: CB/FCI/9009489/Gqd3 n2 Special Instruction:

Surveyor: Steve

**ASSIGNMENT (Office)**

CWS

From (Person): Eileen Lee of FCI Date/Time: 28/5/19@ 5.27pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKA 8204R Insured: SH 9788J

at Workshop m/s Falcon Air Tel: 67795665

of No. 8 Pandan Twp (Blk 1 / Blk 16)

Policy No: Claim No: D19003448MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 24/5/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS (DS) H.O.D. Endorsement:

Date/Time: 28/5/2019 Person Contacted: Andy Vehicle IN / OUT

| Date/Time | Action/Instruction Estimate (✓) |
|---|---|
| | SKA 8204R - X |
| | SH 9788J - X |
| 30/5/19@ | 11.01am revised to Eileen Lee by email. |
| | |
| | |
| | |

ASS. F&C. BA: Steve | REF: FCI

# ASSIGNMENT

From: | Date: 27/5/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKA 8204R

at Workshop m/s: Falcon Air

of: Blk 8 ponden loop

Insured:

Policy No.:

Claims No.:

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Carln Ready Andy

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| X X | X |

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: 11 days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SKA 8204R | Yr Regn: 5/4/11

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda City | c.c: 1497

Colour: Grey | A/C: Insured / Std / NI / NA

Sp.Reading: 161811 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHGM 26509P 029498

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 6 mm | R/Bal. | 6 mm |
| L/Bal. | 6 mm | L/Bal. | 6 mm |
| D.O.A. | 24/5/19 | D.O.I. | 28/5/19 |

Survey held at: Falcon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | MV- 24,000 |
| | LTA- 17,282 |
| | NV - 6718 |
| | RECEIVED 19 JUN 2019 |
| 13/6/19 | Finalize Comfl. $4550, 11 days (Andy) Clsd $7576.80, 38%) |

Date/Time, File Pass to?: 14/6 [illegible]

Date/Time, File Return to?:

Prell. Report

Final Report

Days Of Repair: 11

Resurvey No. of Trip: 1

Add Fee: Site Insp. ($) / Interview ($) / Tech. Invs ($) / Weekend ($)

Report Format: TP

Lump Sum / LPR: 4550

| | |
|---|---|
| Survey Fee: | 150 |
| Transportation: | 50 |
| 3 - RS SI | 50 |
| Photos: | 58 |
| Other: | |
| TOTAL | 308 |

## Nivitha (LKK Auto)

**From:** PBSP <pml-pbsp@simedarby.com.sg>
**Sent:** Tuesday, 7 May 2019 12:21 PM
**To:** assignments
**Cc:** Kevin Leong Wai Kit
**Subject:** Re: REQUEST FOR DIRECT SETTLEMENT - SKP6401Y & SFE2221T ON 03/04/2019 ***LKK REF:CC3/AIG19006168/jb3

Dear Sirs

Please arrange survey on 21 May 2019.

Owner leaving car in for survey + repair by 10am.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

---

**From:** PBSP
**Sent:** Tuesday, 7 May 2019 11:01:13 AM
**To:** Kevin Leong Wai Kit
**Subject:** Fw: REQUEST FOR DIRECT SETTLEMENT - SKP6401Y & SFE2221T ON 03/04/2019 ***LKK REF:CC3/AIG19006168/jb3

---

**From:** Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
**Sent:** Tuesday, 7 May 2019 11:00 AM
**To:** PBSP; Mei Kwan (LKKAuto); Khanchna (LKK Auto)
**Cc:** 甯珺 ©; CS A Team
**Subject:** RE: REQUEST FOR DIRECT SETTLEMENT - SKP6401Y & SFE2221T ON 03/04/2019 ***LKK REF:CC3/AIG19006168/jb3

WITHOUT PREJUDICE

Dear Caroline,

We refer to the subject.
Please be informed that solely basing on the accident statements submitted by parties involved, the liability is clear.

Kindly note on the following:

1) The final repair cost is subject to the consistency of the damages according to the nature of the accident and approval of our principal insurer;

LKK Auto Consultants Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003448MFSH
Our Ref: CS/FCI19009489/Eqd3

Date: 30 May 2019

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SKA 8204R .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/05/2019 at the premises of M/s FALCON-AIR AUTO. and have the following to report:-

| | |
|---|---|
| Workshop Estimate Amount | : S$ 7,076.80 . |
| Revised Estimate Amount | : S$ 6,098.24 . |
| "Check" Items Amount | : S$ 388.56 . |
| Market Value | : S$ - . |
| LTA Reimbursement Value | : S$ - . |
| Nett Value | : S$ - . |

Description of Damage:
The vehicle sustained damages at the rear portion.




Yours faithfully

Steve
Automotive Assessor

MS FirstCapital

MS First Capital Insurance Limited Co.Reg No. 199000106C GST Reg No. M2-0001675-9
6 Raffles Quay #21-00 Singapore 048580
Tel: (65) 6222 2311 Fax: (65) 6222 3547
Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877
Tel: (65) 6507 3848 Fax: (65) 6507 3849
www.msfirstcapital.com.sg

## MOTOR SURVEY ASSIGNMENT

| | | | |
|---|---|---|---|
| **Date** | 27-05-2019 | **Our Ref No.** | D19003448MFSH |
| **Accident Date** | 24-05-2019 | **Claim Type.** | Third Party |
| **Insured Vehicle** | SH9788J | **Third Party Vehicle.** | SKA8204R |
| **Survey Location** | NO.8 PANDAN LOOP (BLK 1 / BLK K) | | |
| **Contact Person.** | ANDY | | |
| **Contact No.** | 67795665/ 0 | **Fax No.** | 67791110 |
| **Survey Type** | DIRECT SETTLEMENT: | | |
| **Appointed Surveyor** | LKK AUTO CONSULTANTS PTE LTD | | |
| **Contact Person** | NA | **Fax No.** | 68416315 |
| **Contact Number.** | NA | | |

### FOR DIRECT SETTLEMENT

**Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.**

THIRD PARTY SURVEY REQUEST

| | | | |
|---|---|---|---|
| **Cc : Workshop** | FALCON-AIR AUTO SERVICES PTE LTD | **Attention.** | NIL |
| **Cc : TP Solicitor** | NA | **TP Solicitor Fax No.** | NA |
| **Officer Incharge** | EILEEN LEE | | |

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

**From:** Shiau Chan (LKKAuto)
**Sent:** Thursday, 30 May 2019 11:01 AM
**To:** 'CWS Motor Claims'; assignments
**Cc:** 'Eileen Lee'; SUR
**Subject:** RE: SURVEY ASSESSMENT - D19003448MFSH/1
**Attachments:** CSFCI19009489Eqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SKA 8204R.

Best Regards,
**Shiau Chan (Ms)** | Case Handler
**LKK Auto Consultants Pte Ltd**
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
**Sent:** Tuesday, 28 May, 2019 5:27 PM
**To:** ASSIGNMENTS@LKKAUTO.COM
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
**Subject:** PRI: SURVEY ASSESSMENT - D19003448MFSH/1

Dear Sir/Mdm,
We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

# Honda City 1.5A VTEC



| | | | |
|---|---|---|---|
| **Price** | $24,888 | | |
| **Depreciation** | $9,080 /yr<br>View models with similar depre | **Reg Date** | 23-Mar-2011<br>(1yr 9mths 25days COE left) |
| **Mileage** | N.A. | **Manufactured** | 2009 |
| **Road Tax** | $684 /yr | **Transmission** | Auto |
| **Dereg Value** | $16,916 as of today (change) | **OMV** | $16,603 |
| **COE** | $42,600 | **ARF** | $16,603 |
| **Engine Cap** | 1,497 cc | **Power** | 88.0 kW (118 bhp) |
| **Curb Weight** | 1,150 kg | **No. of Owners** | 1 |
| **Type of Vehicle** | Mid-Sized Sedan | | |

Location Map

Shortlist | Compare | Add new

Report Error | More Actions

### Features

Reputable 1.5L DOHC VTec Engine! Smooth & Fuel Efficient Automatic Transmission Gearbox! ABS! EPS! Climatic Aircon Controls! Optitron Meters! Dual SRS View specs of the Honda City (2008-2014)

### Accessories

Upgraded Sound System With Revs Camera N Sensors! Genuine Leather Seats With Black Upholstery! Sports Rims With New Tyres! 3M Solarfilms! Tyre Sensors

### Description

Lowest Mileage In Town! Owned By A Meticulous Owner! Loan Or Trade In Available! Lowest Int Rates In Town Only 2.18%! Try Out Our Latest V.T.A.C Loan Services! Approval Almost Immediate! $500 Monthly! Hurry Down For A No Obligation Test Drive Today Before It's Gone Again!

### Category

PARF Car, Premium Ad Car

### Status

Available

### Resources

Car Valuation - Free
Find out the market value of your existing car for free. Get started

Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 22-May-2019 | Last Updated on: 24-May-2019

Seller Information

| | | |
|---|---|---|
| **Company** | SG Auto Pte Ltd<br>▸ Dealer's profile<br>▸ 25 were sold \| 6 were available | |
| **Address** | 1 Tampines North Drive 1 #01-32<br>Search cars nearby this location | |
| **Location** | T-Space | |
| **Office No** | 68484844 | |
| **Contact Person(s)** | Koh | 92475893 |
| | Jamme | 98179689 |

Optional Payments

| | | |
|---|---|---|
| **Transfer Fee** | $25 | |
| **Down Payment** | $7,466 (change) | Maximum 70% Loan |
| **1s** | $873 | Based on 2.98% interest rate |

| | | |
|---|---|---|
| **Insurance** | $1,280 onwards<br>Not at fault? No upfront payment required! (Get a quote)<br>Quote assumes a standard profile. "Get a quote" for exact figure. | Powered by AVIVA |
| **Total Upfront Payment** | $9,644 | Check with seller for exact figure. |

Products and Services

• View All

For Handling & Excellent Braking

LED Scuff Plate

Chrome Fuel Tank Cover

Steering Wheel

Long Lasting, 15" Value Tyre Deal $65/pcs

Bidded Carplate for Sale

Check out the specialist workshop for Honda cars: Pro-Jex V2D Auto Pte Ltd

Tags: Honda City, honda city, 2011 Honda City, 2011 honda city, Honda, City, city, Used Honda

**Recommended for you**

1-6 of 18

10 facts about renewing your COE

14 tyre myths you shouldn't believe

Toyota Camry takes on Volkswagen's Passat

Turbo Toyota Harrier meets its matches

Gewinnen Engine Enhancement Tapes?

Honda Owners..... Pls Check In..



sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, financial services, low mileage cars, car brands, car insurance, carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partners for job openings, Singapore jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**



©2004-2019 sgCarMart. All rights reserved.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

| | |
|---|---|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 6148Z |

### Vehicle Details

| | |
|---|---|
| Vehicle No.: | SKA8204R |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 25 May 2019 |
| Vehicle Make: | HONDA |
| Vehicle Model: | CITY 1.5L I-VTEC AUTO |
| Primary Colour: | Grey |
| Manufacturing Year: | 2009 |
| Engine No.: | L15A71811080 |
| Chassis No.: | MRHGM26509P020498 |
| Maximum Power Output: | 88.0 kW (118 bhp) |
| Open Market Value: | $16,603.00 |
| Original Registration Date: | 05 Apr 2011 |
| First Registration Date: | 05 Apr 2011 |
| Transfer Count: | 0 |
| Actual ARF Paid: | $16,603.00 |

### Intended PARF Rebate Details

| | |
|---|---|
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 04 Apr 2021 |
| PARF Rebate Amount: | $9,131.00 |

### Intended COE Rebate Details

| | |
|---|---|
| COE Expiry Date: | 04 Apr 2021 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | $43,813.00 |
| COE Rebate Amount: | $8,151.00 |
| **Total Rebate Amount:** | **$17,282.00** |

The information contained herein is correct as at 25 May 2019

OK

# FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

FALCON-AIR

THET NAING
3 JURONG EAST ST 32 #08-04
609478

Attention : Motor Claim Department

Contact : 98735595

Estimate : ES003469

Date : 24/05/2019
Vehicle Num. : SKA8204R
Make/Model : HONDA CITY-2009
Chassis/Eng# : MRHGM26509P020498/L15A7181108
Accident Date : 24/05/2019
Claim No. :
Reference : TP NTUC VS MSFCI
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S$ |
|---|---|---|---|---|
| | | LIST ITEMS : | | |
| 1. | 1 | BOOTLID / OD | | 440.00 / |
| 2. | 1 | BOOTLID LOCK / BT | | 179.00 / |
| 3. | 1 | BOOTLID LOGO / NEC | | 24.00 / |
| 4. | 1 | BOOTLID EMBLEM CITY / NEC | | 24.00 / |
| 5. | 1 | BOOTLID EMBLEM IVTEC / NEC | | 34.00 / |
| 6. | 1 | BOOTLID WEATHERSTRIP / CRU | | 84.00 / |
| 7. | 2 | TAILLAMP LH/RH / ~~OD~~ BR | 286.00 | 572.00 / |
| 8. | 1 | REAR END PANEL / OD | | 325.00 / |
| 9. | 1 | REAR END PANEL TOP GARNISH / CRU | | 80.00 / |
| 10. | 1 | SPARE TYRE BOARD / BR | | 108.00 / |
| 11. | 1 | LH TAILLAMP PANEL / OD | | 120.00 / |
| 12. | 1 | SPARE TYRE PANEL / OD | | 406.80 / |
| 13. | 1 | SPARE TYRE PANEL BRACKET / OD | | 180.00 / |
| 14. | 1 | REAR BUMPER / OD | | 464.00 / |
| 15. | 2 | REAR BUMPER SIDE RETAINER LH/RH / BR | | 17.00 / |
| 16. | 4 | REAR BUMPER SIDE CLIPS / NEC | 10.00 | 40.00 / |
| 17. | 1 | LH REAR FENDER / OD | | 624.50 / |
| 18. | 2 | REAR FENDER TRIMBOARD / CRU | 118.00 | 236.00 / |
| 19. | 1 | REAR EXHAUST ? ? × NN | | 457.70 × |
| 20. | 1 | EXHAUST HEAT SHIELD ? × NN | | 28.00 × |
| 21. | ~~2~~ 1 | EXHAUST RUBBER HOLDER / CRU | 16.50 / | ~~48.50~~ / |
| 22. | 1 | REAR WINDSCREEN GLASS MOULDING / NEC | | 115.00 / |
| | | List TotalS$ : | | 4,608.50 |
| | | 20.00% Discount S$ : | | 921.70 |
| | | | | 3,686.80 |

LKK Auto Consultants hereby notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CONTINUE / ...

4089.80
- 20%
3271.84

LKK Auto Consultants hereby
the Repairer of the following:
* To resurvey beforehand any
* To display damaged parts during
* Parts prices are subject to confir
* Third party survey is on a "With
* No illegal modifications is allow
* Supplementary item(s) must be
is subject to final approval from

Acknowledged by Repairer

Signature:

Date:

# FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

FALCON-AIR

THET NAING
3 JURONG EAST ST 32 #08-04
609478

Attention : Motor Claim Department
Contact : 98735595

Estimate : ES003469

Date : 24/05/2019
Vehicle Num. : SKA8204R
Make/Model : HONDA-CITY-2009
Chassis/Eng# : MRHGM26509P020498/L15A7181108
Accident Date : 24/05/2019
Claim No. :
Reference : TP NTUC VS MSFCI
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S$ |
|---|---|---|---|---|
| | | SPECIAL NETT ITEMS : | | |
| 1. | 1 | REVERSE SENSOR / BR | | 200.00 / |
| 2. | 1 | SEALANT / NLC | | 40.00 / |
| | | Special Nett Total S$ : | | 240.00 / |
| | | LABOUR : | | |
| | | TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING | | 80.00 / 20 |
| | | TO TRANSFER BOOTLID PARTS/MECHANISMS | | 50.00 / 30 |
| | | TO RUST PROOF ON ACCIDENT DAMAGED PARTS | | 150.00 / 30 |
| | | SPRAY PAINTING FRONT & REAR ACCIDENT DAMAGED AREAS | | 1,300.00 / 1000 |
| | | TO REMOVE/REFIX REAR WINDSCREEN GLASS | | 120.00 / 50 |
| | | TO REMOVE/REFIX CUSHION SEAT,CARPET,GARNISH,WIRING | | 150.00 / 80 |
| | | TO CUT OUT/ REWELD REAR END PANEL , SPARE TYRE PANEL LH TAILLAMP PANEL, REPAIR REAR FLOOR BOARD REAR CHASSIS RHREAR FENDER INCLUDES KNOCKING & REPLACEMENT OF PARTS | | 1,200.00 950 |
| | | TO REMOVE/REPLACE EXHAUST, HEAT SHIELD & HOLDERS | | 100.00 ~~50~~ 40 |
| | | Labour Total S$ : | | 3,150.00 |
| | | | | 2200 / |

E. & O.E.

30/5/19

Total S$ : 7,076.80

for FALCON AIR AUTO SERVICES PTE LTD

Steve (LKK) Via Projusc 28/5/19, 1.00 pm
83228813 11 8 Jing
Steve chm @ lkkauto.com
L/S
Rng Afy Spy

P - 3,271.84
N - 240
L - 2200
5711.84
L/S - 4569.47
= 4550

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD #16-01 CITY HOUSE
SINGAPORE 068877

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 65073849

Estimate : ES003469

Date : 24/05/2019
Vehicle Num. : SKA8204R
Make/Model : HONDA CITY-2009
Chassis/Eng# : MRHGM26509P020498/L15A718110
Accident Date : 24/05/2019
Claim No. :
Reference : TP NTUC VS MSFCI
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S$ |
|---|---|---|---|---|
| | | LIST ITEMS : | | |
| 1. | 1 | BOOTLID | | 440.00 |
| 2. | 1 | BOOTLID LOCK | | 179.00 |
| 3. | 1 | BOOTLID LOGO | | 24.00 |
| 4. | 1 | BOOTLID EMBLEM CITY | | 24.00 |
| 5. | 1 | BOOTLID EMBLEM IVTEC | | 34.00 |
| 6. | 1 | BOOTLID WEATHERSTRIP | | 04.00 |
| 7. | 2 | TAILLAMP LH/RH | 286.00 | 572.00 |
| 8. | 1 | REAR END PANEL | | 325.00 |
| 9. | 1 | REAR END PANEL TOP GARNISH | | 80.00 |
| 10. | 1 | SPARE TYRE BOARD | | 108.00 |
| 11. | 1 | LH TAILLAMP PANEL | | 120.00 |
| 12. | 1 | SPARE TYRE PANEL | | 406.80 |
| 13. | 1 | SPARE TYRE PANEL BRACKET | | 180.00 |
| 14. | 1 | REAR BUMPER | | 464.00 |
| 15. | 1 | REAR BUMPER SIDE RETAINER LH/RH | | 17.00 |
| 16. | 4 | REAR BUMPER SIDE CLIPS | 10.00 | 40.00 |
| 17. | 1 | LH REAR FENDER | | 624.50 |
| 18. | 2 | REAR FENDER TRIMBOARD | 118.00 | 236.00 |
| 19. | ~~1~~ | ~~REAR EXHAUST~~ | | |
| 20. | ~~1~~ | ~~EXHAUST HEAT SHIELD~~ | | |
| 21. | 1 | EXHAUST RUBBER HOLDER | | 16.50 |
| 22. | 1 | REAR WINDSCREEN GLASS MOULDING | | 115.00 |
| | | List TotalS$ : | | 4,089.80 |
| | | 20.00% Discount S$ : | | 817.96 |
| | | | | 3,271.84 |

CONTINUE / ...

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD #16-01 CITY HOUSE
SINGAPORE 068877

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 65073849

Estimate : ES003469

Date : 24/05/2019
Vehicle Num. : SKA8204R
Make/Model : HONDA CITY-2009
Chassis/Eng# : MRHGM26509P020498/L15A718110
Accident Date : 24/05/2019
Claim No. :
Reference : TP NTUC VS MSFCI
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S$ |
|---|---|---|---|---|
| | | SPECIAL NETT ITEMS : | | |
| 1. | 1 | REVERSE SENSOR | | 200.00 |
| 2. | 1 | SEALANT | | 40.00 |
| | | Special Nett Total S$ : | | 240.00 |
| | | LABOUR : | | |
| | | TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING | | 20.00 |
| | | TO TRANSFER BOOTLID PARTS/MECHANISMS | | 30.00 |
| | | TO RUST PROOF ON ACCIDENT DAMAGED PARTS | | 30.00 |
| | | SPRAY PAINTING FRONT & REAR ACCIDENT DAMAGED AREAS | | 1,000.00 |
| | | TO REMOVE/REFIX REAR WINDSCREEN GLASS | | 50.00 |
| | | TO REMOVE/REFIX CUSHION SEAT,CARPET,GARNISH,WIRING | | 80.00 |
| | | TO CUT OUT/ REWELD REAR END PANEL , SPARE TYRE PANEL LH TAILLAMP PANEL, REPAIR REAR FLOOR BOARD REAR CHASSIS RHREAR FENDER INCLUDES KNOCKING & REPLACEMENT OF PARTS | | 950.00 |
| | | TO REALIGN EXHAUST | | 40.00 |
| | | Labour Total S$ : | | 2,200.00 |

E. & O.E.

Total S$ : 5,711.84

L/S less-20% – 1,142.20

4,568.80

L/S 4,550.00

11 DAYS

for FALCON AIR AUTO SERVICES PTE LTD

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref : CS/FCI19009489/Eqd3n2

Date : 18-06-2019

Code : FCI2

| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | |
|---|---|---|---|---|
| | **Insured Veh.** | SH 9788J | **Veh. Inspected** | SKA 8204R |
| | **Policy No.** | | **Coverage ($)** | 0.00 |
| | **Claim No.** | D19003448MFSH | **Excess ($)** | 0.00 |
| | **Assign From** | EILEEN LEE | **Assign Date** | 28/05/2019 |

| 2. | Vehicle Particulars & Condition | | | |
|---|---|---|---|---|
| | **Make & Model** | HONDA CITY | **c.c** | 1497 |
| | **Engine No.** | HIDDEN | **Year of Reg.** | 2011 |
| | **Chassis No.** | MRHGM26509P020498 | **Colour** | GREY |
| | **Odometer** | 161811 | **Steering** | IN ORDER |
| | **Brakes** | IN ORDER | **Modification** | SPORTS RIM |
| | **General** | FAIR | | |

| 3. | Conditions of Tyres | | | |
|---|---|---|---|---|
| | | **Size** | **Make** | **Balance** |
| | **R/H Front Tyre** | 175/65 R15 | DUNLOP | 6 mm |
| | **L/H Front Tyre** | 175/65 R15 | DUNLOP | 6 mm |
| | **R/H Rear Tyre** | 175/65 R15 | DUNLOP | 6 mm |
| | **L/H Rear Tyre** | 175/65 R15 | DUNLOP | 6 mm |

| 4. | Description of Damages |
|---|---|
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br><br>DAMAGES SEE DETAILS. |

| 5. | General Information | | | |
|---|---|---|---|---|
| | **Accident Date** | 24/05/2019 | **Inspection Date** | 28/05/2019 |
| | **Survey held at** | FALCON-AIR AUTO SERVICES PTE LTD<br><br>BLK 8 PANDAN LOOP<br>SINGAPORE 128226 | | |

| 5a. | Remarks |
|---|---|
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |

| 5b. | Estimate Days of Repair | |
|---|---|---|
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | **11 Working Days** |

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R




## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 8204R

| Qty | Description of Parts | Condition | Estimate By Workshop ($)) | Our Adjusted ($) |
|---|---|---|---|---|
| | **REPLACEMENT OF PARTS** | | | |
| 1 | BOOTLID | DENTED | 440.00 | 440.00 |
| 1 | BOOTLID LOCK | BENT | 179.00 | 179.00 |
| 1 | BOOTLID LOGO | NECESSARY | 24.00 | 24.00 |
| 1 | BOOTLID EMBLEM CITY | NECESSARY | 24.00 | 24.00 |
| 1 | BOOTLID EMBLEM IVTEC | NECESSARY | 34.00 | 34.00 |
| 1 | BOOTLID WEATHERSTRIP | CRUMPLED | 84.00 | 84.00 |
| 2 | TAILLAMP LH/RH @$286.00 | BROKEN | 572.00 | 572.00 |
| 1 | REAR END PANEL | DENTED | 325.00 | 325.00 |
| 1 | REAR END PANEL TOP GARNISH | CRUMPLED | 80.00 | 80.00 |
| 1 | SPARE TYRE BOARD | BROKEN | 108.00 | 108.00 |
| 1 | LH TAILLAMP PANEL | DENTED | 120.00 | 120.00 |
| 1 | SPARE TYRE PANEL | DENTED | 406.80 | 406.80 |
| 1 | SPARE TYRE PANEL BRACKET | DENTED | 180.00 | 180.00 |
| 1 | REAR BUMPER | DENTED | 464.00 | 464.00 |
| 2 | REAR BUMPER SIDE RETAINER LH/RH | BROKEN | 17.00 | 17.00 |
| 4 | REAR BUMPER SIDE CLIPS @$10.00 | NECESSARY | 40.00 | 40.00 |
| 1 | LH REAR FENDER | DENTED | 624.50 | 624.50 |
| 2 | REAR FENDER TRIMBOARD @$118.00 | CRUMPLED | 236.00 | 236.00 |
| 1 | REAR EXHAUST | NOT NECESSARY | 457.70 | - |
| 1 | EXHAUST HEAT SHIELD | NOT NECESSARY | 28.00 | - |
| 3 | EXHAUST RUBBER HOLDER @$16.50 | CRUMPLED (1 PC ONLY) | 49.50 | 16.50 |
| 1 | REAR WINDSCREEN GLASS MOULDING | NECESSARY | 115.00 | 115.00 |
| | LESS 20% DISCOUNT | | -921.70 | -817.96 |
| | | | 3,686.80 | 3,271.84 |
| | **SPECIAL NETT ITEMS** | | | |
| 1 | REVERSE SENSOR (SN) | BROKEN | 200.00 | 200.00 |
| 1 | SEALANT (SN) | NECESSARY | 40.00 | 40.00 |
| | | | 240.00 | 240.00 |

Report Ref No. CS/FCI19009489/Eqd3n2

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R




| Qty | Description of Parts | Condition | Estimate By Workshop ($)) | Our Adjusted ($) |
|---|---|---|---|---|
| | **LABOUR** | | | |
| | TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING. | | 80.00 | 20.00 |
| | TO TRANSFER BOOTLID PARTS/MECHANISMS. | | 50.00 | 30.00 |
| | TO RUST PROOF ON ACCIDENT DAMAGED PARTS. | | 150.00 | 30.00 |
| | SPRAY PAINTING FRONT & REAR ACCIDENT DAMAGED AREAS. | | 1,300.00 | 1,000.00 |
| | TO REMOVE/REFIX REAR WINDSCREEN GLASS. | | 120.00 | 50.00 |
| | TO REMOVE/REFIX CUSHION SEAT,CARPET,GARNISH,WIRING. | | 150.00 | 80.00 |
| | TO CUT OFF/REWELD REAR END PANEL,SPARE TYRE PANEL,LH TAILLAMP PANEL,REPAIR REAR FLOOR BOARD,REAR CHASSIS RH,REAR FENDER INCLUDES KNOCKING & REPLACEMENT OF PARTS. | | 1,200.00 | 950.00 |
| | TO REMOVE/REPLACE EXHAUST,HEAT SHIELD & HOLDERS. | | 100.00 | 40.00 |
| | | | 3,150.00 | 2,200.00 |
| | **GRAND TOTAL** | | **7,076.80** | **5,711.84** |

| | | | |
|---|---|---|---|
| **RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)** | | | **4,550.00** |

Report Ref No. CS/FCI19009489/Eqd3n2

**MARKET VALUE: $24,000.00 (EST)-LTA REIMBURSEMENT VALUE: $17,282.00=NETT VALUE: $6,718.00**

**CHEN TSUE YEE**

**Automotive Assessor**

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.