AIG vehicle in LKK

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

Not authorised
Reserve B&P paint
4-5 days

28/05/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLK1588P

1pc	rear tailgate "PRIUS" emblem	Na	$ 61.75	—
1pc	rear tailgate "HYBRID" emblem	Na	$ 53.75	—
1pc	rear tailgate "TOYOTA" logo	Na	$ 61.10	—
1pc	rear tailgate outer garnish	N	$ 741.35	X
1pc	rear bumper	CM	$ 928.35	—
2pcs	rear bumper side retainer @$141.40	Sn	$ 282.80	X
2pcs	rear bumper side lower bumper @$274.45	Sn	$ 548.90	X
1pc	rear bumper diffuser	Replace	$ 379.00	—
1pc	rear bumper reinforcement		$ 458.00	?
1pc	rear end panel	N	$ 970.25	X
1pc	rear end panel inner garnish	Sn	$ 381.90	X
2pcs	front headlamp @$2250.00		$ 4,500.00	?
1pc	front bumper	Bu	$ 972.45	—
1pc	front bumper number plate garnish	CM	$ 181.25	—
2pcs	front bumper side retainer @$131.35	Olsdn	$ 262.70	—
15pcs	front bumper clip @$5.00	Na	$ 75.00	—
1pc	front bumper "TOYOTA" logo	Na	$ 95.85	—
1pc	front bumper centre grille	CM	$ 381.85	—
1pc	front bumper top rubber Pr?	Na	$ 281.70	2
1pc	front bumper lower grille		$ 281.85	?
1pc	front bumper top sponge		$ 172.40	?
			$ 12,072.20	
	less 25%		$ 3,018.05	
			$ 9,054.15	
1set	rear parking sensor	s.nett	$ 280.00	?
2set	front & rear number plate & casing Replace	s.nett	$ 100.00	90 Sn
	wiring		$ 60.00	30
	tuffkote		$ 80.00	X
	spray painting		$ 1,400.00	800
	labour charges		$ 1,400.00	?
	Total		$ 12,374.15	

LKK Auto Consultants hence notify the Recipient of the following:
- To remove Bumper for spray painting
- To remove Headlamp for painting insurance
- Front bumper and rear bumper
- Front bumper and rear bumper "Bumper" black
- Front bumper and rear bumper
- Front bumper and rear bumper are recovered and [illegible] Insurance Company

Signature / Stamp
Date

Hui Yang Motor Pte Ltd
Reg No. 201629438M

2004