LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

30 MAY 2019

VEHICLE NO. : SMA 4129 C
MAKE : HONDA
MODEL : FIT 1.3GF CVT
YEAR : 2018
CHASSIS NO : GK31318294

DATE : 29-May-19
DATE OF ACCIDENT : 27-May-19
THIRD PARTY REF : AN 9139 P / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				$ B 492.70
1 pc	N/S Rear Bumper Retainer				$ DIY 16.90
1 pc	N/S Rear Bumper Garnish				$ N 20.70
10 pcs	Rear Bumper Clips		$ 3.90		$ N 39.00
1 pc	Rear End Panel				$ 1 390.00
1 pc	N/S Taillamp				$ CM 237.40
1 pc	Tailgate				$ B 850.00
1 pc	Tailgate FIT Emblem				$ N 35.10
1 pc	Rear Windscreen Moulding				$ N 95.20
					$ 2,177.00
	Less 20%				$ 435.40
					$ 1,741.60
1 pc	Rear Number Plate	S.Nett			$ N 40.00
1 pc	Rear Number Plate Seal	S.Nett			$ N 60.00
1 pc	Rear Windscreen Sealant	S.Nett			$ N 40.00
	To putty and spray painting				$ 7 00 800.00
	To remove and refix rear windscreen glass				$ ✓ 120.00
	To transfer tailgate fittings				$ 6 00 80.00
	To anti-rust				$ 3 00 50.00
	Labour Charges				$ 5 00 600.00
TG/RA-	**Total**				**$ 3,531.60**

Not authorised Resurvey B4 paint

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

5 days

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd