CITY CAB PTE LTD

REPAIR ESTIMATE*

AXA - JH.

P/P

VEHICLE NO : SHA 699J **DATE 17/6/2019 11:30**

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover			$ 418.30	XR
	Front Bumper Bracket Top (LH)			$ 35.00	?
	Front Bumper Bracket (LH)			$ 28.00	?
	Front Bumper Clips 10 pcs			$ 22.00	XJVC
	Front Fender (LH)			$ 490.70	/ DE
	Front Fender Shield (LH)			$ 114.70	?
	Front Fender Retainer			$ 41.40	?
	Emblem-Blue Drive (LH)			$ 26.60	/ NE
	Front Wheel Hub Cap (LH)			$ 346.40	/ SCR
	SUB TOTAL			**$ 1,523.10**	
	LESS 20%			$ 304.62	
	DISCOUNTED TOTAL			**$ 1,218.48**	
	Labour Charge				
	Panel Beating			$ ~~400.00~~	300
	Spray Painting Charge			$ ~~600.00~~	40
	Tuff Kote			$ ~~50.00~~	40
	Frt Wheel Alignment			$ 120.00	XNW
	TOTAL LABOUR			**$ 1,170.00**	
	ESTIMATE TOTAL			**$ 2,388.48**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NAZ LKK
17/6/19 1610
P/P

3 DAYS

CHECK ITEMS PHOTO

BY PAINT PHOTOS

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.