OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg /OptimaWerkz /OptimaWerkz

Date:	26.06.2019	Third Party Insurer:	AIG
Vehicle No:	SMG2016B	Third Party Veh No:	SJS3641L
Model:	TOYOTA NOAH HYBRID 1.8 - 2018	Date of Accident:	23.06.2019
Chassis:	ZWR800324338		
Reg.Year:	2018		

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S$	AMOUNT S$
1	REAR DOOR RH			$1,839.50
2	REAR DOOR FRAME PROTECTIVE STICKER RH			$102.55
4	FRONT DOOR RH			REPAIR
5	REAR WHEEL ARCH PANEL RH			REPAIR
			SUB TOTAL	$1,942.05
			LESS 25%	-$485.51
			PARTS TOTAL	$1,456.54

NO.	SPECIAL NETT	QTY	UNIT S$	AMOUNT S$
1	FRONT DOOR PROTECTIVE RUBBER RH			$150.00 ?
			S/N TOTAL	$150.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPAIR, REPLACE, READJUST, ALL ACCIDENT AREAS & ETC.	$800.00	500
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIAL AT FRONT DOOR RH, SLIDING DOOR RH, REAR WHEEL ARCH PANEL & ETC.	$900.00	660
TO DISMANTLE & REINSTALL SLIDING DOOR INNER MECHANISM & ETC BACK TO ORIGINAL OPERATION.	$120.00	60
TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC.	$80.00	20
TO UNDERSEAL MATERIALS.	$80.00	30
	LABOUR TOTAL	$1,980.00
ONG	**TOTAL**	**$3,586.54**

Not authorised
Resurvey B4 paint
4 days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: