~~CITY~~ CITY CAB PTE LTD

REPAIR ESTIMATE*

APPY LKCK

All

VEHICLE NO : SHC 421H **DATE 9/7/2019 16:02**

MAKE :

MODEL : HYUNDAI IONIQ

Chong

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper x repair			$ 459.40	
	Rear Bumper Centre Moulding Assy – Cra			$ 451.25	
	Rear Bumper Lower Centre Moulding Assy x sve			$ 47.50	
	Rear Bumper Stay x rvc			$ 138.10	
	Rear Bumper Side Bracket (LH/RH) x sve		$ 33.10	$ 66.20	
	Bumper clips – rec		$22.00		
	SUB TOTAL			**$ 1,162.45**	
	LESS 20%			$ 232.49	
	DISCOUNTED TOTAL			**$ 929.96**	
	Rear No.Plate – cra			$ 25.00	Nett
	Rear Bumper Reverse Sensor – sbh			$ 135.70	Nett
	Rear Bumper Rubber Mat – rec			$ 50.00	Nett
				$ 210.70	
	Labour Charge				
	Panel Beating			$ ~~400.00~~ 200	
	Spray Painting Charge			$ ~~300.00~~ 200	
	Wiring Charge			$ ~~50.00~~ x 2	
	Remove/Refix Reverse Sensor			$ ~~120.00~~ 30	
	TOTAL LABOUR			**$ 870.00**	
	ESTIMATE TOTAL			**$ 2,010.66**	
				2,020.26	

Katrin LKK

10/7/19 1055h.

2 days

8/8

After Repair photo

LKK A... the R...
- To re...
- To ...
- Pa...
- Third party ... survey is on ...
- No illegal mod... must be resurveyed and
- Supplementary item(s) is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.