(08/13/13)
Surveyor Marcus

REF: ASM (AXA)

ASSIGNMENT

From: Date: 11.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 1585R

at Workshop m/s Bodyshop Service Koh motor

of 15 ubi road 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Before 12.00 p.m

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 72k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "up" MA3160S

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMJ1585R Yr Regn: 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA1

Make: Honda Jazz CVT c.c 1318

Colour orange A/C: Insured / Std / NI / NA

Sp.Reading 4897 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMGK3850KS208068

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : NiL / S/Rim / STD A/Rim or

Tyre Size: F: 175/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm
D.O.A.	9/7/19	D.O.I.	11/7/19

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear 8

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS.___SI

Photos

Others

TOTAL