陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD
1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SJS7241G
Date of Accident : 09 July 2019

Not Applicable
A/S #2005
15/7/19
Take 2nd Appointment
3 days

Mr Thng Eng Kwee

Date : 11 July 2019

Rep: Luk - Marcus
15/07/19 C090Uhp

Estimate To Repair SJJ1253J - Toyota Vios 1.5E A
Chassis No : MR053HY9305078432

S/No	Quantity	Description	Amount	
		LIST ITEMS		
01	1 pc	bootlid Vios badge N.A	$ 48.00	
02	1 pc	bootlid Sports badge N.A	$ 50.00	
03	1 pc	bootlid centre logo N.A	$ 55.00	
04	1 pc	bootlid E badge N.A	$ 45.00	
05	1 pc	rear bumper D.O.R	$ 455.00	
06	2 ps	rear bumper side retainers @ $100.00 R	$ 200.00	X
07	2 ps	rear bumper side holders @ $35.00 R	$ 70.00	X
08	2 ps	rear bumper reflectors @ $90.00 R	$ 180.00	X
09	8 ps	rear bumper fastener clips @ $4.30 N.A	$ 34.40	
10	2 ps	rear bumper splashield cover @ $50.00 R	$ 100.00	X
11	1 pc	rear end panel R	$ 605.00	X
12	1 pc	rear end panel inner trim R	$ 80.70	X
13	3 ps	rear end panel inner trim clips @ $4.50 R	$ 13.50	X
			887.4 $ 1,936.60	
		Less 25 %	415.55 $ 484.15	
			$ 1,452.45	
		SPECIAL NETT ITEMS		
14	1 set	rear bumper parking sensor Shield	$ 400.00	200
15	1 pc	rear bumper lower spoiler (after market accessory) C.N.E	$ 800.00	600
			$ 1,200.00	
		LABOUR & MISC. CHARGES		
01		To reinstall of rear bumper parking sensor.	$ 120.00	50
02		To check electrical lighting concerned.	$ 60.00	20
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	$ 150.00	60
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	$ 800.00	400
05		Putty and spray painting of the affected portion.	$ 800.00	700
			$ 1,930.00	
		Total	$ 4,582.45	2452.55

LHK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: