LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	: 24th July 2019
TIME OF SURVEY	:

VEHICLE NO. : SKZ 8208 Z
MAKE : HONDA
MODEL : CRV 2.4 5AT 2WD S/R
YEAR : 2015
CHASSIS NO : MRHRM3850GP000073

DATE : 18-Jul-19
DATE OF ACCIDENT : 17-Jul-19
THIRD PARTY REF : FBH 5874 X / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			Bu	$ 609.50
2 pcs	Rear Bumper Retainer		$ 19.80	Sm	$ 39.60
1 pc	Rear Bumper Lower Garnish			Rd/Lu	$ 149.10
2 pcs	Rear Bumper Side Garnish		$ 66.40		$ 132.80
10 pcs	Rear Bumper Clips		$ 3.50	Ma	$ 35.00
1 pc	Rear Bumper Lower Cover				$ 81.50
1 pc	Tailgate Outer Garnish			CMA	$ 283.10
1 pc	Tailgate CRV Emblem			Ma	$ 20.90
					$ 1,351.50
	Less 20%				$ 270.30
					$ 1,081.20
1 set	Rear Bumper Sensor	S.Nett			$ 400.00
	To putty and spray painting				$ 500.00
	Labour Charges				$ 400.00
	Not Authorise LISup 87 Resurvey After Paint 3days				
TG/RA-	**Total**				**$ 2,381.20**

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

LTM Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: