22/03/2002

ASS. REC. BY: | REF: CS3/SMO19013402/RICF302 | Special Instruction:

Surveyor : Rosu

Melinum

ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi of SMO Date/Time: 31.7.19 8.39 a-m

Estimated Cost: Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 6769H Insured: SKP 3384H

at Workshop m/s Tj Car Service Tel: 97575155

of BIK 1010 #01-115 Bukit Merah Lane 3

Policy No: D19MTPV0101091I Claim No: CMTD1903518

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 20.7.2019

CA / REV / REP. / REV 24 HRS "up"

Date/Time: 31.7.19 9.43 a.m Person Contacted: Boon Leong H.O.D. Endorsement: Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate	
	SLX 6769H - NBA/AIG 19013449/Y	DOA - 20/07/2019
	SKP 3384H - NBA/AIG 19013349/Y	DOA - 20/07/2019
	Dismantle part : 01/08/2019	
	After repair : 06/08/2019	

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

D.O.A. 20/07/19 D.O.I. 31/07/19

Survey held at TJ CAR

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	ESTIMATE RANGE OF REPAIR - (5K - 6K) / 6 days
	31/7/2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: –

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Report Format : PRS

Lump Sum / I.B.I: ($)

Survey Fee:	100
Transportation:	60
S + RS, SI	60
Photos	
Others	11
TOTAL	231